

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000601/UGA3Q2**Date:** 10/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800018600
Claimant Vehicle No :	SML6694R	Insured Vehicle No :	SCA7876C
Date of Loss:	17/01/2022	Nature of Claim:	TP
		Claim No:	7003769507SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML6694R	Engine No:	1ZR0D51261
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 Elegance (A)	Chassis No:	MR053REH604596553
Reg. Date:	30/05/2019 (Man. Year: 2019)	Odometer:	41997 km
Colour:	Red		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45Z R17	Rear Tyre Size:	215/45Z R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,125.95	8,689.02	5,436.93	38.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,540.00	3,940.00	1,600.00	28.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,665.95	12,629.02	7,036.93	35.78
Approved Total (Overridden) (S\$)		10,100.00		
(S\$)	19,665.95	10,100.00	9,565.95	48.64
+ GST 7.00/7.00% (S\$)	1,376.62	707.00	669.62	48.64
Nett Amount (S\$)	21,042.57	10,807.00	10,235.57	48.64
+ Car Rental (7.5 x S\$100.00/day + 7.00% GST) (S\$)		802.50		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		11,659.50		

INSPECTION

Date of Assignment:	17/01/2022		
Date Inspected:	17/01/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	8.0 days		

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Deformed	458.10 FL	*458.10 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	43.00 FL	*43.00 FL
3	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	163.40 FL	*- FL
4	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	155.00 FL	*- FL
5	1		*FRONT BUMPER FOAM	Torn	78.80 FL	*78.80 FL
6	1		*FRONT BUMPER BEAM	Bent	382.70 FL	*382.70 FL
7	1		*FRONT GRILLE ASSY	Cracked	564.70 FL	*564.70 FL
8	1		*HEADLAMPS (O/S Not Necessary)	N/S Holder Cracked	7,758.00 FL	*3,847.90 FL
9	2		*HEADLAMPS TOP CHROME MOULDING	Not Necessary	400.00 FL	*- FL
10	1		*REAR BUMPER	Distorted	486.80 FL	*486.80 FL
11	1		*SET REAR BUMPER CLIPS	Necessary	43.00 FL	*43.00 FL
12	1		*REAR BUMPER SIDE RETAINER	N/S Cracked / O/S Not Necessary	221.00 FL	*89.10 FL
13	1		*REAR BUMPER REFLECTOR	N/S Cracked / O/S Not Necessary	116.00 FL	*58.00 FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	395.00 FL	*395.00 FL
15	2		*TAILLAMP	Cracked	790.00 FL	*790.00 FL
16	2		*TAILLAMP CLIPS	Not Necessary	8.60 FL	*- FL
17	1		*BOOTLID LOCK WITH COVER	Twisted	382.50 FL	*382.50 FL
18	1		*BOOTLID REFLECTOR	N/S Cracked / O/S Not Necessary	710.00 FL	*355.00 FL
19	1		*BOOTLID KEYLESS SWITCH ANTENA	Not Necessary	161.00 FL	*- FL
20	1		*REAR END PANEL	Badly Dented	590.00 FL	*590.00 FL
21	1		*REAR END PANEL TOP GARNISH	Twisted	240.00 FL	*240.00 FL
22	1		*N/S REAR FENDER	Warped / Buckled	986.80 FL	*986.80 FL
23	1		*N/S REAR FENDER INNER COWLING	Not Necessary	52.80 FL	*- FL
24	8		*N/S REAR FENDER INNER COWLING CLIPS	Not Necessary	34.40 FL	*- FL
25	1		*N/S REAR FENDER MUDFLAP	Not Necessary	138.00 FL	*- FL
26	1		*N/S REAR FENDER INNER TRIM BOARD	Not Necessary	789.00 FL	*- FL
27	1		*FLOOR PANEL	Repair	797.00 FL	*- FL
28	1		*FLOOR BOARD	Torn	267.00 FL	*267.00 FL
29	1		*REAR WINDSCREEN MOULDING	Necessary	162.00 FL	*162.00 FL
30	1		*FRONT NUMBER PLATE	Bent	40.00 FS	*40.00 FS
31	1		*REAR WINDSCREEN PRIMER	Necessary	40.00 FS	*40.00 FS
32	1		*TUBE REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
33	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
34	1		*REAR BOOTLID COVER	Buckled	755.00 FL	*753.30 FL
35	1		*REAR BOOTLID RUBBER	Twisted	185.00 FL	*185.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,704.60	11,478.70
- List Item Discount on L Items 25.00/25.00% (\$)	4,578.65	2,789.68
Total Parts (\$)	14,125.95	8,689.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND PARALLEL MEASUREMENT AND CORRECT TO MANUFACTURE SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK	New	350.00	250.00
2	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	140.00	120.00
3	TO DROP PETROL TANK ,HOSES TO FACILITATE BODYWORK REPAIR ,FINAL CHECKING AND TESTING	New	80.00	60.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	150.00	30.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS	New	350.00	100.00
6	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
7	TO CONDUCT WATER SEEPAGE TEST	New	150.00	0.00
8	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	120.00	80.00
9	TOWING CHARGES	New	80.00	50.00
10	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,000.00	1,600.00
11	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,000.00	1,600.00
Gross Labour Cost (\$)			5,540.00	3,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >