



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 7295C

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|---------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | REAR TAILLAMP OUTER RH | SERVICEABLE | 341.00 | - |
| 1 | REAR TAILLAMP OUTER LOWER BRACKET RH | SERVICEABLE | 66.00 | - |
| 1 | REAR BUMPER | BUCKLED | 330.00 | 330.00 |
| 1 | REAR BUMPER SIDE RETAINER RH | DISTORTED | 88.00 | 88.00 |
| 1 | REAR BUMPER REFLECTOR RH | SERVICEABLE | 77.00 | - |
| 1 | REAR BUMPER REFLECTOR GARNISH RH | SERVICEABLE | 88.00 | - |
| 1 | REAR BUMPER LOWER | SERVICEABLE | 308.00 | - |
| 1 | REAR FENDER INNER SHIELD RH | SERVICEABLE | 209.00 | - |
| 1 | REAR WHEEL ARCH GARNISH RH | CUT | 154.00 | 154.00 |
| 1 | REAR SPORT RIM RH | DENTED | 1,430.00 | 1,050.00 |
| 1 | REAR SPORT RIM CAP RH | SERVICEABLE | 44.00 | - |
| 1 | REAR SUSPENSION SHOCK ABSORBER RH | SERVICEABLE | 165.00 | - |
| 1 | REAR SUSPENSION KNUCKLE ARM RH | BENT | 616.00 | 583.60 |
| 1 | REAR SUSPENSION WHEEL BEARING RH | NECESSARY | 462.00 | 344.20 |
| 1 | REAR SUSPENSION LOWER ARM RH | SERVICEABLE | 275.00 | - |
| 1 | REAR SUSPENSION UPPER ARM RH | SERVICEABLE | 341.00 | - |
| 1 | REAR SUSPENSION TRAILING ARM RH | DISTORTED | 275.00 | 275.00 |
| | LESS 25% DISCOUNT | | -1,317.25 | -706.20 |
| | | | 3,951.75 | 2,118.60 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | REAR BUMPER CLIPS (SN) | NECESSARY | 50.00 | 50.00 |
| 1 | REAR BUMPER LOWER CLIPS (SN) | NOT NECESSARY | 50.00 | - |
| 1 | REAR FENDER INNER SHIELD CLIPS RH (SN) | NOT NECESSARY | 40.00 | - |
| 1 | REAR WHEEL ARCH GARNISH CLIPS RH (SN) | NECESSARY | 40.00 | 40.00 |
| 1 | REAR TYRE RH - 215/60R17 (SN) | SERVICEABLE | 350.00 | - |
| | | | 530.00 | 90.00 |
| <u>LABOUR</u> | | | | |
| | LABOUR CHARGES TO REMOVE, REPLACE, REPAIR & REFIX REAR ACCIDENT AREA. | | 700.00 | 360.00 |
| | LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT FRT REAR ACCIDENT. | | 700.00 | 400.00 |

Report Ref No. CS/FCI22000604/Kqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|---|---------------|---------------------------|-------------------|
| | TO TUFF KOTE & UNDERSEAL MATERIALS. | NOT NECESSARY | 120.00 | - |
| | TO WHEEL ALIGNMENT & BALANCING. | | 100.00 | 60.00 |
| | TO DIAGNOSIS FAULT CODE & RESET MEMORY. | NOT NECESSARY | 100.00 | - |
| | TO REMOVE & REFIX REAR WHEEL SUSPENSION ARM & ETC. TO EFFECT ON REAR FENDER RH. | | 150.00 | 100.00 |
| | TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. | | 80.00 | 15.00 |
| | | | 1,950.00 | 935.00 |
| GRAND TOTAL | | | 6,431.75 | 3,143.60 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 2,500.00 |

Report Ref No. CS/FCI22000604/Kqf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.