

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000607/GVY3E2**Date:** 20/01/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00155002100
Claimant Vehicle No :	SJM4269D	Insured Vehicle No :	XE6893P
Date of Loss:	06/01/2022	Nature of Claim:	TP
		Claim No:	SNM22D200407/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM4269D	Engine No:	1AZE119128
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Chassis No:	MR053BK4107036751
Reg. Date:	02/01/2009 (Man. Year: 2008)	Odometer:	170807 km
Colour:	Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,280.31	4,544.90	8,735.41	65.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,240.00	1,650.00	2,590.00	61.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,520.31	6,194.90	11,325.41	64.64
Approved Total (Overridden) (S\$)		4,950.00		
Nett Amount (S\$)	17,520.31	4,950.00	12,570.31	71.75

INSPECTION

Date of Assignment:	17/01/2022		
Date Inspected:	18/01/2022	Inspected At:	JEW Motors (HQ) 60 Jalan Lam Huat Carros Centre #03-72 Singapore 737869
Estimated Period of Repair:	6.0 days		

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jan 2023)
Parts:	143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM4269D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	670.20 FL	*670.20 FL
2	1		*BONNET RH HINGE	Not Necessary	64.80 FL	*- FL
3	1		*BONNET LH HINGE	Not Necessary	64.80 FL	*- FL
4	1		*BONNET LOCK	Not Necessary	166.10 FL	*- FL
5	1		*BONNET INSULATOR	Not Necessary	231.60 FL	*- FL
6	1		*FRONT BUMPER	Broken	624.70 FL	*624.70 FL
7	1		*FRONT BUMPER RH SIDE RETAINER	Not Necessary	59.89 FL	*- FL
8	1		*FRONT BUMPER RH CHROME MOULDING	Not Necessary	193.70 FL	*- FL
9	1		*FRONT BUMPER LH CHROME MOULDING	Not Necessary	193.70 FL	*- FL
10	1		*FRONT BUMPER RH FOG LAMP	Not Necessary	384.50 FL	*- FL
11	1		*RH FRONT FENDER	Buckled	856.30 FL	*856.30 FL
12	1		*RH FRONT FENDER EMBLEM	Necessary	56.80 FL	*56.80 FL
13	1		*RH FRONT FENDER SPLASH SHIELD	Deformed	184.50 FL	*184.50 FL
14	1		*RH FRONT FENDER ENCLOSER	Not Necessary	68.70 FL	*- FL
15	1		*RH FRONT FENDER INNER PANEL	Repair	703.70 FL	*- FL
16	1		*RH FRONT SPORT RIM (ORIGINAL)	Cut	934.50 FN	*400.00 F
17	1		*RH FRONT SPORT RIM CENTRE EMBLEM COVER	Not Necessary	76.30 FL	*- FL
18	1		*RH FRONT LOWER ARM	Bent	605.30 FL	*435.00 FL
19	1		*RH FRONT LOWER ARM BALL JOINT	Not Necessary	245.60 FL	*- FL
20	1		*RH FRONT SHOCK ABSORBER TOP MOUNTING	Not Necessary	161.00 FL	*- FL
21	1		*RH FRONT SHOCK ABSORBER TOP MOUNTING BEARING	Not Necessary	32.00 FL	*- FL
22	1		*RH FRONT SHOCK ABSORBER	Not Necessary	598.60 FL	*- FL
23	1		*RH FRONT KNUCKLE ARM	Bent	634.20 FL	*634.20 FL
24	1		*RH FRONT WHEEL BEARING WITH HUB	Necessary	265.30 FL	*171.00 FL
25	1		*RH FRONT TIE ROD	Not Necessary	151.20 FL	*- FL
26	1		*RH FRONT TIE ROD END	Not Necessary	76.40 FL	*- FL
27	1		*RH FRONT DRIVE SHAFT	Not Necessary	1,008.00 FL	*- FL
28	1		*RH FRONT ABS SENSOR	Not Necessary	211.20 FL	*- FL
29	1		*STEERING RACK AND PINION	Not Necessary	2,664.00 FL	*- FL
30	1		*FRONT UNDERCARRIAGE CROSSMEMBER	Not Necessary	1,161.10 FL	*- FL
31	1		*RH FRONT DOOR	Repair	1,304.20 FL	*- FL
32	1		*RH FRONT DOOR PROTECTOR	Necessary	137.60 FL	*137.60 FL
33	1		*RH FRONT DOOR PROTECTOR CHROME MOULDING	Necessary	78.30 FL	*78.30 FL
34	1		*RH FRONT DOOR WEATHERSTRIP	Not Necessary	167.80 FL	*- FL
35	1		*FRONT WINDSCREEN GLASS RUBBER MOULDING	Not Necessary	113.00 FL	*- FL
36	1		*FRONT WINDSCREEN GLASS WIPER GARNISH RH COVER	Not Necessary	32.90 FL	*- FL
37	1		*FRONT WINDSCREEN GLASS WIPER GARNISH	Cracked	303.20 FL	*303.20 FL
38	1		*SET BONNET INSULATOR CLIPS	Necessary	70.00 FS	*20.00 FS
39	1		*SET FRONT BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
40	1		*SET RH FRONT FENDER SPLASH SHIELD CLIPS	Necessary	60.00 FS	*20.00 FS
41	1		*RH FRONT FENDER INNER PANEL JOINT SEALANT	Not Necessary	75.00 FS	*- FS
42	1		*BRAKE FLUID	Not Necessary	60.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*SET RH FRONT DOOR INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
44	1		*RH FRONT TYRE (\$300) (70%)	Punctured	400.00 FS	*210.00 FS
45	1		*FRONT WINDSCREEN GLASS SEALANT	Not Necessary	70.00 FS	*- FS
46	1		*FRONT WINDSCREEN GLASS INNER SEAL	Not Necessary	50.00 FS	*- FS
47	1		*RH HEADLAMP ASSY	Cracked	1,001.40 FL	*1,001.40 FL
F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.						
				Sub Total (\$)	17,402.09	5,833.20
				- List Item Discount on L Items 25.00/25.00% (\$)	3,888.15	1,288.30
				- Nett Item Discount on N Items 25.00/0.00% (\$)	233.63	0.00
				Total Parts (\$)	13,280.31	4,544.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,600.00	500.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,300.00	800.00
3	TO CHECK WIRING AND LIGHTING SYSTEM }	New	100.00	30.00
4	TO REFOCUS AND ADJUST HEADLAMPS ASSY }	New	60.00	0.00
5	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	100.00	60.00
6	TO REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS }	New	550.00	200.00
7	TO REMOVE, REPLACE AND BALANCER RH FRONT SPORT RIM WITH TYRE }	New	70.00	0.00
8	TO TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	120.00	60.00
9	TO REMOVE AND REFIT RH FRONT DOOR INNER COMPONENTS TO NEW DOOR	New	120.00	0.00
10	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS	New	220.00	0.00
Gross Labour Cost (\$\$)			4,240.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >