



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 1922U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEADLAMP LH	SERVICEABLE	2,719.00	-
1	HEADLAMP LOWER MOULDING LH	CRACKED	223.00	223.00
1	FRONT BUMPER	BENT	625.00	625.00
1	FOG LAMP COVER LH	SERVICEABLE	161.00	-
1	FRONT BUMPER LOWER LID LH (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	228.00	-
10	FRONT BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	95.00	-
	LESS 25% DISCOUNT		-1,025.25	-224.50
			3,075.75	673.50
	<u>LABOUR</u>			
	TO INSPECT FRONT LIGHTING MECHANISM & CHECK WIRING.		80.00	15.00
	TO REMOVE & REPLACE DAMAGED ITEMS.TO REMOVE TRANSFER AFFECTED ATTACHMENT,REALIGN CONNECTION.		280.00	200.00
	TO SPRAY PAINT ON REPAIRED AREAS.		280.00	220.00
			640.00	435.00
	GRAND TOTAL		3,715.75	1,108.50
	RECOMMENDED COST OF REPAIRS			1,108.50

Report Ref No. CS/SMO22000614/Kty3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.