

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG22000635/EQF3N2**Date:** 03/03/2022**REFERENCE**

Insured/Claimant:	SIM KAY TEE	Policy No:	1800018600	
Date of Loss:	17/01/2022	Nature of Claim:	OD	Claim No: 7003769507SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCA7876C		
Make & Model:	KIA FORTE K3, 1.6 (A)	Engine No:	G4FGJH695303
Reg. Date:	28/02/2018 (Man. Year: 2017)	Chassis No:	KNAFJ411MJ5764840
Colour:	Grey	Odometer:	55724 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$59,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Continental 4 mm	Rear Left Side:	Continental 4 mm
Front Right Side:	Continental 4 mm	Rear Right Side:	Continental 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,472.40	2,742.80	2,729.60	49.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,420.00	2,270.00	1,150.00	33.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,892.40	5,012.80	3,879.60	43.63
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	8,592.40	4,712.80	3,879.60	45.15
+ GST 7.00/7.00% (S\$)	601.47	329.90	271.57	45.15
Nett Amount (S\$)	9,193.87	5,042.70	4,151.17	45.15

INSPECTION

Date of Assignment:	19/01/2022	
Date Inspected:	18/01/2022 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	7.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY-HEAD,RH	Broken	810.00 FL	*810.00 FL
2	1		*PANEL ASSY-HOOD	Repair	1,384.00 FL	*- FL
3	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 FL	*675.00 FL
4	1		*LATCH ASSY-HOOD	Not Necessary	65.00 FL	*- FL
5	1		*ORNAMENT-KIA NO 115	Necessary	32.00 FL	*32.00 FL
6	1		*STRIP ASSY-FR BUMPER UPR	Broken	29.00 FL	*29.00 FL
7	1		*GARNISH-RADIATOR GRILLE-UPR	Broken	54.00 FL	*54.00 FL
8	1		*GRILLE ASSY-RADIATOR	Broken	160.00 FL	*160.00 FL
9	1		*COVER-FR BUMPER	Dented	633.00 FL	*633.00 FL
10	1		*CAP-FRONT HOOK	Broken	9.00 FL	*9.00 FL
11	1		*MOULDING-FRT BPR LICENSE PLATE	Broken	18.00 FL	*18.00 FL
12	1		*LIP ASSY-FRONT BUMPER	Not Necessary	55.00 FL	*- FL
13	1		*MOULDING-FRONT BUMPER A/INTAKE	Broken	91.00 FL	*91.00 FL
14	1		*AIR DUCT-FR BUMPER,RH	Not Necessary	33.00 FL	*- FL
15	1		*DUCT ASSY-AIR CURTAIN,RH	Not Necessary	6.00 FL	*- FL
16	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 FL	*84.00 FL
17	1		*STIFFNER-FR BPR LWR	Dented	114.00 FL	*114.00 FL
18	1		*RAIL ASSY-FR BUMPER	Dented	496.00 FL	*496.00 FL
19	1		*BRACKET-FR BUMPER SIDE MTG,RH	Broken	13.00 FL	*13.00 FL
20	1		*GUARD-AIR,LH	Not Necessary	19.00 FL	*- FL
21	1		*GUARD-AIR,RH	Crushed	19.00 FL	*19.00 FL
22	1		*CONDENSER ASSY-COOLER	Not Necessary	681.00 FL	*- FL
23	1		*RADIATOR ASSY	Not Necessary	546.00 FL	*- FL
24	1		*BLOWER ASSY	Not Necessary	623.00 FL	*- FL
25	1		*COOLANT (4L)	Necessary	26.00 FL	*26.00 FL
26	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
27	1		*FR NUMBER PLATE WITH CASING	Cut	50.00 FS	*50.00 FS
28	1		*BODY PNL SEALANT	Necessary	40.00 FS	*40.00 FS
29	1		*COVER-BLANKING FRT FOG,RH (Supplementary)	Broken	18.00 FL	*18.00 FL
30	10		*CLIP (Supplementary)	Necessary	10.00 FL	*10.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,813.00	3,401.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,340.60	658.20
Total Parts (\$\$)	5,472.40	2,742.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW FR BUMPER,BONNET & FR SUPPORT REPAIR RHF FENDER	New	2,000.00	1,200.00
2	RESPRAY FR BUMPER,BONNET & RHF FENDER	New	1,050.00	700.00
3	REMOVE & REFIT AC COND & RADIATOR	New	100.00	100.00
4	TOP UP AC GAS	New	80.00	80.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
7	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	40.00
Gross Labour Cost (\$\$)			3,420.00	2,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >