

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG22000636/ETF3E2

Date: 23/03/2022

REFERENCE

Insured/Claimant:	RIO INTERIORS PTE LTD	Policy No:	1900096865	
Date of Loss:	17/01/2022	Nature of Claim:	OD	Claim No: 3133246593SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML1933J	Engine No:	G4FGKH728104
Make & Model:	KIA CERATO, 1.6 EX (A)	Chassis No:	KNAF3416MK5041188
Reg. Date:	09/05/2019 (Man. Year: 2018)	Odometer:	64523 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$69,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,075.20	5,676.80	2,398.40	29.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,540.00	6,010.00	3,530.00	37.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,615.20	11,686.80	5,928.40	33.66
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	17,315.20	11,386.80	5,928.40	34.24
+ GST 7.00/7.00% (S\$)	1,212.06	797.08	414.98	34.24
Nett Amount (S\$)	18,527.26	12,183.88	6,343.38	34.24

INSPECTION

Date of Assignment:	18/01/2022	
Date Inspected:	18/01/2022 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	10.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RHF SPORT RIM - S8004	Cut	380.00 FS	*380.00 FS
2	1		*FR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
3	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
4	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
5	1		*GRILLE-FRONT BUMPER	Broken	262.00 FL	*262.00 FL
6	1		*CAP-FRONT HOOK	Missing	9.00 FL	*9.00 FL
7	1		*COVER-FR BUMPER FOG LAMP, RH	Broken	15.00 FL	*15.00 FL
8	1		*GRILLE ASSY-RADIATOR	Not Necessary	328.00 FL	*- FL
9	1		*GARNISH-RADIATOR GRILLE	Not Necessary	38.00 FL	*- FL
10	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
11	1		*LAMP ASSY-FRONT FOG, RH	Bent	303.00 FL	*303.00 FL
12	1		*MOULDING-FRONT BUMPER, RH	Broken	36.00 FL	*36.00 FL
13	1		*LAMP ASSY-SIDE REPEATER, RH	Broken	143.00 FL	*143.00 FL
14	1		*AIR DUCT-FR BUMPER, RH	Broken	14.00 FL	*14.00 FL
15	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 FL	*84.00 FL
16	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
17	1		*BRACKET-FR BUMPER UPR SIDE MTG	Broken	22.00 FL	*22.00 FL
18	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	497.00 FL	*- FL
19	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 FL	*675.00 FL
20	1		*PNL-FENDER APRON UPR OTR, RH	Dented	30.00 FL	*30.00 FL
21	1		*PANEL ASSY-FNDR APRON, RH	Repair	538.00 FL	*- FL
22	1		*PANEL-FENDER, RH	Dented	430.00 FL	*430.00 FL
23	1		*PANEL ASSY-HOOD	Dented	1,502.00 FL	*1,502.00 FL
24	1		*HINGE ASSY-HOOD, LH	Bent	43.00 FL	*43.00 FL
25	1		*HINGE ASSY-HOOD, RH	Bent	43.00 FL	*43.00 FL
26	1		*PAD-HOOD INSULATING	Crushed	156.00 FL	*156.00 FL
27	13		*CLIP-HOOD INSULATING PAD MTG	Necessary	13.00 FL	*13.00 FL
28	1		*LATCH ASSY-HOOD	Not Necessary	103.00 FL	*- FL
29	1		*LAMP ASSY-HEAD, LH	Not Necessary	1,219.00 FL	*- FL
30	1		*LAMP ASSY-HEAD, RH	Broken	1,219.00 FL	*1,219.00 FL
31	1		*RESERVOIR & PUMP ASSY-WASHER	Broken	146.00 FL	*146.00 FL
32	1		*GUARD ASSY-FRONT WHEEL, RH	Broken	95.00 FL	*95.00 FL
33	1		*COVER ASSY-COWL TOP	Cut	247.00 FL	*247.00 FL
34	1		*COVER-AFTER SERVICE, LH	Not Necessary	11.00 FL	*- FL
35	1		*COVER-AFTER SERVICE, RH	Not Necessary	11.00 FL	*- FL
36	1		*W/STRIP ASSY-FR DR BELT O/S RH	Not Necessary	64.00 FL	*- FL
37	1		*PANEL ASSY-UNDER COVER	Broken	117.00 FL	*117.00 FL
38	1		*BRACKET ASSY-FENDER & BPR MTG (Supplementary)	Missing	14.00 FL	*14.00 FL
39	6		*RETAINER-COWL TOP COVER MTG (Supplementary)	Necessary	12.00 FL	*12.00 FL
40	1		*ARM COMPLETE-FR LWR, RH (Supplementary)	Bent	286.00 FL	*286.00 FL
41	15		*CLIP (Supplementary)	Necessary	15.00 FL	*15.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,979.00	6,996.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,903.80	1,319.20
Total Parts (\$\$)	8,075.20	5,676.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FR BUMPER, FR SUPPORT, BONNET & RHF FENDER. REPAIR FR CHASSIS, RHF DOOR, LHF FENDER & FR A PILLAR LH / RH	New	4,000.00	2,600.00
2	RESPRAY FR BUMPER, BONNET, LHF FENDER, RHF FENDER, FR CHASSIS, RHF WHEELHOUSE PNL, RHF DOOR & FR A PILLAR LH / RH	New	3,500.00	2,450.00
3	REMOVE & REFIT AC COND & RADIATOR	New	100.00	100.00
4	TOP UP AC GAS	New	80.00	80.00
5	RENEW RHF SPORT RIM & TRANSFER TYRE	New	30.00	30.00
6	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
8	CONDUCT CHASSIS ALIGNMENT - CELETE BENCH	New	1,000.00	-
9	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
10	APPLY ANTI COROSSION ON AFFECTED AREAS	New	80.00	40.00
11	SUPPLY BODY PNL SEALANT	New	80.00	40.00
12	RENEW FRONT UNDERCARRIAGE RH (Supplementary)	New	400.00	400.00
Gross Labour Cost (\$\$)			9,540.00	6,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >