



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name / RIO INTERIORS PTE LTD Reg No/Reg Date SML1933J*KC17/ 09/05/201 Date In/Mileage / 64523 Chassis No KNAF3416MK5041188 Engine No G4FGKH728104 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	17/01/2022/ 18:57	BLE	261 / Edwin Caina	45719
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW FR BUMPER, FR SUPPORT, BONNET & RH FENDER	6.5-5-5 X 470	2600		4000.00
28	REPAIR FR CHASSIS, RH FENDER, LHF FENDER & FR A PILLAR LH / RH				
E PNT98000	RESPRAY FR BUMPER, BONNET, LHF FENDER, RH FENDER, FR CHASSIS,				3500.00
	RHF WHEELHOUSE PNL, RH FENDER & FR A PILLAR LH / RH	7 X 350			
E PNT88000	REMOVE & REFIT AC COND & RADIATOR (photo)				100.00
M SUNDRY	TOP UP AC GAS				80.00
M SUNDRY	RENEW RH SPORT RIM & TRANSFER TYRE				30.00
M SUNDRY	SUPPLY RH SPORT RIM-S8004				380.00
A 54900099	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM				30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
E PNT88000	CONDUCT CHASSIS ALIGNMENT-CELETE BENCH (photo)				1000.00
B WHEELALIGNMENT	To Conduct Computerize Full Wheel Alignment				120.00
M SUNDRY	SUPPLY FR NUMBER PLATE WITH CASING				50.00
M SUNDRY	APPLY ANTI COROSSION ON AFFECTED AREAS				40 80.00
M SUNDRY	SUPPLY BODY PNL SEALANT				40 80.00
M SUNDRY	Sundries				20 30.00
M COVER-FR BUMPER		1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER		1.00	262.00	20.00	209.60
M CAP-FRONT HOOK		1.00	9.00	20.00	7.20

## Confirm &amp; accepted by

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name / RIO INTERIORS PTE LTD Reg No/Reg Date SML1933J*KC17/ 09/05/201 Date In/Mileage / 64523 Chassis No KNAF3416MK5041188 Engine No G4FGKH728104 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	17/01/2022/ 18:57	BLE	261 / Edwin Caina	45719			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M COVER-FR BUMPER FOG LAMP,RH					1.00	15.00	20.00	12.00
M GRILLE ASSY-RADIATOR					1.00	328.00	20.00	262.40
M GARNISH-RADIATOR GRILLE					1.00	38.00	20.00	30.40
M ORNAMENT-KIA NO.115					1.00	32.00	20.00	25.60
M LAMP ASSY-FRONT FOG,RH					1.00	303.00	20.00	242.40
M MOULDING-FRONT BUMPER,RH					1.00	36.00	20.00	28.80
M LAMP ASSY-SIDE REPEATER,RH					1.00	143.00	20.00	114.40
M AIR DUCT-FR BUMPER,RH					1.00	14.00	20.00	11.20
M ABSORBER-FRONT BUMPER ENERGY					1.00	84.00	20.00	67.20
M STIFFNER-FR BPR LWR					1.00	114.00	20.00	91.20
M BRACKET-FR BUMPER UPR SIDE MTG					1.00	22.00	20.00	17.60
M BEAM COMPLETE-FR BUMPER					1.00	497.00	20.00	397.60
M CARRIER ASSY-FRONT END MODULE					1.00	675.00	20.00	540.00
M PNL-FENDER APRON UPR OTR,RH					1.00	30.00	20.00	24.00
M PANEL ASSY-FNDR APRON,RH					1.00	538.00	20.00	430.40
M PANEL-FENDER,RH					1.00	430.00	20.00	344.00
M PANEL ASSY-HOOD					1.00	1502.00	20.00	1201.60
M HINGE ASSY-HOOD,LH					1.00	43.00	20.00	34.40
M HINGE ASSY-HOOD,RH					1.00	43.00	20.00	34.40
M PAD-HOOD INSULATING					1.00	156.00	20.00	124.80
M CLIP-HOOD INSULATING PAD MTG					13.00	1.00	20.00	10.40
M LATCH ASSY-HOOD					1.00	103.00	20.00	82.40
M LAMP ASSY-HEAD,LH					1.00	1219.00	20.00	975.20
M LAMP ASSY-HEAD,RH					1.00	1219.00	20.00	975.20
M RESERVOIR & PUMP ASSY-WASHER					1.00	146.00	20.00	116.80
M GUARD ASSY-FRONT WHEEL,RH					1.00	95.00	20.00	76.00
M COVER ASSY-COWL TOP					1.00	247.00	20.00	197.60
M COVER-AFTER SERVICE,LH					1.00	11.00	20.00	8.80
M COVER-AFTER SERVICE,RH					1.00	11.00	20.00	8.80
M W/STRIP ASSY-FR DR BELT					1.00	64.00	20.00	51.20
M PANEL ASSY-UNDER COVER					1.00	117.00	20.00	93.60

Estimate

Steve CLKK

SURVEYOR NAME: 00- M ML

18/1/22, 3:07pm

SURVEYOR NAME:

SURVEYOR SIGNATURE:

Confirm &amp; accepted by

DATE:

REMARKS:

Steve CLKK

OD-M HL

18/1/22, 3:00pm

EXACU-?

7% GST on

Nett 16,953.60

16,953.60  
1186.75

Total Payable

18,140.35

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.