

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte.	Cust No/Name	/ RIO INTERIORS PTE LTD		
Ltd.	Reg No/Reg Date	SML1933J*KC17/ 09/05/201		
MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Date In/Mileage	/ 64523		
	Chassis No	KNAF3416MK5041188		
	Engine No	G4FGKH728104		
	Make/Model	KIA/CERATO 1.6 A EX G333		
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	THE RES	
LAX00000	Credit	17/01/2022/ 18:57	BLE	261 / Edwin Caina		45719		
		Description of Goo	ds / Service	S	Qty	Unit Price	Disc%	Amount
E PNT88000	DIMDED	ED CHDDODT DOWN	FT 0 DUE E	ENDED			T	4000.00
		FR SUPPORT , BONN , RHF DOOR , LHF						
E PNT98000	(0///0010	, Kill DOOK , LIII	I LNULK & FI	X A FILLAK EN / KN				3500.00
RESPRAY I	R BUMPER	, BONNET , LHF FE	NDER , RHF	FENDER , FR CHASSIS ,				3300.00
RHF WHEEL	HOUSE PN	L , RHF DOOR & FR /	A PILLAR LI	ł/RH				
E PNT88000	DECLT 40							100.00
M SUNDRY	REFIT AC	COND & RADIATOR						00.00
TAD UD A	GAS							80.00
M SUNDRY			P***I	imai	_			30.00
RENEW RHE	SPORT R	IM & TRANSFER TYRE			100		ľ	33131
M SUNDRY	IF DDART	2711 2222	50			_]		380.00
SUPPLY RF A 54900099	IF SPURI	R1M-S8004				7		22.00
	ING ELEC	TRICAL SYSTEM & ADJ	IUST HEADLA	IMP ATM				30.00
A 10028901				un 11211				120.00
	OUT DIAG	NOSTIC CHECK ON ELE	CTRONIC CO	NTROL SYSTEM				220100
E PNT88000								1000.00
CONDUCT C B WHEELALIGN		LIGNMENT-CELETE BEN	ICH					100.00
		erize Full Wheel Al	ianment					120.00
M SUNDRY		or recorder milect year	rgiment					50.00
	NUMBER I	PLATE WITH CASING						30.00
M SUNDRY	T CODOCC	TON ON AFFECTED ADD						80.00
APPLY AND M SUNDRY	I COROSS	ION ON AFFECTED ARE	.AS					00.00
SUPPLY BO	DY PNL SI	EALANT					1	80.00
M SUNDRY	- · · · · · ·							30.00
Sundries								
Y COVER-FR					1.00	633.00		506.40
M GRILLE-FR M CAP-FRONT		±K			1.00	262.00		209.60
M CAPERUNI	HUUK				1.00	9.00	20.00	7.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

Movement that inspires

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info		
AIG Asia Pacific Insurance Pte.	Cust No/Name	/ RIO INTERIORS PTE LTD	
Ltd.	Reg No/Reg Date	SML1933J*KC17/ 09/05/201	
MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Date In/Mileage	/ 64523	
	Chassis No	KNAF3416MK5041188	
	Engine No	G4FGKH728104	
	Make/Model	KIA/CERATO 1.6 A EX G333	
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK	

Account No Terms Date/Time Printed CSE Operator		WIP No		
LAX00000 Credit 17/01/2022/ 18:57 BLE 261 / Ed	win Caina	45719		
Description of Goods / Services	Qty	Unit Price Disc%	Amount	
M COVER-FR BUMPER FOG LAMP,RH	1.00	15.00 20.00	12.00	
M GRILLE ASSY-RADIATOR	1.00	328.00 20.00	262.40	
M GARNISH-RADIATOR GRILLE	1.00	38.00 20.00	30.40	
M ORNAMENT-KIA NO.115	1.00	32.00 20.00	25.60	
M LAMP ASSY-FRONT FOG,RH	1.00	303.00 20.00	242.40	
M MOULDING-FRONT BUMPER,RH	1.00	36.00 20.00	28.80	
M LAMP ASSY-SIDE REPEATER, RH	1.00	143.00 20.00	114.40	
M AIR DUCT-FR BUMPER,RH	1.00	14.00 20.00	11.20	
M ABSORBER-FRONT BUMPER ENERGY	1.00	84.00 20.00	67.20	
M STIFFNER-FR BPR LWR	1.00	114.00 20.00	91.20	
M BRACKET-FR BUMPER UPR SIDE NTG M BEAM COMPLETE-FR BUMPER M CARRIER ASSY-FRONT END MODULE M PNL-FENDER APRON UPR OTR,RH	1.00	22.00 20.00	17.60	
M BEAM COMPLETE-FR BUMPER	1 6 7.99	497.00 20.00	397.60	
M CARRIER ASSY-FRONT END MODULE	1.00	675.00 20.00	540.00	
M PNL-FENDER APRON UPR OTR,RH 🕒 💙 🖔 📗 📗 📗		7 30.00 20.00	24.00	
M PANEL ASSY-FNDR APRON,RH	1.00	538.00 20.00	430.40	
M PANEL-FENDER, RH	1.00	430.00 20.00	344.00	
M PANEL ASSY-HOOD	1.00	1502.00 20.00	1201.60	
M HINGE ASSY-HOOD,LH	1.00	43.00 20.00	34.40	
M HINGE ASSY-HOOD,RH	1.00	43.00 20.00	34.40	
M PAD-HOOD INSULATING	1.00	156.00 20.00	124.80	
M CLIP-HOOD INSULATING PAD MTG	13.00	1.00 20.00	10.40	
M LATCH ASSY-HOOD	1.00	103.00 20.00	82.40	
M LAMP ASSY-HEAD, LH	1.00	1219.00 20.00	975.20	
M LAMP ASSY-HEAD,RH	1.00	1219.00 20.00	975.20	
M RESERVOIR & PUMP ASSY-WASHER	1.00	146.00 20.00	116.80	
M GUARD ASSY-FRONT WHEEL,RH	1.00	95.00 20.00	76.00	
M COVER ASSY-COWL TOP	1.00	247.00 20.00	197.60	
M COVER-AFTER SERIVCE, LH	1.00	11.00 20.00	8.80	
M COVER-AFTER SERIVCE,RH	1.00	11.00 20.00	8.80	
M W/STRIP ASSY-FR DR BELT O/S RH	1.00	64.00 20.00	51.20	
A PANEL ASSY-UNDER COVER	1.00	117.00 20.00	93.60	
SURVEYOR NAME:				
Confirm & accepted by SURVEYOR SIGNATURE:	_			
DATE:	30. 007	Nett	16,953.6	
REMARKS:	7 % GST on	16953.60	1186.7	
KEMBACKO . —	To	Total Payable		
Authorized signatory and company stamp				

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.