

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG22000637/ETF3E2

Date: 01/06/2022

REFERENCE

Insured/Claimant:	DESMOND TAN JUN YUAN	Policy No:	1900017590	
Date of Loss:	18/01/2022	Nature of Claim:	OD	Claim No: 1268841262SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ4963M	Engine No:	G4FGJH722036
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5031070
Reg. Date:	08/03/2019 (Man. Year: 2018)	Odometer:	28593 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$69,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,382.80	10,312.40	2,070.40	16.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,320.00	5,560.00	2,760.00	33.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,702.80	15,872.40	4,830.40	23.33
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	20,402.80	15,572.40	4,830.40	23.68
+ GST 7.00/7.00% (S\$)	1,428.20	1,090.07	338.13	23.68
Nett Amount (S\$)	21,831.00	16,662.47	5,168.53	23.68

INSPECTION

Date of Assignment:	18/01/2022	
Date Inspected:	18/01/2022 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	8.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FR NUMBER PLATE WITH CASING	Broken	50.00 FS	*50.00 FS
2	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
3	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
4	1		*GRILLE-FRONT BUMPER	Cut	485.00 FL	*485.00 FL
5	1		*GRILLE ASSY-RADIATOR	Broken	328.00 FL	*328.00 FL
6	1		*GARNISH-RADIATOR GRILLE	Broken	38.00 FL	*38.00 FL
7	1		*MOULDING-FRONT BUMPER, LH	Cut	216.00 FL	*216.00 FL
8	1		*MOULDING-FRONT BUMPER, RH	Cut	216.00 FL	*216.00 FL
9	1		*LAMP ASSY-SIDE REPEATER, LH	Not Necessary	143.00 FL	*- FL
10	1		*LAMP ASSY-SIDE REPEATER, RH	Not Necessary	143.00 FL	*- FL
11	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 FL	*84.00 FL
12	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
13	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
14	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
15	1		*WIRING ASSY-BUMPER EXTENSION	Broken	207.00 FL	*207.00 FL
16	4		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	652.00 FL	*- FL
17	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
18	1		*BEAM COMPLETE-FR BUMPER	Dented	497.00 FL	*497.00 FL
19	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 FL	*675.00 FL
20	1		*PANEL ASSY-HOOD	Dented	1,502.00 FL	*1,502.00 FL
21	1		*HINGE ASSY-HOOD, LH	Bent	43.00 FL	*43.00 FL
22	1		*HINGE ASSY-HOOD, RH	Bent	43.00 FL	*43.00 FL
23	1		*PANEL-FENDER, LH	Dented	430.00 FL	*430.00 FL
24	1		*PANEL-FENDER, RH	Dented	430.00 FL	*430.00 FL
25	1		*PAD-HOOD INSULATING	Necessary	156.00 FL	*156.00 FL
26	13		*CLIP-HOOD INSULATING PAD MTG	Crushed	13.00 FL	*13.00 FL
27	1		*LATCH ASSY-HOOD	Bent	103.00 FL	*103.00 FL
28	1		*LAMP ASSY-HEAD, LH	Broken	2,210.00 FL	*2,210.00 FL
29	1		*LAMP ASSY-HEAD, RH	Broken	2,210.00 FL	*2,210.00 FL
30	1		*GUARD-AIR, LH	Broken	28.00 FL	*28.00 FL
31	1		*GUARD-AIR, RH	Broken	28.00 FL	*28.00 FL
32	1		*CONDENSER ASSY-COOLER	Dented	687.00 FL	*687.00 FL
33	1		*RADIATOR ASSY	Not Necessary	646.00 FL	*- FL
34	1		*BLOWER ASSY	Not Necessary	656.00 FL	*- FL
35	1		*GUARD ASSY-FRONT WHEEL, LH	Not Necessary	95.00 FL	*- FL
36	1		*GUARD ASSY-FRONT WHEEL, RH	Not Necessary	95.00 FL	*- FL
37	1		*AIR DUCT-FR BUMPER, LH (Supplementary)	Broken	14.00 FL	*14.00 FL
38	1		*COVER-FR BUMPER FOG LAMP, RH (Supplementary)	Cut	15.00 FL	*15.00 FL
39	1		*COVER-FR BUMPER FOG LAMP, LH (Supplementary)	Cut	15.00 FL	*15.00 FL
40	1		*CAP-FRONT HOOK (Supplementary)	Crushed	9.00 FL	*9.00 FL
41	1		*CLEANER ASS-AIR (Supplementary)	Broken	174.00 FL	*174.00 FL
42	1		*DUCT ASSY-AIR (Supplementary)	Broken	55.00 FL	*55.00 FL
43	1		*DUCT-EXTENSION (Supplementary)	Broken	5.00 FL	*5.00 FL
44	1		*PANEL ASSY-UNDER COVER (Supplementary)	Broken	126.00 FL	*126.00 FL
45	1		*CLIPS (X10) (Supplementary)	Necessary	10.00 FL	*10.00 FL
46	1		*RETAINER (X10) (Supplementary)	Necessary	20.00 FL	*20.00 FL
47	1		*HORN ASSY-LOW PITCH (Supplementary)	Broken	74.00 FL	*74.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
48	1		*COOLANT (4L) (Supplementary)	Necessary	26.00 FL	*26.00 FL
49	1		*WIRING ASSY-CONTROL (Supplementary)	Broken	966.00 FL	*966.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					15,461.00	12,873.00
- List Item Discount on L Items 20.00/20.00% (S\$)					3,078.20	2,560.60
Total Parts (S\$)					12,382.80	10,312.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FR BUMPER, FR SUPPORT, BONNET, LHF FENDER & RHF FENDER. REPAIR LHF DOOR, RHF DOOR & FR A PILLAR LH / RH	New	3,200.00	2,000.00
2	RESPRAY FR BUMPER, BONNET, LHF FENDER, RHF FENDER, LHF DOOR, RHF DOOR & FR A PILLAR LH / RH	New	3,840.00	2,400.00
3	REMOVE & REFIT AC COND & RADIATOR	New	100.00	100.00
4	TOP UP AC GAS	New	80.00	80.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
7	SUPPLY BODY PNL SEALANT	New	80.00	40.00
8	APPLY ANTI CORROSION ON AFFECTED AREAS	New	120.00	40.00
9	RESPRAY ON RH A PILLAR (Supplementary)	New	350.00	350.00
10	REPLACE ENGINE WIRING (Supplementary)	New	400.00	400.00
Gross Labour Cost (\$\$)			8,320.00	5,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >