

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22000638/EVF3E2

Date: 09/03/2022

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1000775319

Claimant Vehicle No : SMY1960L

Insured Vehicle No : GBG3995Z

Date of Loss: 17/01/2022

Nature of Claim: TP

Claim No: 268408

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMY1960L**

Make & Model: TOYOTA PRIUS PLUS, 1.8 (A)

Engine No: 2ZR2F74130

Reg. Date: 23/02/2021 (Man. Year: 2020)

Chassis No: JTDZS3EU10J059924

Colour: Silver

Odometer: 52478 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R15

Rear Tyre Size: 205/60 R15

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,817.30	5,906.89	7,910.41	57.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,530.00	6,481.00	4,049.00	38.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,347.30	12,387.89	11,959.41	49.12
+ GST 7.00/7.00% (S\$)	1,704.31	867.15	837.16	49.12
Nett Amount (S\$)	26,051.61	13,255.04	12,796.57	49.12

INSPECTION

Date of Assignment: 19/01/2022

Date Inspected: 18/01/2022

Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)

2 Pandan Crescent

Singapore 128462

Estimated Period of Repair: 10.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Feb 2022)
Parts:	M1-MPV	TOYOTA PRIUS PLUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY1960L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*COVER, FR BUMPER	Crushed	442.12 FS	*442.12 FS
3	1		*GRILLE SUB-ASSY	Cut	447.75 FS	*447.75 FS
4	1		*ABSORBER, FR BUMPER	Not Necessary	63.15 FS	*- FS
5	1		*REINFORCEMENT	Not Necessary	522.00 FS	*- FS
6	1		*GRILLE, RADIATOR	Broken	382.57 FS	*382.57 FS
7	1		*UNIT ASSY, HEADLAMP	Not Necessary	2,008.57 FS	*- FS
8	1		*UNIT ASSY, HEADLAMP	Not Necessary	2,008.57 FS	*- FS
9	1		*LAMP ASSY, FOG, RH	Not Necessary	246.75 FS	*- FS
10	1		*LAMP ASSY, FOG, LH	Not Necessary	234.75 FS	*- FS
11	1		*COVER, RR BUMPER	Broken	442.12 FS	*442.12 FS
12	1		*SUPPORT, RR BUMPER	Not Necessary	113.40 FS	*- FS
13	1		*SUPPORT, RR BUMPER	Broken	113.40 FS	*113.40 FS
14	1		*SEAL, RR BUMPER	Not Necessary	71.55 FS	*- FS
15	1		*SEAL, RR BUMPER	Torn	102.60 FS	*102.60 FS
16	1		*REINFORCEMENT	Dented	172.65 FS	*172.65 FS
17	1		*PANEL SUB-ASSY, BODY	Not Necessary	553.50 FS	*- FS
18	1		*PANEL SUB-ASSY	Repair	767.47 FS	*- FS
19	1		*PROTECTOR, QUARTER	Necessary	18.30 FS	*18.30 FS
20	1		*PANEL SUB-ASSY, BACK	Dented	882.97 FS	*882.97 FS
21	1		*WEATHERSTRIP, BACK	Crushed	266.32 FS	*266.32 FS
22	1		*GLASS SUB-ASSY, BACK	Broken	820.20 FS	*820.20 FS
23	1		*DAM, WINDOW GLASS	Necessary	22.95 FS	*22.95 FS
24	1		*BOARD ASSY, BACK	Not Necessary	261.52 FS	*- FS
25	1		*LENS & BODY, RR	Not Necessary	548.17 FS	*- FS
26	1		*LENS & BODY, RR	Broken	529.57 FS	*529.57 FS
27	1		*REFLECTOR ASSY	Not Necessary	47.55 FS	*- FS
28	1		*REFLECTOR ASSY	Broken	47.55 FS	*47.55 FS
29	1		*SPOILER, RR NO.1	Broken	674.77 FS	*674.77 FS
30	1		*GARNISH SUB-ASSY	Not Necessary	344.70 FS	*- FS
31	1		*EMBLEM ASSY	Necessary	84.22 FS	*84.22 FS
32	1		*PLATE, BACK DOOR	Necessary	50.40 FS	*50.40 FS
33	1		*EMBLEM ASSY	Necessary	50.40 FS	*50.40 FS
34	1		*PLATE, LUGGAGE COMPT	Necessary	43.50 FS	*43.50 FS
35	1		*EMBLEM, SIDE PANEL	Not Necessary	43.50 FS	*- FS
36	1		*BACK SENSOR STEEL BLONDE ME	Broken	101.05 FS	*75.79 FS
37	1		*ARM SUB-ASSY, RR	Bent	139.72 FS	*139.72 FS
38	1		*RETAINER, RR BUMPER	Broken	47.02 FS	*47.02 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **13,817.30** **5,906.89**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING & CONDUCT LEAK TEST	New	180.00	162.00
2	RESET ECU UPON COMPLETION OF REPAIR	New	180.00	162.00
3	DRILL HOLE & INSTALL REVERSE SENSOR	New	180.00	162.00
4	TRANSFER TAILGATE MACH	New	720.00	648.00
5	REPL ACC AFF AREA. STRAIGHTEN & PANEL BEAT ACC AFF AREA	New	5,040.00	2,592.00
6	RESPRAY ACC AFF AREA	New	4,130.00	2,655.00
7	SUPPLY PHV STICKER	New	20.00	20.00
8	SUPPLY FRONT REGN PLATE (PO#)	New	80.00	80.00
Gross Labour Cost (\$\$)			10,530.00	6,481.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >