

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22000639/KVY3E2

**Date:** 05/04/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00058662102  
**Claimant Vehicle No :** SMU5089Y **Insured Vehicle No :** SLZ2167K  
Date of Loss: 17/01/2022 Nature of Claim: TP Claim No: SNM22D200412/C02/LEEPG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU5089Y**  
Make & Model: HONDA HR-V, 1.5 DX CVT (A) Engine No: L15B5672709  
Reg. Date: 17/08/2020 (Man. Year: 2020) Chassis No: JHMRU1810JX202701  
Colour: Metallic Black Odometer: 20288 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16  
Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 8 mm  
Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,364.00	562.00	802.00	58.80
Miscellaneous Items	172.00	112.00	60.00	34.88
Labour	441.26	632.86	-191.60	-43.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,977.26</b>	<b>1,306.86</b>	<b>670.40</b>	<b>33.91</b>
<b>+ GST 7.00/7.00% (S\$)</b>	138.41	91.48	46.93	33.91
<b>Nett Amount (S\$)</b>	<b>2,115.67</b>	<b>1,398.34</b>	<b>717.33</b>	<b>33.91</b>

### INSPECTION

Date of Assignment: 18/01/2022 Present Location: S & H Motor Pte Ltd (Sin Ming)  
Date Inspected: 21/01/2022 Inspected At: S & H Motor Pte Ltd (Sin Ming)  
Estimated Period of Repair: 4.0 days 160 Sin Ming Drive #07-02, Sin Ming AutoCity  
Singapore 575722

**Adjuster:** KENNETH KONG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Apr 2022)	
Parts:	N/A	HONDA HR-V 1.5 DX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU5089Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Parts		1,364.00 F	*562.00 F
F=Franchise part.						
Total Parts (S\$)					1,364.00	562.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Misc	172.00	112.00
Sub Total (\$\$)			172.00	112.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Labour for panel/mechanical	New	168.00	159.60
2	Labour for paintwork	New	273.26	273.26
3	SPRAY PAINT R BUMPER REAR BUMPER	New	-	200.00
Gross Labour Cost (\$\$)			441.26	632.86

Report was unsubmitted during this print-out.

< END OF ESTIMATES >