

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22000640/KVY3N2**Date:** 24/02/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00014122100

**Claimant Vehicle No :** SFM8008L **Insured Vehicle No :** GBK9956B

Date of Loss: 04/12/2021 Nature of Claim: TP Claim No: SNM21D207104/C02/TAYHP

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SFM8008L**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 1ZRY348818

Reg. Date: 19/12/2016 (Man. Year: 2016) Chassis No: MR053REH104563070

Colour: Metallic Silver Odometer: 262525 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16

Front Left Side: Tourador 8 mm Rear Left Side: Tourador 8 mm

Front Right Side: Tourador 8 mm Rear Right Side: Tourador 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	670.00	505.00	165.00	24.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	400.00	500.00	55.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>1,570.00</b>	<b>905.00</b>	<b>665.00</b>	<b>42.36</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	109.90	63.35	46.55	42.36
<b>Nett Amount (\$\$)</b>	<b>1,679.90</b>	<b>968.35</b>	<b>711.55</b>	<b>42.36</b>

**INSPECTION**

Date of Assignment: 18/01/2022

Date Inspected: 17/01/2022 Inspected At: 10 ANG MO KIO IND PARK 2A  
#01-04 ANG MO KIO AUTOPOINT . SINGAPORE  
568047  
REPAIRER: CHENG HOE MOTOR SERVICE

Estimated Period of Repair: 2.0 days

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Feb 2022)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFM8008L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 pc front bumper	Buckled	210.00 F	*210.00 F
2	1		*1 pc front bumper RH fog lamp cover	Serviceable	55.00 F	*- F
3	1		*1 pc front bumper RH side retainer	Distorted	26.00 F	*26.00 F
4	1		*6 pcs front bumper clips @ \$1.50/pc	Necessary	9.00 F	*9.00 F
5	1		*1 pc front bumper sponge	Serviceable	55.00 F	*- F
6	1		*1 pc LH headlamp	Cut	260.00 F	*260.00 F
7	1		*1 pc air resonator	Serviceable	55.00 F	*- F
Total Parts (\$\$)						670.00 505.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	Remove & refix frt bumper & attachments, grille,headlamp;knocking & repair frt panel & realign fender the same	New	400.00	200.00
2	Putty & respray frt bumper & attachments,fender,frt panel & all affected areas	New	500.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>900.00</b>	<b>400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >