

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD	R	Ref:	CS3/ASM22000641/Rvy3e2	
	8 SHENTON WAY SINGAPORE 0688	D	Date:	09/02/2022		
	ATTN: KOH JANIC	E	C	Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHC 8113U	Veh. Inspected		SMS 9039B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S2M03RB2	Excess (\$)		0.00	
	Assign From	KOH JANICE	Assign Date		18/01/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	HONDA VEZEL 1.5X CVT	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	RU11320955	Colour		WHITE	
	Odometer	96780 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	DUNLOP		6 mm	
	L/H Front Tyre	215/60 R16	DUNLOP		6 mm	
	R/H Rear Tyre	215/60 R16	DUNLOP		6 mm	
	L/H Rear Tyre	215/60 R16	DUNLOP		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	16/01/2022	Inspect Date / Ti	me	24/01/2022 (04:35 PM)	
	Survey held at	ENG SOON PAINTING SVC				
		BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/ASM22000641/Rvy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser