

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EGI22000642/UQF3Q2**Date:** 09/03/2022**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:  
**Claimant Vehicle No :** SKW1847R **Insured Vehicle No :** GBD3727Y  
 Date of Loss: 15/01/2022 Nature of Claim: TP Claim No: CDMCG22000109

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SKW1847R**  
 Make & Model: MAZDA 5, 2.0 (A) Engine No: PE10267665  
 Reg. Date: 20/10/2015 (Man. Year: 2015) Chassis No: JM6CW1071G0122545  
 Colour: White Odometer: 140621 km  
 Engine Capacity: 1998 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
 Front Left Side: Habilead 6 mm Rear Left Side: Linglong 6 mm  
 Front Right Side: Habilead 6 mm Rear Right Side: Linglong 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	48,394.70	18,575.12	29,819.58	61.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,380.00	4,240.00	3,140.00	42.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>55,774.70</b>	<b>22,815.12</b>	<b>32,959.58</b>	<b>59.09</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>18,200.00</b>		
<b>(S\$)</b>	55,774.70	18,200.00	37,574.70	67.37
<b>+ GST 7.00/7.00% (S\$)</b>	3,904.23	1,274.00	2,630.23	67.37
<b>Nett Amount (S\$)</b>	<b>59,678.93</b>	<b>19,474.00</b>	<b>40,204.93</b>	<b>67.37</b>

**INSPECTION**

Date of Assignment: 18/01/2022  
 Date Inspected: 18/01/2022 Inspected At: Fastech Auto Pte Ltd (HQ)  
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay  
 Singapore 417883  
 Estimated Period of Repair: 10.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2022)
<b>Parts:</b> M1-MPV	MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SKW1847R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	3,885.20 F	*1,637.00 FL
2	1		*TAILGATE REAR WINDSCREEN	Shattered	4,121.60 F	*1,121.00 FL
3	1		*REAR WINDSCREEN MOULDING	Necessary	126.30 F	*126.30 FL
4	1		*TAILGATE TOP SPOILER	Not Necessary	645.00 F	*- FL
5	1		*TAILGATE WIPER ARM	Serviceable	102.90 F	*- FL
6	1		*TAILGATE WIPER MOTOR	Bent / Jammed	365.00 F	*365.00 FL
7	1		*TAILGATE REAR LOGO	Necessary	48.60 F	*48.60 FL
8	1		*TAILGATE MAZDA EMBLEM	Necessary	42.00 F	*42.00 FL
9	1		*TAILGATE 5 EMBLEM	Necessary	38.00 F	*38.00 FL
10	1		*TAILGATE SKYACTIC EMBLEM	Necessary	60.00 F	*60.00 FL
11	1		*TAILGATE OUTER GARNISH	Distorted	341.80 F	*186.90 FL
12	1		*TAILGATE LICENCE PLATE LAMP	Serviceable	42.00 F	*- FL
13	2		*TAILGATE REFLECTORS	Cracked	970.00 F	*790.00 FL
14	1		*TAILGATE INNER LOCK	Dented	299.00 F	*286.90 FL
15	1		*TAILGATE INNER TRIM BOARD	Torn	426.00 F	*421.60 FL
16	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
17	1		*TAILGATE INNER TOP TRIM O/S	Cut	66.00 F	*66.00 FL
18	1		*TAILGATE WEATHERSTRIP	Twisted	285.00 F	*162.60 FL
19	2		*TAILLAMPS	Cracked / Broken	1,700.00 F	*1,190.00 FL
20	1		*REAR BUMPER	Distorted	1,541.90 F	*915.40 FL
21	1		*REAR BUMPER REFLECTORS	O/S Cracked	120.00 F	*60.00 FL
22	2		*REAR BUMPER SIDE RETAINERS	Bent	136.00 F	*136.00 FL
23	1		*REAR BUMPER REINFORCEMENT	Bent	425.10 F	*165.00 FL
24	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
25	1		*REAR END PANEL	Dented	580.90 F	*491.10 FL
26	1		*REAR END PANEL TOP GARNISH	Distorted	181.20 F	*181.20 FL
27	1		*REAR FLOOR PANEL	Repair	1,895.20 F	*- FL
28	1		*REAR FLOOR PANEL TOP TRAY	Distorted	455.00 F	*385.00 FL
29	1		*REAR FLOOR PANEL TOP BOARD	Distorted	615.00 F	*581.20 FL
30	1		*REAR EXHAUST	Repair	1,135.10 F	*- FL
31	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	122.00 F	*- FL
32	2		*REAR FENDERS	Repair	2,910.20 F	*- FL
33	2		*REAR FENDER INNER TRIM BOARDS	Deformed / Torn	1,576.20 F	*976.60 FL
34	1		*BONNET	Buckled	1,455.10 F	*1,085.60 FL
35	2		*BONNET HINGES	Bent	210.00 F	*210.00 FL
36	1		*BONNET INNER FRT RUBBER	Necessary	48.00 F	*48.00 FL
37	1		*BONNET INSULATOR	Not Necessary	245.00 F	*- FL
38	1		*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*- FL
39	1		*BONNET LOCK	Twisted	230.80 F	*168.00 FL
40	1		*BONNET LOCK CABLE	Serviceable	228.00 F	*- FL
41	1		*FRONT BUMPER	Distorted	1,280.00 F	*1,108.20 FL
42	1		*FRONT BUMPER TOW COVER	Serviceable	50.00 F	*- FL
43	1		*FRONT BUMPER TOP GARNISH	Distorted	152.00 F	*152.00 FL
44	1		*FRONT BUMPER TOP GRILLE	Distorted	155.00 F	*155.00 FL
45	1		*FRONT BUMPER LOWER GRILLE	Twisted	165.00 F	*165.00 FL
46	2		*FRONT BUMPER FOG LAMPS	Not Necessary	590.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	2		*FRONT BUMPER FOG LAMP COVERS	Not Necessary	230.00 F	*- FL
48	1		*FRONT BUMPER FRAME PAD	Distorted	265.00 F	*265.00 FL
49	1		*FRONT BUMPER TOP SUPPORT	Bent	148.00 F	*148.00 FL
50	2		*FRONT BUMPER BRACKETS	Bent	170.00 F	*170.00 FL
51	2		*FRONT BUMPER SIDE RETAINERS	Bent	130.00 F	*130.00 FL
52	1		*FRONT BUMPER SPONGE	Torn	130.60 F	*79.20 FL
53	1		*FRONT BUMPER REINFORCEMENT	Distorted	665.00 F	*645.00 FL
54	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
55	1		*FRONT BUMPER UNDER COVER	Torn	331.00 F	*281.20 FL
56	1		*SET FRONT BUMPER UNDER COVER CLIPS	Necessary	50.00 F	*50.00 FL
57	1		*FRONT BUMPER LOGO	Necessary	85.00 F	*45.60 FL
58	2		*HEADLAMPS	Cracked	6,100.00 F	*2,964.00 FL
59	2		*FRONT FENDERS	Repair	1,210.00 F	*- FL
60	2		*FRONT FENDER INNER SHIELD	Not Necessary	376.00 F	*- FL
61	1		*SET FRONT FENDER INNERSHIELD CLIPS	Not Necessary	50.00 F	*- FL
62	1		*FRONT SUPPORT PANEL	Cracked	765.00 F	*451.20 FL
63	1		*HORN UNIT	Not Necessary	108.00 F	*- FL
64	1		*AIR CON CONDENSER	Bent	1,020.00 F	*820.00 FL
65	1		*RADIATOR	Punctured	1,410.00 F	*1,250.00 FL
66	1		*RADIATOR FAN ASSY	Cracked / Jammed	1,580.00 F	*1,050.00 FL
67	1		*RADIATOR TOP HOSE	Cut	109.00 F	*82.00 FL
68	1		*RADIATOR SPARE TANK	Not Necessary	285.00 F	*- FL
69	1		*INLET MANIFOLD	Not Necessary	950.00 F	*- FL
70	1		*AIR CLEANER BOX	Not Necessary	650.00 F	*- FL
71	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
72	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
73	1		*REAR WINDSCREEN SOLAR FILM	Necessary	200.00 FS	*150.00 FS
74	1		*REAR LICENCE PLATE	Bent	50.00 FS	*40.00 FS
75	1		*SET REAR BUMPER REVERSE SENSOR	Torn	280.00 FS	*200.00 FS
76	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
77	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	150.00 FS	*- FS
78	1		*SET REAR REVERSE CAMERA	Shorted	380.00 FS	*300.00 FS
79	1		*FRONT BUMPER LICENCE PLATE	Broken	50.00 FS	*40.00 FS
80	1		*BOL RADIATOR COOLANT	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>48,394.70</b>	<b>22,996.40</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$)</b>	0.00	4,421.28
<b>Total Parts (\$)</b>	<b>48,394.70</b>	<b>18,575.12</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX TAILGATE MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
6	TO REFILL AIR CON GAS	New	100.00	100.00
7	TO SPRAY RUST PROOFING	New	100.00	100.00
8	TO RESET & REPROGRAMME SYSTEM	New	180.00	0.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	3,500.00	1,800.00
10	TO PUTTY & SPRAY PAINTING	New	3,000.00	1,900.00
			<b>Gross Labour Cost (\$\$)</b>	<b>7,380.00</b>
				<b>4,240.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >