

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM22000646/Evy3e2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	Date:	26/01/2022	
	ATTN: CHAN KIAN	CHUAN	Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	FBS 205C	Veh. Inspected	SLR 1698T	
	Policy No.	A3198162	Coverage (\$)	0.00	
	Claim No.	S2M03R2H	Excess (\$)	0.00	
	Assign From	CHAN KIAN CHUAN	Assign Date	14/01/2022	
2. Vehicle Particulars & Condition					
	Make & Model	MAZDA 6	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	JM6GL1071H0121148	Colour	RED	
	Odometer	105964 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/55 R17	MICHELIN	4 mm	
	L/H Front Tyre	225/55 R17	MICHELIN	4 mm	
	R/H Rear Tyre	225/55 R17	MICHELIN	4 mm	
	L/H Rear Tyre	225/55 R17	MICHELIN	4 mm	
4.	4. Description of Damages				
	THE VEHICLE SUS	HE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5.	5. General Information				
	Accident Date	12/01/2022	Inspect Date / Time	18/01/2022 (03:56 PM)	
	Survey held at AH KOON MOTOR				
		BLK 1001 BUKIT MERAH LANE 3 #01-69 SINGAPORE 159718			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000				
5b.	e. Estimate Days of Repair				
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			

Report Ref No. CS3/ASM22000646/Evy3e2

Inspected By

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser