



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811			Ref: CS3/ASM22000646/Evy3e2	
			Date: 25/01/2022	
			Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	FBS 205C	Veh. Inspected	SLR 1698T
	Policy No.	A3198162	Coverage (\$)	0.00
	Claim No.	S2M03R2H	Excess (\$)	0.00
	Assign From	CHAN KIAN CHUAN	Assign Date	14/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 6	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JM6GL1071H0121148	Colour	RED
	Odometer	105964 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R17	MICHELIN	4 mm
	L/H Front Tyre	225/55 R17	MICHELIN	4 mm
	R/H Rear Tyre	225/55 R17	MICHELIN	4 mm
	L/H Rear Tyre	225/55 R17	MICHELIN	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information				
	Accident Date	12/01/2022	Inspection Date	18/01/2022
	Survey held at	AH KOON MOTOR BLK 1001 BUKIT MERAH LANE 3 #01-69 SINGAPORE 159718		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	