

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000648/AVY3N2**Date:** 24/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00048872101

Claimant Vehicle No : XE5300R **Insured Vehicle No :** XE3520K

Date of Loss: 15/01/2022 Nature of Claim: TP Claim No: SNM22D200451/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE5300R**

Make & Model: MITSUBISHI FUSO, 12.0 D FV51SJD2DEA (M) Engine No: 470912C0475556

Reg. Date: 25/10/2019 (Man. Year: 2019) Chassis No: FP70HDA00050

Colour: White Odometer: 169941 km

Engine Capacity: 10677 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80R22.5 Rear Tyre Size: 295/80R22.5

Front Left Side: Firena 9 mm Rear Left Side: Firena 9 mm

Front Right Side: Firena 9 mm Rear Right Side: Firena 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,111.18	15,850.61	23,260.57	59.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,170.00	4,560.00	3,610.00	44.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	47,281.18	20,410.61	26,870.57	56.83
Approved Total (Overridden) (\$\$)		16,300.00		
Nett Amount (\$\$)	47,281.18	16,300.00	30,981.18	65.53

INSPECTION

Date of Assignment: 19/01/2022

Date Inspected: 18/01/2022 Inspected At: HD Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 May 2022)	
Parts:	N/A	MITSUBISHI FUSO 12.0 D FV51SD2DEA (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE5300R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Chipped	2,790.17 FL	*2,790.17 FL
2	1		*FRONT WINDSCREEN MOULDING	Necessary	694.38 FL	*694.38 FL
3	1		*BONNET	Buckled	2,349.98 FL	*2,349.98 FL
4	2		*BONNET LOCK	Not Necessary	145.16 FL	*- FL
5	2		*BONNET HINGE	Not Necessary	429.74 FL	*- FL
6	1		*BONNET DAMPER	Not Necessary	184.79 FL	*- FL
7	1		*BONNET EMBLEM FUSO	Necessary	320.88 FL	*320.88 FL
8	1		*FRONT GRILLE	Cracked	556.77 FL	*556.77 FL
9	1		*FRONT GRILLE BASE	Not Necessary	558.51 FL	*- FL
10	1		*FRONT GRILLE LOGO	Necessary	307.30 FL	*307.30 FL
11	1		*FRONT GRILLE EMBLEM SUPER GREAT	Necessary	202.50 FL	*202.50 FL
12	1		*FRONT BUMPER	Distorted	2,645.41 FL	*2,645.41 FL
13	2		*FRONT BUMPER CENTRE STEP GARNISH	Not Necessary	242.08 FL	*- FL
14	1		*FRONT BUMPER CENTRE STEP GARNISH UPPER	Not Necessary	71.79 FL	*- FL
15	1		*FRONT BUMPER TOWING COVER GARNISH LH	Cracked	120.61 FL	*120.61 FL
16	1		*FRONT BUMPER SIDE GARNISH LH	Missing	127.30 FL	*127.30 FL
17	1		*FRONT BUMPER CENTER COVER GARNISH	Cracked	346.16 FL	*346.16 FL
18	2		*FRONT BUMPER UPPER SIDE PANEL INNER	Bent	373.06 FL	*373.06 FL
19	1		*FRONT HEADLAMP LH	Cracked	974.85 FL	*974.85 FL
20	1		*FRONT HEADLAMP RING LH	Missing	305.22 FL	*305.22 FL
21	1		*FRONT HEADLAMP SUPPORT BRACKET LH	Not Necessary	314.75 FL	*- FL
22	1		*FRONT FOGLAMP LH	Cracked	296.48 FL	*296.48 FL
23	1		*FRONT LAMP WIRE HARNESS LH	Not Necessary	7,566.84 FL	*- FL
24	1		*ROOF LINING	Not Necessary	2,471.69 FL	*- FL
25	1		*CABIN ROOF TOP SIDE PANEL LH	Repair	1,325.41 FL	*- FL
26	1		*CABIN ROOF TOP SIDE TRIM LH	Repair	342.18 FL	*- FL
27	1		*SIDE MIRROR STAND LH	Bent	1,300.47 FL	*684.00 FL
28	1		*SIDE MIRROR ROUND LH	Cracked	384.44 FL	*384.44 FL
29	1		*SIDE MIRROR SQUARE LH (BIG)	Missing	395.84 FL	*395.84 FL
30	1		*SIDE MIRROR SQUARE LH (SMALL)	Missing	327.14 FL	*327.14 FL
31	1		*FRONT PILLAR INNER LH	Repair	1,321.12 FL	*- FL
32	1		*FRONT PILLAR OUTER LH	Repair	1,468.17 FL	*- FL
33	1		*FRONT DOOR LH	Buckled	3,364.73 FL	*3,364.73 FL
34	1		*FRONT DOOR INNER TRIM LH	Not Necessary	1,809.77 FL	*- FL
35	1		*FRONT DOOR WEATHERSTRIP LH	Not Necessary	511.33 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRONT DOOR FRAME WEATHER STRIP LH	Not Necessary	341.60 FL	*- FL
37	1		*FRONT DOOR OUTER STRIP LH	Not Necessary	560.49 FL	*- FL
38	1		*FRONT DOOR LAMP LH	Cracked	118.77 FL	*118.77 FL
39	2		*FRONT CORNER PANEL	Cracked	1,087.80 FL	*1,087.80 FL
40	2		*FRONT CORNER PANEL INNER SUPPORT BRACKET (FRONT) LH	Damaged	310.08 FL	*125.00 FL
41	1		*FRONT CORNER PANEL INNER SUPPORT BRACKET (REAR) LH	Damaged	111.88 FL	*111.88 FL
42	2		*FRONT CORNER PANEL SIDE RUBBER LH	Cut	127.50 FL	*127.50 FL
43	1		*FRONT WHEEL ARCED GARNISH LH	Not Necessary	32.38 FL	*- FL
44	1		*FRONT WHEEL FENDER LH	Not Necessary	608.58 FL	*- FL
45	1		*FENDER SIDE GARNISH LH	Not Necessary	564.62 FL	*- FL
46	1		*FENDER SIDE GARNISH INNER STRIP LH	Not Necessary	222.10 FL	*- FL
47	1		*FRONT UPPER STEP PANEL LH	Cut	317.51 FL	*317.51 FL
48	1		*FRONT CENTER STEP PANEL INNER GARNISH LH	Cracked	540.14 FL	*540.14 FL
49	1		*FRONT CENTER STEP PANEL LH	Not Necessary	316.81 FL	*- FL
50	1		*FRONT LOWER STEP PANEL INNER GARNISH LH	Not Necessary	540.14 FL	*- FL
51	1		*FRONT LOWER STEP PANEL LH	Not Necessary	316.81 FL	*- FL
52	1		*FRONT LOWER STEP PANEL LOWER GARNISH LH	Not Necessary	399.98 FL	*- FL
53	1		*FRONT LOWER STEP PANEL BOTTOM GARNISH REFLECTOR LH	Not Necessary	38.27 FL	*- FL
54	1		*FRONT LOWER STEP PANEL SUPPORT BRACKET LH (FRONT)	Not Necessary	526.86 FL	*- FL
55	1		*FRONT LOWER STEP PANEL SUPPORT BRACKET LH (REAR)	Not Necessary	456.20 FL	*- FL
56	1		*AIRCON CONDENSER	Not Necessary	2,496.10 FL	*- FL
57	1		*AIRCON CONDENSER BRACKET	Not Necessary	454.18 FL	*- FL
58	1		*AIRCON FAN COWLING	Cracked	856.77 FL	*485.00 FL
59	1		*AIRCON FAN MOTOR	Not Necessary	782.63 FL	*- FL
60	1		*AIRCON PIPE (BIG)	Not Necessary	261.19 FL	*- FL
61	1		*AIRCON PIPE (SMALL)	Not Necessary	302.36 FL	*- FL
62	1		*TEMPERATURE SENSOR	Not Necessary	122.81 FL	*- FL
63	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
64	1		*SET FRONT BUMPER CENTRE STEP GARNISH CLIP	Necessary	80.00 FS	*20.00 FS
65	1		*SET FRONT BUMPER TOWING COVER GARNISH CLIP	Necessary	80.00 FS	*20.00 FS
66	1		*SET FRONT BUMPER SIDE GARNISH CLIP	Necessary	80.00 FS	*20.00 FS
67	1		*FRONT WINDSCREEN GLASS SEALANT	Necessary	120.00 FS	*80.00 FS
68	1		*FRONT ROOF TOP SIDE TRIM CLIP	Not Necessary	40.00 FS	*- FS
69	1		*FRONT ROOF TOP SIDE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
70	1		*SET FRONT CENTRE STEP PANEL INNER GARNISH CLIP	Not Necessary	80.00 FS	*- FS
71	1		*SET FRONT LOWER STEP PANEL LOWER GARNISH CLIP	Not Necessary	80.00 FS	*- FS
72	1		*SET FRONT LOWER STEP PANEL BOTTOM GARNISH CLIP	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

5/24/22, 3:57 PM			Adjuster Report			
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
73	1		*SET FRONT WHEEL ARCED GARNISH CLIP	Not Necessary	80.00 FS	*- FS
74	1		*SET FRONT CENTER GRILLE CLIP	Necessary	80.00 FS	*30.00 FS
75	1		*FRONT ERP BRACKET	Necessary	30.00 FS	*20.00 FS
76	1		*BONNET STICKER COMPANY STICKER	Necessary	650.00 FS	*250.00 FS
77	1		*FRONT DOOR STICKER SGIFT PILOT	Necessary	180.00 FS	*50.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (\$)	51,551.58	20,970.82
				- List Item Discount on L Items 25.00/25.00% (\$)	12,440.40	5,120.21
				Total Parts (\$)	39,111.18	15,850.61
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT,KNOCK,WELD,CUT,ADJUST,STRAIGHTEN,GRAZE,ALIGN	New	3,200.00	2,100.00
2	TO PUTTY,SPRAY PAINT,POLISH,WAX	New	2,000.00	1,700.00
3	TO SPRAY RUST PROOFING AND UNDER COAT	New	250.00	100.00
4	REMOVE AND REFIX UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	650.00	200.00
5	REMOVE AND REFIX FRONT WINDSCREEN GLASS	New	180.00	180.00
6	REFOCUS HEADLAMP BEAM	New	180.00	0.00
7	REMOVE AND REINSTALL FRONT WINDOW GLASS	New	180.00	40.00
8	TRANSFER FRONT DOOR MECHANISM	New	120.00	100.00
9	REMOVE BAD REFIX DASHBOARD	New	650.00	0.00
10	REMOVE AND REFIX AIRCON CONDENSER AND REFILL AIR CON GAS	New	280.00	140.00
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	480.00	0.00
Gross Labour Cost (\$\$)			8,170.00	4,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >