

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000649/AQY3N2**Date:** 09/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00115542100	
Claimant Vehicle No :	SLG4157B	Insured Vehicle No :	GBG1070E	
Date of Loss:	15/01/2022	Nature of Claim:	TP	Claim No: SNM22D200423/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG4157B		Engine No:	P520376264
Make & Model:	MAZDA 3, 1.5 (A)		Chassis No:	JM6BM42A8G0346914
Reg. Date:	29/09/2016 (Man. Year: 2016)		Odometer:	146957 km
Colour:	Blue			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,302.00	10,372.80	8,929.20	46.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,980.00	3,830.00	3,150.00	45.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	26,282.00	14,202.80	12,079.20	45.96
Approved Total (Overridden) (\$\$)		11,300.00		
Nett Amount (\$\$)	26,282.00	11,300.00	14,982.00	57.00

INSPECTION

Date of Assignment:	28/01/2022	JL Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit Singapore 415875
Date Inspected:	18/01/2022 Inspected At:	
Estimated Period of Repair:	12.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2022)
Parts:	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG4157B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	998.10 FL	*998.10 FL
2	2		*REAR BUMPER REFLECTOR	Cracked	179.60 FL	*179.60 FL
3	2		*REAR BUMPER TOW HOOK COVER	Missing	36.00 FL	*36.00 FL
4	2		*REAR BUMPER LOWER CORNER GARNISH	Not Necessary	95.20 FL	*- FL
5	2		*REAR BUMPER SIDE RETAINER	Necessary	106.60 FL	*106.60 FL
6	1		*REAR BUMPER CENTER BRACKET	Not Necessary	196.80 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Distorted	498.90 FL	*498.90 FL
8	2		*TAIL LAMP	Cracked	956.60 FL	*956.60 FL
9	2		*TAIL LAMP PANEL	Dented	568.20 FL	*568.20 FL
10	1		*REAR DOOR RH	Dented	1,270.40 FL	*1,270.40 FL
11	2		*REAR DOOR INNER LOCK	Damaged	425.60 FL	*425.60 FL
12	2		*REAR DOOR INNER TRIM BOARD	Not Necessary	827.20 FL	*- FL
13	2		*REAR DOOR LOCK CLUTCH	Not Necessary	52.20 FL	*- FL
14	2		*REAR DOOR WEATHER STRIP	Not Necessary	273.40 FL	*- FL
15	2		*REAR DOOR FRAME WEATHERSTRIP	Not Necessary	396.20 FL	*- FL
16	2		*REAR FENDER	Buckled	2,348.40 FL	*2,348.40 FL
17	2		*REAR FENDER INNER PANEL RH	Repair	856.00 FL	*- FL
18	2		*REAR FENDER INNER TRIM	Not Necessary	437.40 FL	*- FL
19	2		*REAR FENDER INNER COWLING	Not Necessary	284.40 FL	*- FL
20	1		*REAR WHEEL HOUSE PANEL RH	Not Necessary	1,240.30 FL	*- FL
21	1		*REAR WINDSCREEN MOULDING	Necessary	98.10 FL	*98.10 FL
22	1		*BOOT LID	Distorted	889.60 FL	*889.60 FL
23	2		*BOOT LID NUMBER PLATE LAMP	Not Necessary	95.60 FL	*- FL
24	2		*BOOT LID LAMP	Cracked	492.20 FL	*492.20 FL
25	1		*BOOT LID REVERSE CAMERA	Not Necessary	1,016.00 FL	*- FL
26	1		*BOOT LID LOGO	Necessary	69.00 FL	*69.00 FL
27	1		*BOOT LID EMBLEM MAZDA 3	Necessary	49.50 FL	*49.50 FL
28	1		*BOOT LID EMBLEM SKYACTIV TECHNOLOGY	Necessary	59.60 FL	*59.60 FL
29	1		*BOOT LID INSULATOR	Not Necessary	246.10 FL	*- FL
30	1		*BOOT LID INNER HOLDER	Not Necessary	63.40 FL	*- FL
31	2		*BOOT LID STOPPER (UPPER)	Not Necessary	40.00 FL	*- FL
32	1		*BOOT LID TOP LOCK	Damaged	142.50 FL	*142.50 FL
33	1		*BOOT LID OUTER SWITCH BUTTON	Not Necessary	189.10 FL	*- FL
34	1		*BOOT LID LOWER LOCK	Not Necessary	25.10 FL	*- FL
35	1		*BOOT LID WEATHERSTRIP	Cut	128.70 FL	*128.70 FL
36	2		*BOOT LID HINGE	Bent	128.00 FL	*128.00 FL
37	2		*BOOT LID HINGE COVER GARNISH	Not Necessary	144.40 FL	*- FL
38	1		*REAR END PANEL	Distorted	469.70 FL	*469.70 FL
39	1		*REAR END PANEL TOP GARNISH	Deformed	114.60 FL	*114.60 FL
40	1		*REAR FLOOR SIDE PANEL RH	Repair	547.00 FL	*- FL
41	1		*REAR FLOOR PANEL TOP BOARD	Torn	374.70 FL	*374.70 FL
42	1		*REAR FLOOR TOP SPONGE	Torn	750.00 FL	*375.00 FL
			2 Pcs			
43	1		*REAR CHASIS MEMBER RH	Not Necessary	979.00 FL	*- FL
44	1		*REAR EXHAUST BOX	Dented	986.40 FL	*986.40 FL
45	1		*REAR EXHAUST INSULATOR	Not Necessary	168.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*SET REAR EXHAUST GASKET	Not Necessary	60.00 FL	*- FL
47	2		*REAR EXHAUST MOUNTING	Not Necessary	78.00 FL	*- FL
48	1		*REAR NUMBER PLATE	Bent	80.00 FS	*50.00 FS
49	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
50	1		*SET TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
51	2		*TAIL LAMP PANEL SEALANT	Not Necessary	120.00 FS	*- FS
52	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	80.00 FS	*- FS
53	1		*SET REAR DOOR INNER TRIM BOARD CLIP RH	Not Necessary	80.00 FS	*- FS
54	2		*REAR FENDER SEALANT	Necessary	300.00 FS	*100.00 FS
55	1		*REAR FENDER INNER PANEL SEALANT RH	Not Necessary	80.00 FS	*- FS
56	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	80.00 FS	*60.00 FS
57	1		*SET REAR FENDER COWLING CLIPS	Not Necessary	80.00 FS	*- FS
58	1		*REAR WHEEL HOUSE PANEL SEALANT RH	Not Necessary	120.00 FS	*- FS
59	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
60	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
61	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	550.00 FS	*- FS
62	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
63	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
64	1		*REAR FLOOR SIDE PANEL RH SEALANT	Not Necessary	250.00 FS	*- FS
65	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
66	1		*REVERSE CAMERA	Missing	450.00 FS	*380.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	23,392.50	12,726.00
- List Item Discount on L Items 20.00/20.00% (\$)	4,090.50	2,353.20
Total Parts (\$)	19,302.00	10,372.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	2,800.00	1,600.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,200.00	1,500.00
3	TUFF COAT	New	250.00	100.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	350.00	80.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	120.00	50.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	180.00	50.00
8	TRANSFER REAR DOOR MECHANISM	New	80.00	80.00
9	TRANSFER BOOTLID MECHANISM	New	80.00	60.00
10	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
11	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	80.00
12	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	120.00
13	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	New	80.00	80.00
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	280.00	0.00
Gross Labour Cost (\$\$)			6,980.00	3,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >