

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22000652/DVF3E2

Date: 29/07/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001345463
Claimant Vehicle No :	SHC838P	Insured Vehicle No :	GBE7908K
Date of Loss:	17/01/2022	Nature of Claim:	TP
		Claim No:	268461

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC838P	Engine No:	2ZR2G75410
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU203091172
Reg. Date:	19/02/2020 (Man. Year: 2020)	Odometer:	201189 km
Colour:	Yellow		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,521.92	6,555.52	9,966.40	60.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,900.00	1,820.00	3,080.00	62.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,421.92	8,375.52	13,046.40	60.90
+ GST 7.00/7.00% (S\$)	1,499.53	586.29	913.24	60.90
Nett Amount (S\$)	22,921.45	8,961.81	13,959.64	60.90

INSPECTION

Date of Assignment:	19/01/2022	
Date Inspected:	19/01/2022 Inspected At:	Bifrost Auto Pte Ltd (sin Ming) (HQ) Blk 9 Sector C, #01-42 Sin Ming Industrial Estate Singapore 575644
Estimated Period of Repair:	5.0 days	

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jun 2022)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC838P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID COVER	Dented	1,577.24 FL	*1,577.24 FL
2	1		*REAR TRUNK LID LOCK	Serviceable	641.06 FL	*- FL
3	1		*REAR TRUNK LID COVER TRIM BOARD	Not Necessary	303.10 FL	*- FL
4	1		*REAR TRUNK LID RUBBER	Necessary / Deformed	511.28 FL	*365.20 FL
5	1		*REAR TRUNK LID LAMP G5	Cracked	891.52 FL	*636.60 FL
6	1		*BOARD ASSY, BACK DOOR TRIM	Not Necessary	356.16 FL	*- FL
7	1		*GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	Cracked	1,845.58 FL	*913.60 FL
8	1		*REAR TRUNK LID LOGO (PRIUS)	Necessary	85.12 FL	*85.12 FL
9	1		*REAR TRUNK LID LOGO (HYBRID)	Necessary	73.36 FL	*73.36 FL
10	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	Necessary	74.06 FL	*74.06 FL
11	1		*REAR BUMPER	Dented	642.04 FL	*642.04 FL
12	1		*REAR BUMPER REINFORCEMENT	Dented / Bent	446.32 FL	*446.32 FL
13	1		*REAR BUMPER UNDER COVER	Dented	773.64 FL	*552.60 FL
14	2		*REAR BUMPER SIDE RETAINER	Serviceable	315.56 FL	*- FL
15	2		*REAR BUMPER UNDER SIDE CENTRE COVER	Not Necessary	1,547.28 FL	*- FL
16	1		*REAR BUMPER TOWING COVER	Dislodged	115.78 FL	*82.70 FL
17	1		*REAR BUMPER CLIPS	Necessary	30.80 FL	*30.80 FL
18	2		*REAR BUMPER SIDE CLIP	Not Necessary	70.00 FL	*- FL
19	1		*REAR BUMPER UPPER STOPPER	Not Necessary	106.96 FL	*- FL
20	1		*ARM SUB-ASSY, REAR BUMPER, RH	Not Necessary	195.44 FL	*- FL
21	1		*REAR BUMPER UNDER SIDE COVER (RH)	Mtg Cracked / Broken	324.80 FL	*232.00 FL
22	1		*RETAINER, REAR BUMPER, SIDE, RH	Not Necessary	132.72 FL	*- FL
23	1		*RETAINER, REAR BUMPER, UPPER SIDE (LH/RH)	Not Necessary	42.98 FL	*- FL
24	1		*REAR BUMPER LOWER COVER GARNISH G5	Not Necessary	963.63 FL	*- FL
25	1		*TAIL LAMP ASSY (UPPER) G5	Cracked	942.90 FL	*577.90 FL
26	1		*TAIL LAMP ASSY (LOWER) G5	Cut	860.58 FL	*554.00 FL
27	1		*TAIL LAMP QUARTER PANEL	Repair	302.40 FL	*- FL
28	1		*TAIL LAMP SIDE COVER	Mtg Cracked	358.40 FL	*256.00 FL
29	1		*REAR END PANEL	Dented	842.94 FL	*612.00 FL
30	1		*REAR END PANEL GARNISH	Mtg Cracked	226.52 FL	*226.52 FL
31	1		*REAR FIBER TOOL BOX TRIM	Not Necessary	557.20 FL	*- FL
32	1		*REAR EXHAUST PIPE RH	Not Necessary	1,628.76 FL	*- FL
33	1		*REAR EXHAUST PIPE HANGER	Not Necessary	56.98 FL	*- FL
34	1		*REAR FENDER, RH	Not Necessary	1,171.38 FL	*- FL
35	1		*REAR FENDER SHIELD (LH/RH)	Not Necessary	187.88 FL	*- FL
36	1		*REAR FENDER AIR DUCT	Not Necessary	231.14 FL	*- FL
37	1		*REAR TRUNK LOWER W/S MOULDING	Necessary	180.00 FS	*180.00 FS
38	1		*REAR LOWER W/S SEALANT	Necessary	46.00 FS	*46.00 FS
39	1		*REAR WINDSCREEN MOULDING	Not Necessary	160.00 FS	*- FS
40	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
41	1		*REAR NO. PLATE WITH TRIM COVER	Not Necessary	140.00 FS	*- FS
42	1		*REAR TRUNK LID APPS STICKER	Necessary	56.00 FS	*56.00 FS
43	1		*REAR TRUNK LID COMFORT & TEL NO. STICKER	Necessary	84.00 FS	*84.00 FS
44	1		*REAR BUMPER REVERSE SENSOR	Damaged	189.98 FS	*189.98 FS
45	1		*LAMP ASSY, SIDE TURN SIGNAL, RH	Not Necessary	91.42 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (\$)	20,426.91	8,540.04
					- List Item Discount on L Items 20.00/25.00% (\$)	3,904.99	1,984.52
					Total Parts (\$)	16,521.92	6,555.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	700.00
2	SPRAY PAINTING CHARGE	New	1,600.00	700.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE / REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE / REFIX REAR WINDSCREEN GLASS	New	240.00	80.00
8	REMOVE / REFIX REVERSE SENSOR	New	120.00	40.00
9	REMOVE / REFIX FUEL TANK	New	80.00	0.00
10	REMOVE / REFIX EXHAUST PIPE	New	80.00	0.00
11	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	150.00
Gross Labour Cost (\$\$)			4,900.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >