

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22000657/UPA3Q2**Date:** 11/05/2022REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 1900244033   |
| <b>Claimant Vehicle No :</b> | SJH4477X                             | <b>Insured Vehicle No :</b> | SLR2420X     |
| Date of Loss:                | 17/01/2022                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 3168862638SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |               |
|-----------------------------|-----------------------------------|-------------|---------------|
| Reg No:                     | <b>SJH4477X</b>                   | Engine No:  | 1NZD067989    |
| Make & Model:               | TOYOTA COROLLA AXIO, 1.5 X (A)    | Chassis No: | NZE1416083864 |
| Reg. Date:                  | 07/08/2008 (Man. Year: 2008)      | Odometer:   | 394941 km     |
| Colour:                     | Silver                            |             |               |
| Engine Capacity:            | 1496 cc                           |             |               |
| Market Value/New Car Price: | N/A                               |             |               |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |               |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 195/60 R15  | Rear Tyre Size:  | 195/60 R15  |
| Front Left Side:  | KAPSEN 6 mm | Rear Left Side:  | KAPSEN 6 mm |
| Front Right Side: | KAPSEN 6 mm | Rear Right Side: | KAPSEN 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts   | 13,934.40         | 6,080.52          | 7,853.88          | 56.36         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour  | 3,930.00          | 2,560.00          | 1,370.00          | 34.86         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing  | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>17,864.40</b>  | <b>8,640.52</b>   | <b>9,223.88</b>   | <b>51.63</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>6,650.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 17,864.40         | 6,650.00          | 11,214.40         | 62.78         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 1,250.51          | 465.50            | 785.01            | 62.78         |
| <b>Nett Amount (S\$)</b>                        | <b>19,114.91</b>  | <b>7,115.50</b>   | <b>11,999.41</b>  | <b>62.78</b>  |
| <b>+ Car Rental (5.0 x S\$100.00/day) (S\$)</b> |                   | 500.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 2.00              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>7,617.50</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>7,600.00</b>   |                   |               |

INSPECTION

|                             |            |   |
|-----------------------------|------------|---|
| Date of Assignment:         | 18/01/2022 |   |
| Date Inspected:             | 18/01/2022 | Inspected At: Fastech Auto Pte Ltd (HQ)<br>1 Kaki Bukit Ave 6, #01-46/48/50 Autobay<br>Singapore 417883 |
| Estimated Period of Repair: | 5.0 days   |   |

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                                 | Condition        | Repairer's | Amount       |
|-----|-----|----------|---|------------------|------------|--------------|
| 1   | 1   |          | *BOOTLID                                    | Dented / Buckled | 1,266.10 F | *845.10 FL   |
| 2   | 1   |          | *BOOTLID REAR LOGO                          | Necessary        | 68.50 F    | *68.50 FL    |
| 3   | 1   |          | *BOOTLID AXIO EMBLEM                        | Necessary        | 62.80 F    | *62.80 FL    |
| 4   | 1   |          | *BOOTLID X LOGO                             | Necessary        | 58.00 F    | *58.00 FL    |
| 5   | 1   |          | *BOOTLID OUTER HANDLE                       | Cracked          | 338.00 F   | *332.80 FL   |
| 6   | 1   |          | *BOOTLID INNER LOCK                         | Bent             | 409.10 F   | *398.10 FL   |
| 7   | 1   |          | *BOOTLID LOCK STRICKER                      | Serviceable      | 66.80 F    | *- FL        |
| 8   | 1   |          | *BOOTLID WEATHERSTRIP                       | Twisted          | 282.30 F   | *282.30 FL   |
| 9   | 1   |          | *BOOTLID INNER TRIM                         | Deformed / Torn  | 366.10 F   | *366.10 FL   |
| 10  | 1   |          | *BOOTLID HINGES                             | Repair           | 290.00 F   | *- FL        |
| 11  | 1   |          | *REAR BUMPER                                | Distorted        | 655.10 F   | *655.10 FL   |
| 12  | 2   |          | *REAR BUMPER DAMPERS                        | Dented           | 210.00 F   | *210.00 FL   |
| 13  | 2   |          | *REAR BUMPER REFLECTORS                     | Cracked          | 120.00 F   | *120.00 FL   |
| 14  | 2   |          | *REAR BUMPER SIDE RETAINERS                 | Cracked          | 130.00 F   | *130.00 FL   |
| 15  | 1   |          | *SET REAR BUMPER CLIPS                      | Necessary        | 50.00 F    | *50.00 FL    |
| 16  | 1   |          | *REAR END PANEL                             | Badly Dented     | 788.20 F   | *602.10 FL   |
| 17  | 1   |          | *REAR END PANEL TOP GARNISH                 | Twisted          | 362.30 F   | *362.30 FL   |
| 18  | 2   |          | *TAILLAMP HOUSING PANELS                    | Repair           | 770.00 F   | *- FL        |
| 19  | 2   |          | *TAILLAMPS                                  | Cracked          | 1,160.00 F | *1,090.20 FL |
| 20  | 2   |          | *TAILLAMP LOWER BRACKETS                    | Cracked          | 130.00 F   | *130.00 FL   |
| 21  | 1   |          | *REAR FLOOR PANEL                           | Repair           | 1,145.20 F | *- FL        |
| 22  | 1   |          | *REAR FLOOR PANEL TOP BOARD                 | Warped           | 620.50 F   | *542.10 FL   |
| 23  | 1   |          | *REAR FLOOR PANEL SPARE TYRE LOCK NUT       | Twisted          | 85.00 F    | *85.00 FL    |
| 24  | 2   |          | *REAR FENDER INNER TRIMS                    | Deformed / Torn  | 910.20 F   | *850.20 FL   |
| 25  | 2   |          | *REAR FENDERS                               | Repair           | 2,180.20 F | *- FL        |
| 26  | 1   |          | *SET REAR BUMPER REVERSE SENSOR             | Shorted          | 280.00 FS  | *200.00 FS   |
| 27  | 1   |          | *SET REAR REVERSE CAMERA                    | Serviceable      | 380.00 FS  | *- FS        |
| 28  | 1   |          | *REAR END PANEL SEALANT                     | Necessary        | 50.00 FS   | *50.00 FS    |
| 29  | 1   |          | *SET REAR FLOOR PANEL SOUND PROOF INSULATOR | Necessary        | 550.00 FS  | *300.00 FS   |
| 30  | 1   |          | *SET BOOTLID INNER TRIM CLIPS               | Necessary        | 50.00 FS   | *30.00 FS    |
| 31  | 1   |          | *REAR LICENCE PLATE                         | Bent             | 50.00 FS   | *40.00 FS    |
| 32  | 1   |          | *SET REAR FENDER INNER TRIM CLIPS           | Necessary        | 50.00 FS   | *30.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)** 13,934.40 7,890.70  
**- List Item Discount on L Items 0.00/25.00% (\$\$)** 0.00 1,810.18

**Total Parts (\$\$)** 13,934.40 6,080.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                            | Particulars                               | Lab.Type | Repairer's      | Amount          |
|-------------------------------|---|----------|-----------------|-----------------|
| <b>Labour Items</b>           |   |          |                 |                 |
| 1                             | TO CHECK WIRING                           | New      | 50.00           | 30.00           |
| 2                             | TO DISMANTLE & REPLACED REVERSE SENSOR    | New      | 80.00           | 50.00           |
| 3                             | TO DISMANTLE & REFIX BOOTLID MECHANISM    | New      | 100.00          | 60.00           |
| 4                             | TO DISMANTLE & REFIX CUSHION UPHOLSTERY   | New      | 120.00          | 80.00           |
| 5                             | TO DISMANTLE & REFIX FUEL TANK            | New      | 80.00           | 0.00            |
| 6                             | TO SPRAY RUST PROOFING                    | New      | 100.00          | 60.00           |
| 7                             | LABOUR FOR PANEL BEATING & REPLACED PARTS | New      | 1,600.00        | 1,100.00        |
| 8                             | TO PUTTY & SPRAY PAINTING                 | New      | 1,800.00        | 1,180.00        |
| <b>Gross Labour Cost (\$)</b> |   |          | <b>3,930.00</b> | <b>2,560.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >