



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 7547J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (WCP)	DISTORTED	900.00	900.00
1	FRT BUMPER RETAINER RH (WCP)	CRACKED	45.00	45.00
10	FRT BUMPER CLIP (WCP)	NECESSARY	45.00	45.00
1	FRT BUMPER LOWER RH (MATT BLACK) (WCP)	GRAZED	110.00	110.00
1	FRT BUMPER SIDE GRILLE RH (WCP)	CUT	50.00	50.00
1	FRT BUMPER LOWER GRILLE (WCP)	NOT NECESSARY	150.00	-
1	LOWER GRILLE OUTER CHROME TRIM (WCP)	TWISTED	450.00	450.00
1	FRT BUMPER INNER SPONGE (WCP)	NOT NECESSARY	135.00	-
1	FRT BUMPER REINFORCEMENT (WCP)	NOT NECESSARY	300.00	-
1	FRT PARKING SENSOR RH (OUTER) (WCP)	NOT NECESSARY	185.00	-
1	FRT PARKING SENSOR RH (CTR) (WCP)	NOT NECESSARY	185.00	-
1	FRT NOZZLE COVER RH (WCP)	TWISTED	55.00	55.00
1	FRT NOZZLE RH (WCP)	NOT NECESSARY	185.00	-
1	FRT NOZZLE HOSE (WCP)	NOT NECESSARY	85.00	-
1	FRT BUMPER LOGO (WCP)	NOT NECESSARY	60.00	-
1	FRT BUMPER CTR TOP SEAL (WCP)	NOT NECESSARY	85.00	-
1	HEADLAMP RH (WCP)	CRACKED	1,650.00	1,650.00
1	HEADLAMP BRACKET RH (WCP)	NOT NECESSARY	55.00	-
1	HEADLAMP SUPPORT PANEL (WCP)	CRACKED	550.00	550.00
1	HEADLAMP CONTROL UNIT (WCP)	NOT NECESSARY	500.00	-
1	RADIATOR SPARE TANK (WCP)	NOT NECESSARY	135.00	-
1	RADIATOR SPARE TANK HOSE (LWR) (WCP)	NOT NECESSARY	75.00	-
1	FRT FENDER RH (WCP)	BUCKLED	580.00	580.00
1	FRT FENDER PROTECTOR RH (WCP)	DISTORTED	180.00	180.00
10	PROTECTOR CLIP (WCP)	NOT NECESSARY	45.00	-
1	FRT FENDER INNER COWLING RH (WCP)	TORN	165.00	165.00
10	INNER COWLING CLIP (WCP)	NECESSARY	45.00	45.00
1	FRT SHOCK ABSORBER RH (WCP)	BENT	520.00	520.00
1	FRT SHOCK ABSORBER TOP MOUNTING RH (WCP)	NOT NECESSARY	195.00	-
1	FRT KNUCKLE ARM RH (WITH BEARING) (WCP)	WARPED	615.00	615.00
1	FRT LOWER ARM RH (WCP)	BENT	450.00	450.00

Report Ref No. CS/LPC22000658/Uqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT ANTI ROLL BAR LINK RH (WCP)	BENT	65.00	65.00
1	FRT TIE ROD END RH (WCP)	BENT	125.00	125.00
1	FRT RACK END RH (WCP)	BENT	145.00	145.00
1	STEERING RACK ASSY (WCP)	NOT NECESSARY	3,300.00	-
1	STEERING CROSSMEMBER (WCP)	NOT NECESSARY	1,100.00	-
1	FRT LH SPORT RIM (ORI) (WCP)	CUT	680.00	680.00
1	FRT FENDER SIDE BRACKET RH (WCP)	NOT NECESSARY	35.00	-
1	FRT ENGINE UNDER COVER (WCP) (ADDITIONAL)	TORN	220.00	220.00
	COST PLUS 15%		2,168.25	1,146.75
			16,623.25	8,791.75
	<u>SPECIAL NETT ITEMS</u>			
1	FRT RH TYRE (SN) (70%)	CUT	390.00	273.00
1	RADIATOR COOLANT (SN)	NOT NECESSARY	25.00	-
			415.00	273.00
	<u>LABOUR</u>			
	WIRE CHECKING.		30.00	20.00
	REMOVE & REFIX AIRCON AND GAS.		100.00	100.00
	REMOVE & REFIX FRT UNDERCARRIAGE (WITH CROSSMEMBER).		350.00	300.00
	WHEEL ALIGNMENT.		100.00	60.00
	REPROGRAMME HEADLAMP.	NOT NECESSARY	550.00	-
	LABOUR CHARGE.		850.00	600.00
	SPRAY PAINTING.		800.00	600.00
			2,780.00	1,680.00
	GRAND TOTAL		19,818.25	10,744.75

RECOMMENDED COST OF REPAIRS			10,744.75
LESS EXCESS			-500.00
NETT LIABILITY			10,244.75

Report Ref No. CS/LPC22000658/Uqf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.