



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JTE 5013

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	FRONT FORK TUBE ASSY (CONSISTENT)	SERVICEABLE	640.00	-
1	FORK UNDER BRACKET (CONSISTENT)	NOT NECESSARY	185.00	-
1	FRONT WHEEL RIM (CONSISTENT)	NOT NECESSARY	280.00	-
1	FRONT RIM SHAFT (CONSISTENT)	NOT NECESSARY	45.00	-
1	FRONT RIM BEARING (CONSISTENT)	NOT NECESSARY	38.00	-
1	FRONT BRAKE DISC (CONSISTENT)	NOT NECESSARY	155.00	-
1	MIRROR (O/S) (CONSISTENT)	CUT	80.00	60.00
1	HANDLE-BAR (CONSISTENT)	BENT	88.00	88.00
1	HANDLE -BAR END (CONSISTENT)	MISSING / CUT	65.00	30.00
1	HAND GRIP (CONSISTENT)	TORN	55.00	55.00
1	FRONT HORN INNER COVER CENTRE MATT BLACK (CONSISTENT)	CUT	70.00	70.00
1	FRONT SIGNALS (O/S) (CONSISTENT)	CUT	140.00	75.00
1	PILOT LIGHTS (CONSISTENT)	CRACKED	228.00	155.00
1	BRAKE LEVER (CONSISTENT)	BENT	55.00	55.00
1	SET FAIRING ASSY (CONSISTENT)	CUT	525.00	525.00
1	FRONT FOOTREST (CONSISTENT)	CUT	95.00	48.00
1	SET FRONT FOOTREST BRACKET (CONSISTENT)	BENT	70.00	70.00
1	BRAKE PEDAL (CONSISTENT)	BENT	42.00	42.00
1	MASTER PUMP (CONSISTENT)	CUT	230.00	230.00
1	SET REAR FOOTREST (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR FOOTREST BRACKET (CONSISTENT)	NOT NECESSARY	78.00	-
1	EXHAUST ASSY (CONSISTENT)	DENTED	485.00	485.00
1	EXHAUST PROTECTOR -REAR (CONSISTENT)	TORN	60.00	60.00
1	EXHAUST PROTECTOR -FRONT (CONSISTENT)	TORN	45.00	45.00
1	EXHAUST PIPE AND COVER (CONSISTENT)	TORN	55.00	55.00
1	REAR HANDLE (CONSISTENT)	TO REPAIR SEE LABOUR	180.00	-
1	SET REAR SIGNALS (N/S) (CONSISTENT)	CRACKED	140.00	75.00
	LESS 10% DISCOUNT		-420.90	-222.30
			3,788.10	2,000.70



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
SPECIAL NETT ITEMS				
1	SET NUMBER PLATE (SN) (CONSISTENT)	REAR BENT	38.00	10.00
2	FORK OILS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN) (CONSISTENT)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN) (CONSISTENT)	NOT NECESSARY	95.00	-
1	SET STICKER (SN) (CONSISTENT)	NECESSARY	120.00	60.00
			339.00	70.00
LABOUR				
	TO PROVIDE TOWING SERVICE (LOD).		30.00	30.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.	NOT NECESSARY	350.00	-
1	TO PROVIDE LABOUR.		480.00	220.00
			940.00	250.00
GRAND TOTAL			5,067.10	2,320.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,800.00

Report Ref No. CC4/ASM22000660/Uga3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.