



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBQ 7996S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FAIRING ASSY	BROKEN	1,080.00	850.00
2	FRONT FORK TUBE ASSY	SERVICEABLE	640.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	220.00	-
1	FRONT RIM	TO REPAIR SEE LABOUR	340.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	45.00	-
1	FRONT RIM BEARING	NOT NECESSARY	70.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	180.00	-
1	FRONT SIGNALS	CRACKED	216.00	150.00
1	HEADLAMP (LED)	CRACKED	980.00	980.00
1	HEADLAMP COVER	BROKEN	198.00	128.00
1	HANDLE BAR	BENT	180.00	180.00
1	HANDLE BAR BALANCER	CUT	98.00	35.00
1	SET HAND GRID	NOT NECESSARY	58.00	-
1	MIRROR N/S	CUT	110.00	90.00
1	BRAKE LEVER N/S	CUT	130.00	98.00
1	WINDSCREEN	CRACKED	165.00	165.00
1	FOOT STEP PANEL	CUT	178.00	178.00
1	FOOT STEP LOWER PANEL	CUT	180.00	180.00
1	REAR FOOTREST	NOT NECESSARY	78.00	-
1	SIDE STAND	TO REPAIR SEE LABOUR	95.00	-
1	MAIN STAND	CUT	175.00	175.00
1	AIR FILTER ASSY	CUT	328.00	225.00
1	BELT HOUSING	CRACKED	428.00	320.00
1	RADIATOR	NOT NECESSARY	398.00	-
	LESS 10% DISCOUNT		-657.00	-375.40
			5,913.00	3,378.60
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET NUMBER PLATE (SN)	FRONT NECESSARY	38.00	10.00

Report Ref No. CS/AIS22000664/Uqf3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	E.R.P. IU (SN)	NOT NECESSARY	180.00	-
1	HELMET (SN)	TO REPAIR SEE LABOUR	180.00	-
1	REAR BOX (SN)	SERVICEABLE	580.00	-
1	REAR BOX BRACKET (SN)	CUT	180.00	180.00
1	STICKER (SN)	NECESSARY	120.00	60.00
			1,278.00	250.00
	<b>LABOUR</b>			
	TO PROVIDE TOWING SERVICE (LOD).		40.00	40.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.	NOT NECESSARY	480.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF FRONT RIM, SIDE STAND AND HELMET.		480.00	380.00
			1,080.00	420.00
<b>GRAND TOTAL</b>			<b>8,271.00</b>	<b>4,048.60</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,200.00</b>

Report Ref No. CS/AIS22000664/Uqf3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.