

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000667/EQY3N2**Date:** 05/04/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00054092100

Claimant Vehicle No : SLT3776C**Insured Vehicle No :** GBH3894B

Date of Loss: 15/01/2022

Nature of Claim: TP

Claim No: SNM22D200414/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLT3776C**

Make & Model: LAND ROVER DISCOVERY, 3.0 D TSS SR (A)

Engine No: 1171253306DT

Reg. Date: 26/10/2017 (Man. Year: 2017)

Chassis No: SALRA2AK8HA038154

Colour: Green

Odometer: 71210 km

Engine Capacity: 2993 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/55 R20

Rear Tyre Size: 255/55 R20

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,132.57	14,929.11	7,203.46	32.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,201.00	6,601.00	4,600.00	41.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	33,333.57	21,530.11	11,803.46	35.41
+ GST 7.00/7.00% (\$\$)	2,333.35	1,507.11	826.24	35.41
Nett Amount (\$\$)	35,666.92	23,037.22	12,629.70	35.41

INSPECTION

Date of Assignment: 18/01/2022

Date Inspected: 24/01/2022

Inspected At:

Wearnes automotive Pte Ltd (HQ)
45 LENG KEE ROAD
Singapore 159103

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Apr 2022)

Parts: M1-SUV LAND ROVER DISCOVERY 3.0 D TSS SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLT3776C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER-REAR	Broken	2,171.20 FS	*1,954.08 FS
2	1		*COVER-TOWING HOOK	Cut	432.30 FS	*389.07 FS
3	1		*LH BRACKET-BUMPER	Not Necessary	52.60 FS	*- FS
4	1		*RH BRACKET-BUMPER	Not Necessary	52.60 FS	*- FS
5	1		*INSERT-BUMPER LH	Not Necessary	140.10 FS	*- FS
6	1		*INSERT-BUMPER RH	Not Necessary	140.10 FS	*- FS
7	1		*REINFORCEMENT-REAR	Dented	650.70 FS	*612.27 FS
8	1		*LH REINFORCEMENT-B	Not Necessary	383.80 FS	*- FS
9	1		*RH REINFORCEMENT-B	Not Necessary	383.80 FS	*- FS
10	1		*LH BRACKET-BUMPER	Not Necessary	99.40 FS	*- FS
11	1		*RH BRACKET-BUMPER	Not Necessary	99.40 FS	*- FS
12	1		*BRACKET-BUMPER MOU	Not Necessary	94.90 FS	*- FS
13	1		*WIRING-BUMPER REAR	Not Necessary	299.50 FS	*- FS
14	1		*LAMP-REAR,STOP AN	Not Necessary	1,303.00 FS	*- FS
15	1		*LAMP-REAR,STOP AN	Not Necessary	1,303.00 FS	*- FS
16	1		*LAMP-DAYTIME RUNNI	Broken	1,085.80 FS	*977.22 FS
17	1		*LAMP-DAYTIME RUNNI	Broken	1,085.80 FS	*977.22 FS
18	1		*TAILGATE-COMPLETE	Broken	2,808.40 FS	*2,527.56 FS
19	1		*SEAL-TAILGATE	Necessary	260.10 FS	*234.09 FS
20	1		*GLASS-TAILGATE WIN	Necessary	2,711.50 FS	*2,440.35 FS
21	1		**D* PRIMER GLASS & P	Necessary	43.30 FS	*38.97 FS
22	2		*ADHESIVE AND SEALER	Necessary	319.00 FS	*287.10 FS
23	1		*NAME PLATE-PLASTIC	Necessary	202.20 FS	*181.98 FS
24	1		*NAME PLATE-PLASTIC	Necessary	185.00 FS	*166.50 FS
25	1		*NAME PLATE	Necessary	98.60 FS	*88.74 FS
26	1		*NAME PLATE TD6	Necessary	159.10 FS	*143.19 FS
27	4		*SENSOR-PARKING AID	Not Necessary	1,104.40 FS	*- FS
28	2		*SENSOR-PARKING AID	Not Necessary	552.20 FS	*- FS
29	1		*LAMP-FOG-LH REAR	Broken	586.35 FS	*586.35 FS
30	1		*BRACKET-BUMPER MOU	Broken	85.41 FS	*85.41 FS
31	1		*MOULDING-TAILGATE	Cut	1,255.32 FS	*1,255.32 FS
32	1		*BLIND-TAILGATE	Broken	734.40 FS	*734.40 FS
33	1		*INSERT-BUMPER RH	Broken	132.39 FS	*132.39 FS
34	1		*INSERT-BUMPER LH	Broken	131.85 FS	*131.85 FS
35	1		*PANEL-TAILGATE TRI	Broken	184.68 FS	*184.68 FS
36	1		*PANEL-TAILGATE TRI	Broken	184.68 FS	*184.68 FS
37	1		*LAMP-FOG-REAR	Broken	615.69 FS	*615.69 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **22,132.57** **14,929.11**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER,REAR BOOTLID,BOOTLAMP,TAILLAMP,BUMPER TOW COVER,BUMPER BEAM REAR,REPAIR REAR FENDER LH	New	5,200.00	2,600.00
2	TO SPRAYPAINT ON REAR BUMPER,BOOTLID,REAR FENDER LH ETC	New	4,000.00	2,000.00
3	TO REPLACE REAR WINDSCREEN	New	600.00	600.00
4	TO INSTALL REAR WINDSCREEN FIL	New	280.00	280.00
5	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	621.00	621.00
6	TO REMOVE,REFIT & TRANSFER REAR TAILGATE COMPONENTS	New	500.00	500.00
Gross Labour Cost (\$)			11,201.00	6,601.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >