



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDS 5515B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR FENDER RH	BENT	1,800.00	1,800.00
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	380.00	160.00
1	REAR BUMPER	BUCKLED / DENTED	1,600.00	1,600.00
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	120.00	-
1	REAR BUMPER REVERSE SENSOR	DENTED	290.00	290.00
1	TAILLAMP	CUT	780.00	780.00
1	REAR FUSE CASE	SERVICEABLE	680.00	-
	LESS 10% DISCOUNT		-	-463.00
			5,650.00	4,167.00
	<u>SPECIAL NETT ITEMS</u>			
1	SEALANT (SN)	NECESSARY	180.00	40.00
			180.00	40.00
	<u>LABOUR</u>			
	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS.		180.00	120.00
	TO REMOVE AND INSTALL REAR BOOT GARNISH PANEL, SPARE TANK BOARD, COVER ETC TO FACILATE REPAIR.		280.00	100.00
	TO REMOVE AND REFIT, WELD AND CUT REAR FENDER, REAR END PANEL, REAR BUMPER, TAILLAMP, RETAINER, ETC.		1,400.00	700.00
	TO APPLY PUTTY, PRIMER AND RESPRAY PAINT ON REAR FENDER, END PANEL, REAR BUMPER AND BLEND BONNET AND REAR DOOR (SPECAIL PEARL).		1,200.00	500.00
	TO CHECK REAR WIRING, SYSTEM, FUSE CASE WIRING ETC.		380.00	20.00
			3,440.00	1,440.00
	GRAND TOTAL		9,270.00	5,647.00



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,300.00
---	--	--	-----------------

Report Ref No. CS/FCI22000668/Kqf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.