

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22000669/AVCE2

**Date:** 18/05/2022

### REFERENCE

Insured/Claimant: SHI YAN Policy No: 1900260812-01  
Date of Loss: 23/11/2021 Nature of Claim: OD Claim No: 4789692453SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR2559T**  
Make & Model: AUDI A1 SPORTBACK, 1.0 Advanced TFSI S-tronic (A) Engine No: DKJ047166  
Reg. Date: 26/12/2019 (Man. Year: 2019) Chassis No: WAUZZZGB5LR011999  
Colour: Green Odometer: 10681 km  
Engine Capacity: 999 cc  
Market Value/New Car Price: S\$103,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/55 R16 Rear Tyre Size: 195/55 R16  
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,700.00	3,598.80	7,101.20	66.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,002.00	2,042.00	2,960.00	59.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,702.00</b>	<b>5,640.80</b>	<b>10,061.20</b>	<b>64.08</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	15,102.00	5,040.80	10,061.20	66.62
<b>+ GST 7.00/7.00% (S\$)</b>	1,057.14	352.86	704.28	66.62
<b>Nett Amount (S\$)</b>	<b>16,159.14</b>	<b>5,393.66</b>	<b>10,765.48</b>	<b>66.62</b>

### INSPECTION

Date of Assignment: 19/01/2022

Date Inspected: 18/01/2022 Inspected At:

Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,634.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	137.00 FS	*- FS
3	1		*FRONT SPOILER - LH	Not Necessary	100.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cut	211.00 FS	*168.40 FS
5	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	196.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	167.00 FS	*- FS
7	1		*RADIATOR GRILLE	Not Necessary	926.00 FS	*- FS
8	1		*RADIATOR CLOSING ELEMENT	Not Necessary	161.00 FS	*- FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	118.00 FS	*- FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	723.00 FS	*- FS
11	1		*FRONT BUMPER GUIDE PROFILE - LH	Not Necessary	36.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	107.00 FS	*- FS
13	1		*FRONT BUMPER TOP COVER	Not Necessary	123.00 FS	*- FS
14	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
15	1		*AIRCON STICKER	Not Necessary	19.00 FS	*- FS
16	1		*FRONT FENDER - LH	Repair	978.00 FS	*- FS
17	1		*FRONT FENDER BRACE - LH	Not Necessary	54.00 FS	*- FS
18	1		*FRONT FENDER BRACKET - LH	Not Necessary	37.00 FS	*- FS
19	1		*FRONT FENDER BRACKET - LH CENTER	Not Necessary	14.00 FS	*- FS
20	1		*FRONT FENDER BRACKET - LH END	Not Necessary	58.00 FS	*- FS
21	1		*FRONT WHEEL HOUSING LINER (NPA)	Not Necessary	0.00 FS	*- FS
22	1		*HEADLIGHT - LH	Cut	4,288.00 FS	*3,430.40 FS
23	1		*LIFT CYLINDER - LH	Not Necessary	142.00 FS	*- FS
24	1		*LIFT CYLINDER HOSE	Not Necessary	59.00 FS	*- FS
25	1		*RADIATOR AIR GUIDE - LH	Not Necessary	38.00 FS	*- FS
26	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
27	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)      10,700.00      3,598.80**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			<b>Gross Labour Cost (\$\$)</b>	<b>5,002.00</b>
				<b>2,042.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >