

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22000671/ATCN2**Date:** 24/06/2022**REFERENCE**

Insured/Claimant:	NEO CHOON HONG	Policy No:	1900249328-02	
Date of Loss:	12/01/2022	Nature of Claim:	OD	Claim No: 0572357320SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFV1331B		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK086841
Reg. Date:	21/11/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF41KA109458
Colour:	White	Odometer:	11367 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$138,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,688.40	9,016.96	7,671.44	45.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,122.00	3,022.00	2,100.00	41.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,810.40	12,038.96	9,771.44	44.80
- Excess (\$\$)	400.00	400.00	0.00	0.00
(\$\$)	21,410.40	11,638.96	9,771.44	45.64
+ GST 7.00/7.00% (\$\$)	1,498.73	814.73	684.00	45.64
Nett Amount (\$\$)	22,909.13	12,453.69	10,455.44	45.64

INSPECTION

Date of Assignment:	19/01/2022	
Date Inspected:	18/01/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,913.00 FS	*1,530.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	612.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTER	Not Necessary	219.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Cracked	254.00 FS	*203.20 FS
6	1		*FRONT BUMPER AIR GUIDE-LH	Not Necessary	72.00 FS	*- FS
7	1		*RADIATOR GRILLE	Not Necessary	1,478.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	151.00 FS	*- FS
9	1		*FRONT BUMPER GUIDE SECTION-LH	Cracked	41.00 FS	*32.24 FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	139.00 FS	*- FS
12	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
13	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
14	1		*AIR COND STICKER	Not Necessary	9.00 FS	*- FS
15	1		*FRONT BUMPER LOCK CARRIER BRACKET	Cracked	154.00 FS	*122.80 FS
16	2		*FRONT BUMPER SUPPORT-LH/RH	Not Necessary	64.00 FS	*- FS
17	4		*POP RIVET	Not Necessary	4.00 FS	*- FS
18	2		*FRONT PARKING AID SENSOR-INNER/OUTER	Not Necessary	64.00 FS	*- FS
19	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
20	1		*HORN-LH	Not Necessary	134.00 FS	*- FS
21	1		*HORN BRACKET-LH	Not Necessary	33.00 FS	*- FS
22	1		*FRONT FENDER-LH	Dented	861.00 FS	*688.80 FS
23	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	211.00 FS	*- FS
24	1		*FRONT FENDER CLOSING ELEMENT-LH	Damaged	81.00 FS	*64.24 FS
25	1		*FRONT FENDER BRACKET-LH	Not Necessary	41.00 FS	*- FS
26	1		*FRONT FENDER BRACE-LH	Bent	132.00 FS	*105.20 FS
27	10		*POP RIVET	Necessary	30.40 FS	*30.40 FS
28	1		*FRONT WHEEL HOUSING LINER-LH	Not Necessary	260.00 FS	*- FS
29	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	0.00 FS	*- FS
30	1		*FRONT WHEEL SPOILER-LH	Necessary	82.00 FS	*65.12 FS
31	1		*FRONT WHEEL SPOILER LOWER-LH	Not Necessary	39.00 FS	*- FS
32	1		*HEADLIGHT-LH	Cut	7,693.00 FS	*6,154.40 FS
33	1		*LIFT CYLINDER BRACKET	Not Necessary	7.00 FS	*- FS
34	1		*LIFT CYLINDER-LH	Not Necessary	231.00 FS	*- FS
35	1		*LIFT CYLINDER CORRUCATED PIPE	Not Necessary	107.00 FS	*- FS
36	2		*RADIATOR AIR GUIDE INNER/OUTER-LH	Not Necessary	46.00 FS	*- FS
37	1		*RADIATOR AIR GUIDE UPPER-LH	Not Necessary	19.00 FS	*- FS
38	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
39	1		*SUNDRIES	Necessary	300.00 FS	*20.16 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 16,688.40 9,016.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,122.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >