6/24/22, 1:26 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CC3/AIG22000673/AQCN2

AIG Building, 78 Shenton Way, #09-16

Singapore 079120 Date: 24/06/2022

REFERENCE

Insured/Claimant: GU YANYUN Policy No: 7210027649

Date of Loss: 28/12/2021 Nature of Claim: OD Claim No: 7513380813SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGE6176C

Make & Model: AUDI A3, 999cc SEDAN TFSI S TRONIC (LED) (A) Engine No: CHZC34154

Reg. Date: 22/03/2021 (Man. Year: 2019) Chassis No: WAUZZZ8V5LA000654

Colour: Grey Odometer: 7528 km

Engine Capacity: 999 cc
Market Value/New Car Price: \$\$120,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		7,816.00	5,352.40	2,463.60	31.52
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,992.00	2,852.00	2,140.00	42.87
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	12,808.00	8,204.40	4,603.60	35.94
	- Excess (S\$)	600.00	600.00	0.00	0.00
	(S\$)	12,208.00	7,604.40	4,603.60	37.71
	+ GST 7.00/7.00% (S\$)	854.56	532.31	322.25	37.71
	Nett Amount (S\$)	13,062.56	8,136.71	4,925.85	37.71

INSPECTION

Date of Assignment: 19/01/2022

Date Inspected: Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR DOOR-RH	Dented	3,039.00 FS	*2,431.20 FS
2	1	*REAR DOOR OUTER SEAL-RH	Necessary	161.00 FS	*128.40 FS
3	1	*BONDING AGENT	Not Necessary	49.00 FS	*- FS
4	1	*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
5	1	*APPLICATOR	Not Necessary	8.00 FS	*- FS
6	1	*REAR DOOR ATTACHMENT PARTS	Not Necessary	129.00 FS	*- FS
7	1	*REAR DOOR CATCH-RH	Not Necessary	94.00 FS	*- FS
8	1	*FRONT DOOR-RH	Dented	3,265.00 FS	*2,612.00 FS
9	1	*FRONT DOOR OUTER SEAL-RH	Necessary	179.00 FS	*142.80 FS
10	1	*BONDING AGENT	Not Necessary	51.00 FS	*- FS
11	1	*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
12	1	*APPLICATOR	Not Necessary	8.00 FS	*- FS
13	1	*FRONT DOOR ATTACHMENT PARTS	Not Necessary	252.00 FS	*- FS
14	1	*FRONT DOOR CATCH-RH	Not Necessary	105.00 FS	*- FS
15	1	*TYRE PRESSURE DATA PLATE	Necessary	34.00 FS	*26.96 FS
16	1	*SUNDRIES	Necessary	300.00 FS	*11.04 FS
F=Fr	anchise part. S=Spc	Nett.	Total Parts (S\$)	7,816.00	5,352.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	700.00	560.00
2	TO DISMANTLE AND RENEW RHS FRONT DOOR AND RHS REAR DOOR.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
3	TO RESPRAY RHS FRONT DOOR AND RHS REAR DOOR	New	2,000.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labo	ur Cost (S\$)	4,992.00	2,852.00
	Report was unsubmitted during thi	s print-out.		

< END OF ESTIMATES >