

NOT AUTHORIZED  
11 Sep @ 1130h

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB9888R**

**AAD2201-089**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

18 JAN 2022

**SHB9888R**

VF1ABL15AUC282182

RENAULT

LATITUDE

15/01/2022

**AIG**

22/03/2016

**PART**

- 1 TAILLAMP RH
- 1 BUMPER COVER REAR
- 1 BUMPER LOWER REAR
- 1 BUMPER BRACKET CTR REAR
- 1 BUMPER BRACKET SIDE RH REAR
- 1 BUMPER RETAINER RH REAR
- 1 BUMPER BEAM REAR
- 1 OUTER PANEL REAR
- 1 OUTER PANEL REAR (End Panel) TRIM
- 1 BUMPER REFLECTOR RH
- 1 FENDER PANEL REAR RH

**LIST**

|    |    |          |   |
|----|----|----------|---|
| \$ | PL | 401.40   | X |
| \$ | BL | 561.70   | ✓ |
| \$ | PL | 411.90   | X |
| \$ | PL | 98.10    | X |
| \$ | PL | 82.10    | X |
| \$ | PL | 59.80    | X |
| \$ | PL | 547.80   | X |
| \$ | PL | 745.80   | X |
| \$ | PL | 404.56   | X |
| \$ | PL | 16.60    | X |
| \$ | PL | 1,933.20 | X |

**TOTAL \$ 5,262.96**

**10% \$ 526.30**

**\$ 4,736.66**

**Special Nett**

- 1 REVERSE SENSOR
- 1 FENDER CLIP
- 1 REAR BUMPER CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

|    |    |        |   |
|----|----|--------|---|
| \$ | PL | 700.00 | X |
| \$ | PL | 65.00  | X |
| \$ | PL | 65.00  | ✓ |
| \$ | PL | 150.00 | X |
| \$ | PL | 200.00 | X |
| \$ | PL | 130.00 | X |

**TOTAL \$ 1,310.00**

**TOTAL PARTS \$ 6,046.66**

**LABOUR**

To transfer of door fittings, attachment and perform water seepage test.

\$ PL 300.00 X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB9888R****AAD2201-089**

|                                                                                                                           |    |    |          |      |
|---------------------------------------------------------------------------------------------------------------------------|----|----|----------|------|
| To check steering geometry and computer wheel alignment                                                                   | \$ | nn | 220.00   | X    |
| To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.                                                    | \$ | 4  | 300.00   | X    |
| To remove and refit interior fittings, trimings, garnish, fittings and others, to enable repair.                          | \$ | 4  | 380.00   | X    |
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ |    | 1,400.00 | 4001 |
| To rust-proofing and apply undercoat of the affected areas.                                                               | \$ | nn | 240.00   | X    |
| Putty and spray painting of the affected portion.                                                                         | \$ |    | 1,400.00 | 4401 |
| To transfer of tire, rim and on wheel balancing.                                                                          | \$ | nn | 170.00   | X    |
| To Check Electrical Lighting Concerned.                                                                                   | \$ |    | 170.00   | 101  |

**TOTAL \$ 4,580.00****Over All Total \$ 10,626.66****LUMP SUM (REPAIR DAY)****20 DAYS****2 days****LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

Signature:

Date: