

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS22000676/ETF3E2**Date:** 04/04/2022REFERENCE

Handling Insurer: ECICS Limited

Policy No:

**Claimant Vehicle No :** SLN4222J**Insured Vehicle No :** SGW8273Y

Date of Loss: 17/01/2022

Nature of Claim: TP

Claim No: DMPC2200029H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLN4222J**

Make &amp; Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZRS041023

Reg. Date: 03/05/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU503556477

Colour: White

Odometer: 370408 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,228.25	1,793.25	4,435.00	71.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,500.00	2,440.00	4,060.00	62.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>12,728.25</b>	<b>4,233.25</b>	<b>8,495.00</b>	<b>66.74</b>
<b>+ GST 7.00/7.00% (S\$)</b>	890.98	296.33	594.65	66.74
<b>Nett Amount (S\$)</b>	<b>13,619.23</b>	<b>4,529.58</b>	<b>9,089.65</b>	<b>66.74</b>

INSPECTION

Date of Assignment: 19/01/2022

Date Inspected: 28/02/2022

Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)

2 Pandan Crescent

Singapore 128462

Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 04 Apr 2022)

**Parts:** 144      TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLN4222J)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*COVER, RR BUMPER	Broken	469.50 FS	*469.50 FS
3	1		*RETAINER, RR BUMPER	Not Necessary	124.90 FS	*- FS
4	1		*RETAINER, RR BUMPER	Not Necessary	123.60 FS	*- FS
5	1		*REINFORCEMENT	Dented	353.10 FS	*353.10 FS
6	1		*SEAL, RR BUMPER	Not Necessary	93.50 FS	*- FS
7	1		*SEAL, RR BUMPER	Not Necessary	93.50 FS	*- FS
8	1		*FILLER, RR BUMPER	Not Necessary	131.10 FS	*- FS
9	1		*FILLER, RR BUMPER	Not Necessary	131.10 FS	*- FS
10	1		*GUARD, RR BUMPER	Cut	611.30 FS	*611.30 FS
11	1		*PANEL SUB-ASSY, BODY	Not Necessary	689.70 FS	*- FS
12	1		*GARNISH SUB-ASSY	Not Necessary	984.40 FS	*- FS
13	1		*EMBLEM SUB-ASSY	Necessary	76.00 FS	*76.00 FS
14	1		*PLATE, LUGGAGE COMPT	Necessary	58.00 FS	*58.00 FS
15	1		*PLATE, LUGGAGE COMPT	Necessary	58.00 FS	*58.00 FS
16	1		*LENS & BODY, RR	Not Necessary	479.30 FS	*- FS
17	1		*LENS & BODY, RR	Not Necessary	469.90 FS	*- FS
18	1		*LENS & BODY, RR	Not Necessary	532.00 FS	*- FS
19	1		*LENS & BODY, RR	Not Necessary	532.00 FS	*- FS
20	1		*2PT R SENSOR WITH ANGLE 070 WH	Shorted	101.05 FS	*101.05 FS
21	1		*COVER, RR BUMPER	Crushed	16.30 FS	*16.30 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **6,228.25**      **1,793.25**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK WIRING & CONDUCT LEAK TEST	New	180.00	180.00
2	RESET ECU UPON COMPLETION OF REPAIR	New	180.00	180.00
3	DRILL HOLE & INSTALL REVERSE SENSOR	New	180.00	180.00
4	REPL ACC AFF AREA. STRAIGHTEN & PANEL BEAT ACC AFF AREA	New	3,600.00	720.00
5	RESPRAY ACC AFF AREA	New	2,360.00	1,180.00
<b>Gross Labour Cost (\$)</b>			<b>6,500.00</b>	<b>2,440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >