



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJC 212X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (N)	TO REPAIR SEE LABOUR	1,150.40	-
2	FRONT BUMPER SIDE RETAINER @\$125.40 (N)	NOT NECESSARY	250.80	-
1	SET FRONT BUMPER CLIP (N)	NOT NECESSARY	50.00	-
1	RADIATOR GRILLE BASE (N)	SERVICEABLE	799.60	-
1	RADIATOR GRILLE CHROME MOULDING (N)	CRACKED	355.40	298.32
1	RADIATOR GRILLE LOGO (N)	NOT NECESSARY	495.80	-
1	FRONT NUMBER PLATE BASE (N)	DEFORMED	175.00	118.00
	LESS 10% DISCOUNT		-327.70	-41.63
			2,949.30	374.69
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	BENT	45.00	40.00
			45.00	40.00
<u>LABOUR</u>				
	TO CHECK LIGHT SYSTEM AND WIRING.		50.00	20.00
	TO RE-CALIBRATE ADAS.	NOT NECESSARY	350.00	-
	LABOUR/PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		400.00	180.00
	SPRAY PAINTING BUMPER.		500.00	200.00
			1,300.00	400.00
GRAND TOTAL			4,294.30	814.69
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				650.00

Report Ref No. CS/SMO22000677/Utf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.