

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG22000678/RGA3Q2**Date:** 29/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900022916
<b>Claimant Vehicle No :</b>	SHB388B	<b>Insured Vehicle No :</b>	SKK1208Z
Date of Loss:	17/01/2022	Nature of Claim:	TP
		Claim No:	7756113909SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB388B</b>		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZR1449314
Reg. Date:	24/10/2014 (Man. Year: 2014)	Chassis No:	JTDKN36U605752469
Colour:	Maroon	Odometer:	559532 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,831.70	0.00	2,831.70	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	885.00	400.00	485.00	54.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>3,716.70</b>	<b>400.00</b>	<b>3,316.70</b>	<b>89.24</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b>		150.00		
<b>+ Car Rental (3.0 x S\$66.00/day) (S\$)</b>		198.00		
<b>+ Doc/Search Fee (S\$)</b>		7.00		
<b>Nett Liability (S\$)</b>		<b>755.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>750.00</b>		

INSPECTION

Date of Assignment:	18/01/2022	
Date Inspected:	18/01/2022 Inspected At:	Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

**Adjuster:** MOHD RASUL**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR RR/RH	Repair	954.50 F	*- F
2	1		*DOOR LOCK RR/RH	Not Necessary	709.30 F	*- F
3	1		*DOOR REGULATOR MOTOR FRONT RH	Not Necessary	947.80 F	*- F
4	1		*CHECK ASSY ,RR DOOR	Not Necessary	150.30 F	*- F
5	1		*DOOR OUTER HANDLE RR/RH	Not Necessary	69.80 F	*- F
F=Franchise part.						
Total Parts (\$\$)					2,831.70	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODY WORK	New	507.00	200.00
2	SPRAY PAINT	New	378.00	200.00
<b>Gross Labour Cost (S\$)</b>			<b>885.00</b>	<b>400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >