

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122000682/AVF3N2**Date:** 25/05/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SMN1968Z **Insured Vehicle No :** GBC205L

Date of Loss: 18/01/2022 Nature of Claim: TP Claim No: CDMCG22000122

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN1968Z**

Make & Model: TOYOTA HARRIER, 2.0 (A) Engine No: 8ARZ158763

Reg. Date: 30/08/2019 (Man. Year: 2019) Chassis No: JTEZB3GH90J004519

Colour: White Odometer: 38905 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,970.54	8,238.79	11,731.75	58.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,630.00	2,520.00	3,110.00	55.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,600.54	10,758.79	14,841.75	57.97
Approved Total (Overridden) (S\$)		8,600.00		
Nett Amount (S\$)	25,600.54	8,600.00	17,000.54	66.41

INSPECTION

Date of Assignment: 19/01/2022

Date Inspected: 19/01/2022 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki
Bukit
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 May 2022)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN1968Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,378.60 FL	*1,850.00 FL
2	2		*TAILGATE HINGE	Not Necessary	178.60 FL	*- FL
3	2		*TAIL GATE LAMP	Not Necessary	988.80 FL	*- FL
4	1		*TAIL GATE APRON GARNISH	Not Necessary	1,120.60 FL	*- FL
5	1		*TAILGATE LOGO	Necessary	85.00 FL	*85.00 FL
6	1		*TAILGATE LOGO BASE GARNISH	Not Necessary	84.50 FL	*- FL
7	1		*TAILGATE EMBLEM HARRIER	Necessary	75.00 FL	*75.00 FL
8	1		*TAILGATE EMBLEM TURBO	Necessary	68.00 FL	*68.00 FL
9	1		*TAILGATE INNER LOCK	Damaged	954.40 FL	*554.00 FL
10	1		*TAILGATE WEATHER STRIP	Cut	353.40 FL	*353.40 FL
11	4		*TAILGATE STOPPER	Not Necessary	102.80 FL	*- FL
12	1		*TAILGATE INNER TRIM (LOWER)	Cracked	1,075.00 FL	*731.00 FL
13	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	277.20 FL	*- FL
14	2		*TAILGATE DAMPER	Not Necessary	422.80 FL	*- FL
15	1		*TAILGATE DETECTOR	Damaged	489.70 FL	*255.00 FL
16	1		*REAR BUMPER (UPPER)	Deformed	1,381.75 FL	*1,381.75 FL
17	1		*REAR BUMPER (LOWER)	Deformed	744.50 FL	*744.50 FL
18	2		*REAR BUMPER CORNER RETAINER	Not Necessary	190.00 FL	*- FL
19	2		*REAR BUMPER SIDE RETAINER	Necessary	110.00 FL	*110.00 FL
20	1		*REAR BUMPER SPONGE	Cracked	359.20 FL	*359.20 FL
21	1		*REAR BUMPER REFLECTOR	N/s Cracked	178.60 FL	*89.30 FL
22	2		*TAIL LAMP	Not Necessary	1,379.20 FL	*- FL
23	1		*REAR END PANEL	Dented	795.30 FL	*795.30 FL
24	1		*REAR END PANEL TOP GARNISH	Deformed	395.40 FL	*395.40 FL
25	1		*REAR END PANEL DAMPER	Bent	1,343.70 FL	*1,007.00 FL
26	2		*REAR END PANEL DAMPER BRACKET	Not Necessary	544.20 FL	*- FL
27	2		*REAR TOOLS COMPARTMENT (INNER)	Not Necessary	1,394.80 FL	*- FL
28	2		*REAR TOOLS COMPARTMENT COVER	Deformed (1 Pc only)	1,517.20 FL	*685.00 FL
29	1		*REAR SIDE TOOLS COMPARTMENT GARNISH	N/S Deformed	962.40 FL	*481.20 FL
30	1		*REAR TOOLS COMPARTMENT BOARD(SIDE)	Not Necessary	379.20 FL	*- FL
31	1		*REAR EXHAUST GASKET	Not Necessary	28.00 FL	*- FL
32	1		*REAR EXHAUST BOX	Not Necessary	896.60 FL	*- FL
33	1		*REAR EXHAUST INSULATOR	Not Necessary	238.20 FL	*- FL
34	4		*REAR EXHAUST MOUNTING	Not Necessary	156.40 FL	*- FL
35	1		*TOOLS TRAY	Deformed	685.00 FL	*685.00 FL
36	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
37	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
38	1		*REAR BUMPER FOOT ACTIVATED STICKER	Necessary	120.00 FS	*20.00 FS
39	1		*SET TAILGATE INNER TRIM (LOWER) CLIP	Necessary	50.00 FS	*30.00 FS
40	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
41	1		*TAILGATE WINDSCREEN INNER SHIELD	Not Necessary	60.00 FS	*- FS
42	1		*TAILGATE AUTO SYSTEM (SPECIAL TYPE)	Not Necessary	1,800.00 FS	*- FS
43	1		*SET TAILLAMP CLIP	Not Necessary	60.00 FS	*- FS
44	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
45	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
46	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS

Report was unsubmitted during this print-out.

5/25/22, 10:57 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
48	1		*REVERSE CAMERA	Not Necessary	550.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					25,554.05	10,915.05
- List Item Discount on L Items 25.00/25.00% (\$\$)					5,583.51	2,676.26
Total Parts (\$\$)					19,970.54	8,238.79
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,800.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	1,000.00
3	TUFF COAT	New	250.00	60.00
4	WIRING AND BULB CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	80.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
8	REMOVE AND REFIX REAR CAR VIDEO RECORDER	New	80.00	50.00
9	CONDUCT WATER LEAKAGE TEST	New	180.00	0.00
10	TRANFER TAILGATE MECHANISM	New	80.00	80.00
11	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
12	RESET TAILGATE SYSTEM	New	250.00	0.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMNET /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	380.00	0.00
Gross Labour Cost (\$\$)			5,630.00	2,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >