ACE AUTOLUTION PTE LTD

13,KAKI BUKIT ROAD 4,BARTLEY BIZ CENTRE #03-29,SINGAPORE 417807.

COMPANY REG. NO: 201403869W EMAIL: admin@aceauto.com.sg

TEL: 6844 1184 FAX: 6702 4202

NAME

HUANG YUQING

DATE :

16/11/2021

PROFORMA INVOICE:

ACE-104-2021

JOB NO.

ADDRESS :

660D JURONG WEST STREET 64 #03-350

SINGAPORE 644660

VEHICLE NO.

SGL 3060 K

MAKE & MODEL : TOYOTA

RUSH

ITEM	DESCRIPTION	QTY RATE	AMOUNT
1	COST OF REPAIR		\$ 4,196.23
		TOTAL	\$4,196.23

IMPORTANT

Please remit payment within 7 days from the due date
An interest of 1.5% per month will be levied on all overdue amounts
All cheques must be made payable to ACE AUTOLUTION PTE LTD
(WE ARE NOT GST REGISTERED)

This a computer generated document. No signature is required.

Motor Vehicle Appraiser and Insurance Loss Adjuster No. 10 Kaki Bukit Ave 4 #06-75 Premier @ Kaki Bukit Singaore 415874 Handphone No.: +65 9146 1186 Email: united.appraisal@live.com.sg Business Registration Nos.: 200817301N

INVOICE

To: Huang Yuqing

Date

: 29 Oct 2021

c/o : Ace Autolution Pte Ltd

13 Kaki Bukit Rd 4

Invoice No. : 8093984

#03-29 Bartley Biz Centre @ Kaki Bukit

Singapore 417807

DESCRIPTION	AMOUNT
Service rendered for appraisal / inspection report :	
Professional inspection fees	SGD 405.00
Photographs 18 pcs	
Transport fees	
Re-inspection fees (work in progress, post repair inspection)	
Total	SGD 405.00
Singapore dollar: FOUR HUNDRED FIVE ONLY.	
Registration no. : SGL3060K	
Make/Model : Toyota Rush 1.5 A	
Our reference : UAM21.10.22-PT-STP-AAL-SGL3060K	
All payments made payee to:-	
" UNITED APPRAISAL & MANAGEMENT PTE LTD"	





Our ref.: UAM21.10.22-PT-STP-AAL-SGL3060K

Date : 29 Oct 2021

Huang Yuqing

Encls.:

WITHOUT PREJUDICE
Dear Sir,
Re: Third Party Claim For Vehicle Registration No. SGL3060K
We refer to your instruction to appraise the above-mentioned vehicle on 16 June 2021
A static inspection was carried out and our report is enclosed for your perusal. The estimated cost of repair submitted by Messrs. Ace Autolution Pte Ltd for SGD 5,623.30 as per our attached schedule has been inspected thoroughly by us against the actual damages sustained on the above-mentioned vehicle and we recommend the replacement and rectification accordingly.
Our revised quotation for the repair is SGD 4,196.23. In our opinion, it to be excessive. Therefore, we recommend a contract lump-sum repair cost. This is more economical than to have the above-mentioned vehicle repaired on parts by/for parts basis. Invariably, the repairer has the prerogative/option for the recommended replacement parts to either be repaired or be replaced.
We have negotiated with the repairer and they have agreed to repair the above-mentioned vehicle for SGD 3,350.00 NETT. Which, in our opinion is fair and reasonable.
The repairer has agreed to undertake the repairs to your requirement at the recommended contract lump-sum. However, we have not given any instruction and authorisation to the repairer to proceed with the repairs.
Under normal circumstances, the entire repair of the damaged vehicle should be completed within a reasonable period of days.
We are reverting the matter to you for a decision, and enclosed is our vehicle inspection report, appraisement schedule and invoice for services rendered.
Please do not hesitate to contact us if you have any queries on this matter.
Yours faithfully. United Appraisa & Management Pte Ltd Ananda K. Biswas Marc Motor Vehicle Appraiser

The information contained in these document may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you received this document by error, please contact us immediately to arrange for its return.

VEHICLE INSPECTION REPORT

To: Huang Yuqing

Our ref.: UAM21.10.22-PT-STP-AAL-SGL3060K

Date : 29 Oct 2021

REFERENCE

Assign by	:	Huang Yuqing	Insured	:	To be advice
Assign on	:	16 Jun 2021	Policy no.	:	To be advice
Inspection on	:	16 Jun 2021	Claim no.	:	To be advice
Accident on	:	14 Jun 2021	Sum insured	:	To be advice
Workshop name	:	Ace Autolution Pte Ltd	Excess	:	Not applicable
Inspection at	:	13 Kaki Bukit Rd 4	3rd party Veh.	:	To be advice
		#03-29 Bartley Biz Centre @ Kaki Bukit	3rd party ins.	:	To be advice
		01			

Singapore 417807

PARTICULARS OF DAMAGED VEHICLE

Registration no.	:	SGL3060K	Odometer	:	246524 km
Make / Model	:	Toyota Rush 1.5 A	Chassis no.	:	J200E0006436
Regn. date	:	11 Sep 2006	Engine no.	:	3SZ1642539
Body colour	:	Black	Engine cap.	:	1495 cc

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

Steering	:	In order	Paintwork	:	Good
Footbrake	:	In order	Undercarriage	:	Serviceable
Handbrake	:	In order	Gen. condition	:	Good

TYRE CONDITION ON VEHICLE


		Make	Size	Tread depth	Type of road wheel
Front N/S	:	Tourador	215/65 R16	70%	Alloy
Front O/S	:	Tourador	215/65 R16	70%	Alloy
Rear N/S	:	Tourador	215/65 R16	70%	Alloy
Rear O/S	:	Tourador	215/65 R16	70%	Alloy

NOTE: The above percentages represent the estimated remaining life of tyre threads.

^{*} Denotes damaged component/s

POINT OF IMPACT

On the off side top in the direction from top to bottom due to fallen object.



SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT

The impact of the collision has damaged / affected the o/s front door, roof side panel, a-pillar and etc...

Please refer to Annex A (Appraisement Schedule) for a detailed account of the damages and photographs taken.

Note:

RECOMMENDATION

The estimate cost of repair submitted by Messrs Ace Autolution Pte Ltd as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. We have not authorised the repairs.

Our adjusted cost of repair is SGD 3,350.00 to carry out the repairs. Please refer to Annex A (Appraisement Schedule) for a detailed account of the cost estimates.

REMARKS

We have not authorised the repair. However, for information, under normal circumstances, the repair would takes approximately 5 (Five) working days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** the repair to the damaged vehicle and the survey was conducted strictly on a "**WITHOUT PREJUDICE**" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report, which includes evidence photographs.

Yours faithfully, United Appraisal & Management Pte Ltd

Ananda K. Biswas Marc Motor Vehicle Appraiser

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SGL3060K Our reference : UAM21.10.

: UAM21.10.22-PT-STP-AAL-SGL3060K

C/NI	O4	Description	Condition /	Estimate by	Adjusted
S/N	Qty	Description	Remarks	Wshop SGD	Amt SGD
		<u>LIST ITEMS</u>			
1	1	Front door o/s	Dented	1112.60	1112.60
2	1	Front door weatherstrip o/s	Necessary	225.70	225.70
3	1	Roof side moulding o/s	Necessary	245.40	245.40
4	1	Roof side panel o/s	Repair	568.70	568.70
5	1	Front a-pillar o/s	Repair	0.00	0.00
6	1	Front windscreen moulding	Necessary	115.90	115.90
		-		2268.30	2268.30
			Less 0% / 25%	0.00	567.08
				2268.30	1701.23
		SPECIAL NETT ITEMS			
1	1	Sundries	Necessary	50.00	30.00
2	1	Front door sealant o/s	Necessary	100.00	80.00
3	1 set	Roof side moulding clips	Necessary	45.00	45.00
4	1	Front windscreen primer and cleaner	Necessary	100.00	80.00
5	1	Front windscreen sealant	Necessary	100.00	80.00
6	1	Front windscreen inner seal	Necessary	80.00	60.00
			·	475.00	375.00
		TOTAL		2743.30	2076.23

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SGL3060K

Our reference

: UAM21.10.22-PT-STP-AAL-SGL3060K

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
		LABOUR & MISC CHARGES			
1		To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.	SGD 350.00/day	1050.00	700.00
2		To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.		80.00	60.00
3		To remove and refit o/s front door component to replace o/s front door, check and alignment.		100.00	80.00
4		To remove and refit roof insulator trims to facilitate repairs on roof top panel.		100.00	80.00
5		To remove and refit front windscreen to to facilitate repairs.		150.00	120.00
6		To apply undercoating on the accident repair and replaced panel for rust protection.		200.00	180.00
7		Supply spray paint material and necessary items to respray a-pillar, front door, roof top panel and other affected area / panel	SGD 300.00/pnl	1200.00	900.00
		TOTAL		2880.00	2120.00
		Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment)		5623.30	4196.23 846.23
		Adjustment Parts and Labour Cost of Repair	r		3350.00