

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000683/AYA3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700035803
Claimant Vehicle No :	SDZ8189C	Insured Vehicle No :	SBB138C
Date of Loss:	14/01/2022	Nature of Claim:	TP
		Claim No:	2559121112SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDZ8189C		
Make & Model:	VOLKSWAGEN TIGUAN R-LINE, 1.4 COMFORTLINE 280 TSI (A)	Engine No:	CZE423448
Reg. Date:	31/08/2017 (Man. Year: 2017)	Chassis No:	WVGZZZ5NZHW407439
Colour:	Blue	Odometer:	70233 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,893.29	3,088.73	1,804.56	36.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	700.00	700.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,293.29	3,788.73	2,504.56	39.80
+ GST 7.00/7.00% (\$\$)	440.53	265.21	175.32	39.80
Nett Amount (\$\$)	6,733.82	4,053.94	2,679.88	39.80
+ Car Rental (5.0 x S\$100.00/day) (\$\$)		500.00		
Nett Liability (\$\$)		4,553.94		

INSPECTION

Date of Assignment:	17/01/2022	
Date Inspected:	17/01/2022 Inspected At:	J-mart Motor Trading (HQ) BLK 5 DEFU LANE 10 #01-578 DEFU INDUSTRIAL PARK C Singapore 539186
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,500.71 FN	*1,500.71 FN
2	1		*REAR BUMPER LOWER SPOILER	Deformed	399.76 FN	*399.76 FN
3	1		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	869.00 FN	*434.50 FN
			(4 PCS)			
4	1		*REAR BUMPER REINFORCEMENT	Dented	600.79 FN	*600.79 FN
5	2		*REAR BUMPER RETAINER	Not Necessary	199.74 FN	*- FN
6	2		*REAR BUMPER REFLECTOR SHORT	Not Necessary	128.30 FN	*- FN
7	1		*REAR BUMPER REFLECTOR LONG	O/S Cut	261.54 FN	*130.77 FN
8	1		*REAR BUMPER TOW HOOK COVER	Deformed	75.60 FN	*75.60 FN
9	1		*REAR BUMPER CENTRE HOLDER	Cracked	289.79 FN	*289.79 FN
10	1		*END PANEL	Repair	1,111.76 FN	*- FN

F=Franchise part. N=NettItemDisc.

Sub Total (S\$)	5,436.99	3,431.92
- Nett Item Discount on N Items 10.00/10.00% (S\$)	543.70	343.19
Total Parts (S\$)	4,893.29	3,088.73

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	300.00
2	SPRAY PAINTING	New	800.00	400.00
Gross Labour Cost (S\$)			1,400.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >