

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000689/ETY3N2
Date: 21/02/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCNA00234652102

Claimant Vehicle No : SLP9243E **Insured Vehicle No :** SJT9837U

Date of Loss: 05/01/2022 Nature of Claim: TP Claim No: SNM22D200120/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP9243E**

Make & Model: NISSAN QASHQAI, 1.2 (A) Engine No: HRA2443087A

Reg. Date: 22/06/2017 (Man. Year: 2017) Chassis No: SJNFEAJ11UZ015673

Colour: Silver Odometer: 37580 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60R17 Rear Tyre Size: 215/60R17

Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,006.96	1,062.56	944.40	47.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,688.00	1,463.00	225.00	13.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,694.96	2,525.56	1,169.40	31.65
+ GST 7.00/7.00% (S\$)	258.65	176.79	81.86	31.65
Nett Amount (S\$)	3,953.61	2,702.35	1,251.26	31.65

INSPECTION

Date of Assignment: 18/02/2022

Date Inspected: 20/01/2022 Inspected At: Tan Chong Motor Sales (HQ)
913 Bukit Timah Road
Singapore 589622

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Feb 2022)
Parts: M1-SUV	NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP9243E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRACKET-BMPR LH	Not Necessary	38.90 FN	*- FN
2	1		*BRACKET-BMPR RH	Broken	38.90 FN	*38.90 FN
3	1		*STAY ASSY-RH	Not Necessary	141.00 FN	*- FN
4	1		*STAY ASSY-LH	Not Necessary	141.00 FN	*- FN
5	1		*REINF-BUMPER RR	Not Necessary	691.50 FN	*- FN
6	1		*ENERGY ABSORBER	Not Necessary	155.60 FN	*- FN
7	1		*FINISHER-REAR B	Cut	18.80 FN	*18.80 FN
8	10		*CLIP	Necessary	13.00 FN	*13.00 FN
9	2		*CANOE	Necessary	14.20 FN	*14.20 FN
10	3		*CLIP	Necessary	24.00 FN	*24.00 FN
11	2		*GROMMET	Necessary	5.40 FN	*5.40 FN
12	1		*FASCIA-RR BUMP	Dented	876.40 FN	*876.40 FN
13	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
14	1		*SENSOR-REVERSE	Shorted	250.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	2,438.70	1,260.70
- Nett Item Discount on N Items 20.00/20.00% (S\$)	431.74	198.14
Total Parts (S\$)	2,006.96	1,062.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	New	120.00	120.00
2	REPLACE REVERSE SENSOR,NECESSARY ADJUSTMENT & FUNCTION TEST	New	110.00	110.00
3	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	New	100.00	0.00
4	CHECK LIGHTING	New	48.00	48.00
5	REPAIR RR END PANEL & RENEW RR BUMPER	New	560.00	560.00
6	S/PAINT RR BUMPER (2 TONE) & RR END PANEL	New	750.00	625.00
Gross Labour Cost (\$\$)			1,688.00	1,463.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >