

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22000693/Eqy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 04/02/2022 SINGAPORE 068811 ATTN: TEO KITTY Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHA 783Z** SKN 2185H Veh. Inspected Policy No. VFX/P2419140 Coverage (\$) 0.00 Claim No. S2M03RCO Excess (\$) 0.00 **TEO KITTY Assign Date** 19/01/2022 Assign From Vehicle Particulars & Condition 2. B.M.W. X3 Make & Model 1997 C.C HIDDEN 2014 Engine No. Year of Reg. WBAWX320900B28693 SILVER Chassis No. Colour Odometer 173931 KM Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 245/50 R18 PIRELLI 5 mm PIRELLI L/H Front Tyre 245/50 R18 5 mm 245/50 R18 **PIRELLI** R/H Rear Tyre 5 mm PIRELLI L/H Rear Tyre 245/50 R18 5 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. 5. **General Information** 16/01/2022 19/01/2022 (04:06 PM) Inspect Date / Time Accident Date **GOLD AUTOWORKS PTE LTD** Survey held at 48 TOH GUAN ROAD EAST #01-119 ENTERPRISE HUB SINGAPORE 608586 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000

Report Ref No. CS3/ASM22000693/Eqy3e2

Estimate Days of Repair

Inspected By

5b.

CHEN TSUE YEE

Automotive Assessor

IEN ISUE TEE

ESTIMATED NORMAL PERIOD FOR REPAIR:

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

6 Working Days