

AUTO BULLOX PTE LTD

53 Ubi Avenue 1#01-25 Paya Ubi Industrial Park Singapore 408934
Tel: 6844 4290 Fax: 6841 6043 HP: 9769 9299 Email: autobullox@gmail.com
UEN:201919765N

To : Sampo Insurance Singapore Pte Ltd
Attn : Motor Claim Department

Xiao Chen

Owner : Nakano Singapore Pte Ltd
Accident Date : 17/01/2022

Vehicle Number : GBG3995Z
Make & Model : Nissan NP300 Navara S/Cabin 6MT

MNTAB4D23Z0000079.

ESTIMATED REPAIR COST DETAILS

Qty	Description	Repairer Amt (\$)	Surveyor App.(\$)
List Item			
1	Rear bumper <i>Distorted</i>	995.45	<i>750</i>
2	Rear bumper side chrome @ SGD 492.40 <i>Distorted</i>	984.80	<i>620</i>
2	Rear bumper bracket corner @ SGD 175.60 <i>Best</i>	351.20	<i>✓</i>
2	Rear bumper arm sub-assy @ SGD 140.30 <i>Men</i>	280.60	<i>+</i>
1	Rear bumper inner beam <i>Men</i>	255.70	<i>+</i>
1	Rear bumper centre top garnish <i>Delhd</i>	386.70	<i>✓</i>
1	Rear bumper number plate panel <i>Best</i>	175.60	<i>✓</i>
1	Rear bumper number plate garnish <i>Delhd</i>	115.60	<i>✓</i>
2	Rear taillamp @ SGD 697.80 <i>could</i>	1,395.60	<i>700</i>
2	Rear taillamp panel @ SGD 226.10 <i>Delhd Men</i>	452.20	<i>+</i>
1	Tailgate panel <i>Distorted</i>	1,986.70	<i>1450</i>
2	Tailgate latch @ SGD 276.80 <i>Delhd</i>	553.60	<i>✓</i>
1	Tailgate emblem (NAVARA) <i>Men</i>	102.40	<i>✓</i>
2	Tailgate gas damper strut @ SGD 176.40 <i>Men</i>	352.80	<i>+</i>
1	Rear end panel beam <i>Delhd</i>	966.40	<i>480</i>
1	Rear floor panel <i>Best</i>	2,268.70	<i>+</i>
1	Rear side panel o/s <i>Bruckhd</i>	1,955.60	<i>800 (SN)</i>
1	Front bumper <i>Distorted</i>	1,376.40	<i>885</i>
2	Front bumper garnish @ SGD 145.60 <i>RH Delhd</i>	291.20	<i>145.60</i>
2	Front bumper bracket @ SGD 68.40 <i>Best</i>	136.80	<i>✓</i>
2	Front bumper side arm @ SGD 142.60 <i>Best</i>	285.20	<i>✓</i>
1	Front bumper number plate garnish <i>Delhd</i>	197.20	<i>✓</i>
1	Radiator grille assy <i>could</i>	497.80	<i>✓</i>
1	Radiator grille logo <i>Men</i>	78.60	<i>✓</i>
1	Bonnet assy <i>Distorted</i>	1,387.20	<i>980</i>
2	Bonnet hinge @ SGD 102.40 <i>Men</i>	204.80	<i>+</i>
2	Headlamp assy @ SGD 745.60 <i>RH could</i>	1,491.20	<i>745.60</i>
1	Front fender @ SGD 772.50 <i>RH Bruckhd</i>	1,545.00	<i>772.50</i>
1	Front fender lamp o/s <i>Men</i>	55.20	<i>X</i>
1	Wiper washer tank <i>Men</i>	168.50	<i>X</i>
1	Horn unit <i>Not Men</i>	110.60	<i>X</i>

AUTO BULLOX PTE LTD

53 Ubi Avenue 1#01-25 Paya Ubi Industrial Park Singapore 408934
Tel: 6844 4290 Fax: 6841 6043 HP: 9769 9299 Email: autobullox@gmail.com
UEN:201919765N

To : Sompo Insurance Singapore Pte Ltd
Attn : Motor Claim Department

Owner : Nakano Singapore Pte Ltd Vehicle Number : GBG3995Z
Accident Date : 17/01/2022 Make & Model : Nissan NP300 Navara S/Cabin 6MT

ESTIMATED REPAIR COST DETAILS

Qty	Description	Repairer Amt (\$)	Surveyor App.(\$)
1	Front support panel <i>Buckled</i>	987.50	✓
1	AC condenser <i>11396.80</i>	1,126.40	+
1	AC condenser discharge hose	286.40	+
1	AC condenser pressure hose <i>10257.21</i>	275.80	+
1	Radiator assy <i>Not in S-N: 800</i>	1,295.60	+
1	Radiator fan cowl assy	676.50	+
	Parts Sum	26,053.55	
	Less 10%	2,605.35	
	Parts Total:	23,448.20	
<u>Special Nett Items</u>			
1set	Rear Number Plate W/Garnish <i>Best</i>	55.00	30
1	Rear end panel sealant <i>Neu</i>	80.00	60
1	Rear floor panel sealant <i>Not in</i>	80.00	60
1set	Rear bumper clips <i>Not in</i>	55.00	+
1	Rear tailgate sticker 70km/h <i>Neu</i>	35.00	15
1	Reverse sensor <i>Damaged</i>	280.00	200
1set	Front bumper clips <i>Neu</i>	55.00	X
1set	Front Number Plate W/Garnish <i>Best</i>	55.00	30
1set	Radiator grille clips <i>Neu</i>	48.00	30
1	Radiator coolant <i>Neu</i>	85.00	50
	Special Nett Items Total	828.00	
<u>Labour & Misc Charges</u>			
	To Remove, Replace, Re-align & Install affected Front Damaged Areas (\$300.00 per day)	1,600.00	800
	To Putty, Prep & Re-spray on affected Front Damaged Areas Front bumper, bonnet, fenders, support panel(\$300.00 per panel)	1,400.00	800
	To Remove, Replace, Re-align & Install affected Rear Damaged Areas (\$300.00 per day)	1,600.00	1400
	To Putty, Prep & Re-spray on affected Rear Damaged Areas -Rear bumper, tailgate, end panel, rear side panels, floor panel (\$300.00 per panel)	1,500.00	1200

AUTO BULLOX PTE LTD

53 Ubi Avenue 1#01-25 Paya Ubi Industrial Park Singapore 408934

Tel: 6844 4290 Fax: 6841 6043 HP: 9769 9299 Email: autobullox@gmail.com

UEN:201919765N

To : Somp Insurance Singapore Pte Ltd

Attn : Motor Claim Department

Owner : Nakano Singapore Pte Ltd

Vehicle Number : GBG3995Z

Accident Date : 17/01/2022

Make & Model : Nissan NP300 Navara S/Cabin 6MT

ESTIMATED REPAIR COST DETAILS

Qty	Description	Repairer Amt (\$)	Surveyor App.(\$)
	To Remove & Transfer Rear Tailgate Components, to Facilitate Repairs	150.00	60
	To Measure, Drill Holes on Replaced Rear Bumper, To Re-position & Install Reverse Sensor	150.00	50
	To Disconnect Front & Rear Wire Harness, Electrical Components to Facilitate Repairs	120.00	60
	To Apply Undercoating on the Affected Damaged Areas	280.00	180
Labour Charges Total		6,800.00	4550
Total Cost of Repair (Non-Inclusive of GST)		31,076.20	

Surveyor's Name

Adrian King LKIC

Survey Date & Time

20/01/22. 12 Days.

Total: 16082.21

L/s: 12850

Remarks:**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: