3/31/22, 9:27 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22000695/KTY3N2

31/03/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNW00003992100

Claimant Vehicle No:

SLQ62P

Insured Vehicle SJV2908J No:

Date of Loss: 18/01/2022 Nature of Claim: TP

Claim

No:

Engine No:

SNM22D200459/C02/IRENE

DCB021611

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLQ62P Reg No:

Make & Model: PORSCHE CAYENNE, 3.0 (A)

Reg. Date: 29/03/2019 (Man. Year: 2018) Chassis No: WP1ZZZ9YZKDA01331

Colour: White Odometer: 35570 km

Engine Capacity: 2995 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 285/40ZR21 Rear Tyre Size: 315/35ZR21 Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		32,722.25	9,942.45	22,779.80	69.62
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,600.00	720.00	1,880.00	72.31
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	35,322.25	10,662.45	24,659.80	69.81
	Approved Total (Overridden) (S\$)		8,000.00		
	(S\$)	35,322.25	8,000.00	27,322.25	77.35
	+ GST 7.00/7.00% (S\$)	2,472.56	560.00	1,912.56	77.35
	Nett Amount (S\$)	37,794.81	8,560.00	29,234.81	77.35

INSPECTION

Date of Assignment: 19/01/2022

Thiam Heng Huat Pte Ltd (SIN MING) 19/01/2022 Inspected At: Date Inspected:

176 SIN MING DRIVE, #05-14

Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: **KENNETH KONG** Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

3/31/22, 9:27 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Mar 2022)

Parts: M1-SUV PORSCHE CAYENNE 3.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLQ62P)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with Validity:

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER UPPER	Buckled/Cracked	3,351.40 FL	*2,008.00 FL
2	1		*REAR BUMPER LOWER	Dented/Cut	1,604.20 FL	*871.38 FL
3	1		*REAR BUMPER CENTER	Dented/Cut	2,675.40 FL	*1,250.24 FL
4	1		*REAR BUMPER CENTER CARRIER	Serviceable	2,048.80 FL	*- FL
5	1		*REAR BUMPER LOWER DIFFUSER	No such part	925.60 FL	*- FL
6	2		*REAR BUMPER LOWER EXHAUST BRACKET	Repair	445.00 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	2,048.40 FL	*1,137.50 FL
8	2		*REAR BUMPER SIDE CARRIER	Serviceable	483.60 FL	*- FL
9	1		*REAR BUMPER SIDE REFLECTOR	O/s Cracked	923.00 FL	*167.65 FL
10	1		*REAR BUMPER PDC MODULE	Serviceable	2,880.80 FL	*- FL
11	1		*REAR BUMPER PDC MODULE HARNESS	Serviceable	1,658.80 FL	*- FL
12	2		*EXHAUST TIP	Serviceable	1,859.00 FL	*- FL
13	1		*EXHAUST TIP CHROME	O/s Dented/N/s Serviceable	1,331.20 FL	*463.00 FL
14	1		*EXHAUST FRONT SILENCER ASSY	Repair	5,930.60 FL	*-FL
15	1		*EXHAUST REAR SILENCER ASSY	Bent	5,002.40 FL	*3,845.00 FL
16	2		*EXHAUST FRONT SILENCER HOLDER	Serviceable	436.80 FL	*-FL
17	2		*EXHAUST REAR SILENCER HOLDER	Serviceable	410.80 FL	*- FL
18	1		*EXHAUST HEATSHIELD UPPER	Serviceable	456.30 FL	*- FL
19	1		*EXHAUST HEATSHIELD LOWER	Dented	374.40 FL	*374.40 FL
20	18		*REAR BUMPER CLIPS	Necessary	117.00 FS	*117.00 FS
21	2		*REAR PDC SENSOR CENTER	Shorted	1,193.40 FS	*720.00 FS
22	1		*SUNDRIES	Not Necessary	50.00 FS	*-FS
F=Fra	nchise	part. S=Spc	Nett. L=ListItemDisc.			

Sub Total (S\$) 36,206.90 10,954.17 - List Item Discount on L Items 10.00/10.00% (S\$) 3,484.65 1,011.72

9,942.45

Total Parts (S\$) 32,722.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,200.00	400.00
2	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS	New	50.00	20.00
3	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	1,200.00	300.00
4	TO RUST PROOF ACCIDENT AFFECTED PORTIONS	New	150.00	0.00
	Gross Labour Cost (S\$)		2,600.00	720.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >