

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000697/UPA3Q2**Date:** 13/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900011859-02
Claimant Vehicle No :	GBK4797B	Insured Vehicle No :	SMH2130Z
Date of Loss:	18/01/2022	Nature of Claim:	TP
		Claim No:	3812285571SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK4797B		
Make & Model:	SUZUKI EVERY, 660cc GA (M)	Engine No:	R06A2757160
Reg. Date:	06/08/2020 (Man. Year: 2020)	Chassis No:	DA17V856861
Colour:	White	Odometer:	23039 km
Engine Capacity:	658 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	145/80 R12	Rear Tyre Size:	145/80 R12
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,482.00	1,542.10	939.90	37.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,870.00	1,310.00	560.00	29.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,352.00	2,852.10	1,499.90	34.46
+ GST 7.00/7.00% (S\$)	304.64	199.65	104.99	34.46
Nett Amount (S\$)	4,656.64	3,051.75	1,604.89	34.46
+ Car Rental (5.0 x S\$80.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,481.75		

INSPECTION

Date of Assignment:	19/01/2022	
Date Inspected:	19/01/2022	Inspected At: Stytech Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub Singapore 417921
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Badly Dented	899.00 F	*899.00 FL
2	1		*REAR BOOT WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
3	1		*REAR BOOT EMBLEM	Serviceable	38.00 F	*- FL
4	1		*REAR BOOT HANDLE	Not Necessary	45.00 F	*- FL
5	1		*REAR BOOT 4 PAX STICKER	Necessary	10.00 FS	*10.00 FS
6	1		*REAR BOOT 70KM/H STICKER	Necessary	10.00 FS	*10.00 FS
7	1		*REAR BUMPER	Bent	527.00 F	*527.00 FL
8	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
9	2		*TAILLAMP (LEFT & RIGHT)	Serviceable	170.00 F	*- FL
10	1		*REAR LICENCE PLATE	Bent	40.00 FS	*40.00 FS
11	1		*REAR LICENCE PLATE LAMP	Not Necessary	35.00 F	*- FL
12	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
13	1		*REAR CAMERA	Serviceable	120.00 FS	*- FS
14	1		*REAR END PANEL	Repair	220.00 F	*- FL
15	1		*REAR BOOT LOCK	Serviceable	78.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,482.00	1,756.00
- List Item Discount on L Items 0.00/15.00% (\$\$)	0.00	213.90
Total Parts (\$\$)	2,482.00	1,542.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER REAR WINDSCREEN	New	120.00	120.00
2	TRANSFER BOOT MECHANISM	New	150.00	60.00
3	ANTI RUST PROOF	New	100.00	30.00
4	CHECK WIRING	New	100.00	20.00
5	PANEL BEATING	New	600.00	580.00
6	PAINT WORK	New	800.00	500.00
Gross Labour Cost (\$\$)			1,870.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >