

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22000700/UPA3Q2**Date:** 20/09/2022REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | F210059242   |
| <b>Claimant Vehicle No :</b> | SFM7887Y                             | <b>Insured Vehicle No :</b> | SNA2399R     |
| Date of Loss:                | 14/01/2022                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 2092804496SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SFM7887Y</b>                   | Engine No:  | 1ZRY296845        |
| Make & Model:               | TOYOTA COROLLA ALTIS, 1.6 CVT (A) | Chassis No: | MR053REH104551882 |
| Reg. Date:                  | 29/08/2016 (Man. Year: 2016)      | Odometer:   | 261291 km         |
| Colour:                     | Black                             |             |                   |
| Engine Capacity:            | 1598 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 215/45Z R17 | Rear Tyre Size:  | 215/45Z R17 |
| Front Left Side:  | CST 6 mm    | Rear Left Side:  | CST 6 mm    |
| Front Right Side: | CST 6 mm    | Rear Right Side: | CST 6 mm    |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 9,646.20          | 1,712.02          | 7,934.18          | 82.25         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 3,850.00          | 1,580.00          | 2,270.00          | 58.96         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>13,496.20</b>  | <b>3,292.02</b>   | <b>10,204.18</b>  | <b>75.61</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>2,600.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 13,496.20         | 2,600.00          | 10,896.20         | 80.74         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 944.73            | 182.00            | 762.73            | 80.74         |
| <b>Nett Amount (S\$)</b>                        | <b>14,440.93</b>  | <b>2,782.00</b>   | <b>11,658.93</b>  | <b>80.74</b>  |
| <b>+ Loss of Use (3.0 x S\$60.00/day) (S\$)</b> |                   | 180.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 2.00              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>2,964.00</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>2,960.00</b>   |                   |               |

INSPECTION

|                             |            |                                                                                                         |
|-----------------------------|------------|---------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 19/01/2022 |                                                                                                         |
| Date Inspected:             | 19/01/2022 | Inspected At: Fastech Auto Pte Ltd (HQ)<br>1 Kaki Bukit Ave 6, #01-46/48/50 Autobay<br>Singapore 417883 |
| Estimated Period of Repair: | 3.0 days   |                                                                                                         |

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                     | Condition         | Repairer's | Amount     |
|-----|-----|----------|---------------------------------|-------------------|------------|------------|
| 1   | 1   |          | *BOOTLID                        | Repair            | 1,266.10 F | *- FL      |
| 2   | 1   |          | *BOOTLID REAR LOGO              | Not Necessary     | 68.50 F    | *- FL      |
| 3   | 1   |          | *BOOTLID COROLLA EMBLEM         | Not Necessary     | 62.80 F    | *- FL      |
| 4   | 1   |          | *BOOTLID ALTIS EMBLEM           | Not Necessary     | 58.00 F    | *- FL      |
| 5   | 1   |          | *BOOTLID 1.6 EMBLEM             | Not Necessary     | 38.00 F    | *- FL      |
| 6   | 1   |          | *BOOTLID INNER LOCK             | Not Necessary     | 409.10 F   | *- FL      |
| 7   | 1   |          | *BOOTLID LOCK STRICKER          | Not Necessary     | 66.80 F    | *- FL      |
| 8   | 1   |          | *BOOTLID WEATHERSTRIP           | Twisted           | 282.30 F   | *266.10 FL |
| 9   | 2   |          | *BOOTLID REFLECTORS             | Not Necessary     | 901.80 F   | *- FL      |
| 10  | 1   |          | *BOOTLID INNER TRIM             | Not Necessary     | 366.10 F   | *- FL      |
| 11  | 1   |          | *REAR BUMPER                    | Dented / Deformed | 655.10 F   | *486.50 FL |
| 12  | 1   |          | *REAR BUMPER BEAM               | Dented            | 505.40 F   | *395.00 FL |
| 13  | 2   |          | *REAR BUMPER BRACKETS           | Not Necessary     | 210.00 F   | *- FL      |
| 14  | 2   |          | *REAR BUMPER REFLECTORS         | Not Necessary     | 120.00 F   | *- FL      |
| 15  | 2   |          | *REAR BUMPER SIDE RETAINERS     | Not Necessary     | 130.00 F   | *- FL      |
| 16  | 1   |          | *SET REAR BUMPER CLIPS          | Necessary         | 50.00 F    | *50.00 FL  |
| 17  | 1   |          | *REAR END PANEL                 | Dented            | 788.20 F   | *645.10 FL |
| 18  | 1   |          | *REAR END PANEL TOP GARNISH     | Not Necessary     | 362.30 F   | *- FL      |
| 19  | 2   |          | *TAILLAMPS                      | Not Necessary     | 1,160.00 F | *- FL      |
| 20  | 1   |          | *REAR FLOOR PANEL               | Not Necessary     | 1,145.20 F | *- FL      |
| 21  | 1   |          | *REAR FLOOR PANEL TOP BOARD     | Not Necessary     | 420.50 F   | *- FL      |
| 22  | 1   |          | *SET REAR BUMPER REVERSE SENSOR | Shorted           | 280.00 FS  | *200.00 FS |
| 23  | 1   |          | *REAR END PANEL SEALANT         | Necessary         | 50.00 FS   | *50.00 FS  |
| 24  | 1   |          | *SET REAR BUMPER RUBBER PAD     | Necessary         | 250.00 FS  | *80.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                 |                 |
|----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (S\$)</b>                                   | <b>9,646.20</b> | <b>2,172.70</b> |
| <b>- List Item Discount on L Items 0.00/25.00% (S\$)</b> | 0.00            | 460.68          |
| <b>Total Parts (S\$)</b>                                 | <b>9,646.20</b> | <b>1,712.02</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                               | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                           |          |                 |                 |
| 1                               | TO CHECK WIRING                           | New      | 50.00           | 20.00           |
| 2                               | TO DISMANTLE & REPLACED REVERSE SENSOR    | New      | 80.00           | 50.00           |
| 3                               | TO DISMANTLE & REFIX BOOTLID MECHANISM    | New      | 100.00          | 0.00            |
| 4                               | TO DISMANTLE & REFIX CUSHION UPHOLSTERY   | New      | 120.00          | 80.00           |
| 5                               | TO SPRAY RUST PROOFING                    | New      | 100.00          | 30.00           |
| 6                               | LABOUR FOR PANEL BEATING & REPLACED PARTS | New      | 1,600.00        | 600.00          |
| 7                               | TO PUTTY & SPRAY PAINTING                 | New      | 1,800.00        | 800.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                           |          | <b>3,850.00</b> | <b>1,580.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >