

ASS. REC. BY: Steve

REF: CS/ASM22000701/Ety3

CS/ASM22000701/Ety3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD/TP/WS/LTP RES/OD RES/EVA/INV/INV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of Inspection.



Bel. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJM4304k Yr Regn: 2/1/09
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda fit as 1339
Colour: White A/C: Insured / Std / Nil / NA
Sp. Reading: 127167 T/Radio: Insured / Std / Nil / NA
Eng/No: _____
C/No: GE6138275
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modl: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/55R15
R: 1
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front R/Bal. 4 mm Rear R/Bal. 4 mm
L/Bal. 4 mm L/Bal. 4 mm
D.O.A. 15/1/09 D.O.I. 9/2/09
Survey held at Win Automotive
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV-16X

Finalize \$3700 (L/S, before GST). 5 days
red: 6127.84;62%

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO: SJM 4344K

Adjustment of Spare Parts Costs for Repairs				Estimated by	Disc.	Adjusted
Item	Qty	Vehicle parts description		workshop	(%)	cost
1	1	Tailgate / DD		796.00	20	636.80
2	1	Tailgate inner lock ?		135.50	20	108.40
3	1	Tailgate lock catch X		97.80	20	78.24
4	1	Tailgate weatherstrip / TA		162.70	20	130.16
5	1	Tailgate centre garnish ?		126.30	20	101.04
6	1	Tailgate centre logo ?		65.00	20	52.00
7	1	Tail gate emblem - 'FIT' / n/c		72.00	20	57.60
8	1	Tailgate inner board ?		168.20	20	134.56
9	1(set)	Tailgate inner cover clips ?		50.00	20	40.00
10	2	tailgate number plate lamp @\$40 X		80.00	20	64.00
11	2	tailgate absorber @\$150 X		300.00	20	240.00
12	2	Taillamp (RH) / LUT		520.00	20	416.00
13	2set	Taillamp fasteners X		28.00	20	22.40
14	1	Rear windscreen X		1450.00	20	1160.00
15	1	Rear windscreen moulding / n/c		105.00	20	84.00
16	1	rear windscreen wiper X		78.00	20	62.40
17	2	Rear fender inner trim X		788.00	20	630.40
18	2(set)	Rear fender inner trim clips X		64.00	20	51.20
19	2	rear air vent @\$35 X		70.00	20	56.00
20	1	Spare tyre floor panel X		790.00	20	632.00
21	1	Spare tyre panel board X		200.00	20	160.00
22	1	Spare tyre bracket X		240.00	20	192.00
23	1	Rear end panel ?		320.00	20	256.00
24	1	Rear end panel top garnish ?		155.00	20	124.00
25	1	Rear bumper / DD		720.00	20	576.00
26	2	rear bumper support bracket @\$40 / BR		80.00	20	64.00
27	2	Rear bumper side retainer @ \$28.10 X		56.20	20	44.96
28	1	Rear bumper tow hook cover X		45.30	20	36.24
29	1(set)	Rear bumper clip / n/c		26.30	20	21.04
30	1	Exhaust end pipe X		580.00	20	464.00
31	2	Exhaust mounting @ \$26.50 X		53.00	20	42.40
Total parts				8422.30		6737.84

Special Nett Items

1	1	Rear bumper sensor / BR	200.00
2	1	Rear windscreen sealant / n/c	40 60.00
3	1	Spare tyre panel sealant X	60.00
4	1	Rear end panel sealant / n/c	60.00
5	1	Rear Carplate w casing X	60.00
Total parts			16844.60 440.00

Adjustment of Labour Costs for Repairs

To remove & replaced damaged parts including straightening/repositioning of replacement parts.	1000.00	600
To remove & install interior fittings/attachments to facilitate	120.00	50
To remove/refit wiring at damaged section. To check electrical system for proper functions.	40.00	30
To supply paint material and expandable items. To respray replaced and affected panels.	800.00	600
To remove/refit windscreen	120.00	/
To remove & replace exhaust end pipe. To realign exhaust system.	80.00	X
Remove & refit tailgate components	80.00	50
To remove & refit & align rear chassis	250.00	X
To carry out anti rust treatment on the affected panels.	80.00	30
to remove and reinstall reverse sensor	80.00	30

Total labour 2650.00

Steve (LKK)
9/2/22, 12.00m

ML
L/S
y M y
S 45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before any repair work
- To display damaged parts
- Parts prices
- Third party
- No illegal
- Supplement

is subject to LKK Auto Consultants Insurance company

Acknowledged by Repairer

Signature:

Date: