3/9/23, 10:35 AM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22000703/UYA3Q2

09/03/2023 Date:

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900095893 **Claimant Vehicle** SLU983K Insured Vehicle No: SML1587A No:

Date of Loss: 18/01/2022 Nature of Claim: ΤP Claim No: 8018157736SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SLU983K** 

Make & Model: VOLKSWAGEN GOLF, 1.4 (A) CJZ614362 Engine No:

Reg. Date: 29/06/2015 (Man. Year: 2015) Chassis No: WVWZZZAUZFW320105

Colour: White Odometer: 115153 km

**Engine Capacity:** 1197 cc Market Value/New Car N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 205/55 R16 Rear Tyre Size: Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,098.65	4,335.71	6,762.94	60.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,610.00	950.00	2,660.00	73.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,708.65	5,285.71	9,422.94	64.06
Approved Total (Overridden) (S\$)		4,200.00		
Nett Amount (S\$)	14,708.65	4,200.00	10,508.65	71.45
+ Car Rental (4.0 x S\$	100.00/day) (S\$)	400.00		
+ Doc/	Search Fee (S\$)	31.00		
N	lett Liability (S\$)	4,631.00		

**INSPECTION** 

Date of Assignment: 20/01/2022

Zoom Autowerks Pte Ltd (HQ)

130 Bedok Reservoir Road, Eunos Spring, #08-Date Inspected: 20/01/2022 Inspected At:

1339

Singapore 470130

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

### **Recommended Parts**

	*FRONT HEADLAMP O/S *FRONT BUMPER  *SET FRONT BUMPER CLIP *FRONT BUMPER REINFORCEMENT *FRONT BUMPER SIDE RETAINER *FRONT FENDER -RH	Cracked Distorted Necessary Not Necessary Bent	1,035.00 FL 1,440.00 FL 60.00 FL 465.00 FL 187.20 FL	*1,035.00 FL *1,145.30 FL *60.00 FL *- FL
	*SET FRONT BUMPER CLIP *FRONT BUMPER REINFORCEMENT *FRONT BUMPER SIDE RETAINER	Necessary Not Necessary	60.00 FL 465.00 FL	*60.00 FL
	*FRONT BUMPER REINFORCEMENT *FRONT BUMPER SIDE RETAINER	Not Necessary	465.00 FL	
	*FRONT BUMPER SIDE RETAINER	•		*- FL
		Bent	187.20 FL	
	*FRONT FENDER -RH			*101.50 FL
		Dented	686.40 FL	*686.40 FL
	*FRONT FENDER INNER SHIELD	Torn	345.60 FL	*188.20 FL
	*SET FRONT FENDER INNER SHIELD CLIP	Necessary	50.00 FL	*50.00 FL
	*FRONT DOOR -RH	Not Necessary	1,645.00 FL	*- FL
	*FRONT DOOR RUBBER	Not Necessary	193.10 FL	*- FL
	*FRONT WHEEL HUB WITH BEARING	Damaged	576.00 FL	*395.00 FL
	*FRONT SHOCK ABSORBER	Not Necessary	384.00 FL	*- FL
	*FRONT KNUCKLE ARM	Bent	751.20 FL	*600.50 FL
	*FRONT LOWER ARM	Not Necessary	420.00 FL	*- FL
	*FRONT TIE ROD	Not Necessary	120.00 FL	*- FL
	*FRONT DRIVE SHAFT -RH	Not Necessary	2,640.00 FL	*- FL
	*FRONT TYRE	Serviceable	400.00 FS	*- FS
	*FRONT WHEEL RIM -RH	Warped	800.00 FS	*500.00 FS
e part. S=SpcN	ett. L=ListItemDisc.	_		
		Sub Total (S\$)	12,198.50	4,761.90
	- List Item Discount on L Items	s 10.00/10.00% (S\$)	1,099.85	426.19
		Total Parts (S\$)	11,098.65	4,335.71
e	part. S=SpcN	*FRONT DOOR RUBBER  *FRONT WHEEL HUB WITH BEARING  *FRONT SHOCK ABSORBER  *FRONT KNUCKLE ARM  *FRONT LOWER ARM  *FRONT TIE ROD  *FRONT DRIVE SHAFT -RH  *FRONT TYRE  *FRONT WHEEL RIM -RH  part. S=SpcNett. L=ListItemDisc.	*FRONT DOOR RUBBER  *FRONT WHEEL HUB WITH BEARING  *FRONT SHOCK ABSORBER  Not Necessary  *FRONT KNUCKLE ARM  *FRONT LOWER ARM  Not Necessary  *FRONT TIE ROD  Not Necessary  *FRONT DRIVE SHAFT -RH  Not Necessary  *FRONT TYRE  Serviceable  *FRONT WHEEL RIM -RH  Part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$)  - List Item Discount on L Items  Total Parts (S\$)	*FRONT DOOR RUBBER         Not Necessary         193.10 FL           *FRONT WHEEL HUB WITH BEARING         Damaged         576.00 FL           *FRONT SHOCK ABSORBER         Not Necessary         384.00 FL           *FRONT KNUCKLE ARM         Bent         751.20 FL           *FRONT LOWER ARM         Not Necessary         420.00 FL           *FRONT TIE ROD         Not Necessary         120.00 FL           *FRONT DRIVE SHAFT -RH         Not Necessary         2,640.00 FL           *FRONT TYRE         Serviceable         400.00 FS           *FRONT WHEEL RIM -RH         Warped         800.00 FS           part. S=SpcNett. L=ListItemDisc.         Sub Total (\$\$)         1,099.85           Total Parts (\$\$)         11,098.65

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	20.00
2	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	450.00	120.00
3	TO CONDUCT WHEEL ALIGNMENT	New	180.00	80.00
4	TO REMOVE ,REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS ,TRANSFER ALL FITTINGS TO NEW DOOR	New	150.00	0.00
5	TO APPLY UNDERCOATING	New	150.00	30.00
6	PANEL BEATING	New	1,400.00	300.00
7	TO RESPRAY PAINTING ON THE AFFECTED AREAS	New	1,200.00	400.00
	Gross Labour Cost (S\$)		3,610.00	950.00
	Report was unsubmitted during th	is print-out.		

< END OF ESTIMATES >