



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 5992T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>LABOUR</u></b> SUPPLY OF LABOUR AND MATERIAL FOR THE REPAIR OF RCV XE5992T AS FOLLOWS REMOVING OF DAMAGED BINLIFTER ASSY, FORMING & WELDING, FABRICATION OF SUB ASSEMBLY, RETROFITTING NEW BIN LIFTER STEPPER AND SENSOR ONTO THE RCV AND TESTING AND PAINTING OF BINLIFTER ASSEMBLY OF AFFECTED AREA OF REPAIR.		14,000.00	13,700.00
			14,000.00	13,700.00
	<b>GRAND TOTAL</b>		<b>14,000.00</b>	<b>13,700.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>13,700.00</b>

Report Ref No. CS/ASM22000709/Ety3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.