



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 2548Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	NOT NECESSARY	3,215.00	-
1	TAILGATE VOLVO EMBLEM	NOT NECESSARY	158.00	-
1	TAILGATE "XC60" EMBLEM	NOT NECESSARY	125.00	-
1	TAILGATE "T5" EMBLEM	NOT NECESSARY	115.00	-
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	295.00	-
1	TAILGATE INNER LOCK	NOT NECESSARY	355.00	-
1	REAR BUMPER TOP	DISTORTED	2,800.00	1,895.00
1	REAR BUMPER LOWER	DISTORTED	2,200.00	1,415.00
1	REAR BUMPER DIFFUSER	DISTORTED	580.00	425.00
2	REAR BUMPER LAMPS @\$215.00	O/S CRACKED / N/S NOT NECESSARY	430.00	182.00
2	REAR BUMPER SIDE HOLDERS @\$148.00	O/S CRACKED / N/S NOT NECESSARY	296.00	142.00
1	REAR BUMPER SPONGE	NOT FITTED	266.00	-
1	REAR BUMPER REINFORCEMENT	BENT	1,415.00	945.00
4	REAR BUMPER PDC SENSORS @\$250.00	SHORTED (1 PC ONLY)	1,000.00	205.00
1	REAR BUMPER PDC SENSOR WIRE	TORN	366.00	315.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR END PANEL	DENTED	1,200.00	1,100.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	421.00	-
1	REAR FENDER UNDER COVER O/S	DISTORTED	455.00	309.00
1	REAR FENDER UNDER COVER CLIPS O/S	NECESSARY	50.00	50.00
1	REAR EXHAUST ASSY	BENT / TWISTED	3,215.00	1,905.00
1	REAR EXHAUST CHROME O/S	BENT	520.00	250.00
1	REAR EXHAUST MOUNTING	NOT NECESSARY	60.00	-
1	REAR EXHAUST HEAT SHIELD	BENT	425.00	298.00
1	TAILLAMP	NOT NECESSARY	980.00	-
	LESS 5% DISCOUNT		-	-474.30
			20,992.00	9,011.70

Report Ref No. CS/AGI22000714/Uvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REAR PDC SENSOR.		100.00	50.00
	TO TRANSFER TAILGATE MECHANISM.	NOT NECESSARY	120.00	-
	TO DISMANTLE & REFIX REAR TAILGATE GLASS.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO DISMANTLE & REPLACED REAR EXHAUST.		180.00	80.00
	TO SPRAY PROOFING.		100.00	30.00
	TO RESET & REPROGRAMME SYSTEM.	NOT NECESSARY	180.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.		1,200.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	900.00
			3,700.00	1,760.00
	GRAND TOTAL		24,692.00	10,771.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,600.00

Report Ref No. CS/AGI22000714/Uvf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.