

The insurer has given adjuster a maximum mandate of S\$25,000.00 to authorize directly on their behalf, but the adjuster has disabled direct offer mode.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22000716/UQF3E2
Date: 07/02/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29147077AT2		
Claimant Vehicle No :	SGT45H	Insured Vehicle No :	SME8392K		
Date of Loss:	19/01/2022	Nature of Claim:	TP	Claim No:	639822

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGT45H	Engine No:	27091031625561
Make & Model:	MERCEDES-BENZ GLA200, 1.6 AMG LINE (R18 BI) (A)	Chassis No:	WDC1569432J506433
Reg. Date:	30/07/2018 (Man. Year: 2018)	Odometer:	74273 km
Colour:	Black		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40Z R19	Rear Tyre Size:	235/40Z R19
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,511.85	7,977.20	9,534.65	54.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,770.00	1,060.00	1,710.00	61.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,281.85	9,037.20	11,244.65	55.44
Approved Total (Overridden) (S\$)		7,200.00		
(S\$)	20,281.85	7,200.00	13,081.85	64.50
+ GST 7.00/7.00% (S\$)	1,419.73	504.00	915.73	64.50
Nett Amount (S\$)	21,701.58	7,704.00	13,997.58	64.50

INSPECTION

Date of Assignment:	26/01/2022		
Date Inspected:	20/01/2022	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Feb 2022)
Parts:	M1-SUV	MERCEDES-BENZ GLA200 1.6 AMG LINE (R18 BI) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGT45H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,715.32 F	*1,715.32 FL
2	1		*FRONT BUMPER BEAM	Bent	845.10 F	*645.32 FL
3	1		*FRONT BUMPER SIDE RETAINER O/S	Cracked	105.00 F	*105.00 FL
4	1		*FRONT BUMPER FOG LAMP GARNISH O/S	Grazed	162.00 F	*148.50 FL
5	1		*FRONT BUMPER PDC SENSORS (2PCS)	Shorted (1Pc Only)	380.00 F	*168.82 FL
6	1		*SET FRONT BUMPER CLIPS & RIVET	Necessary	60.00 F	*60.00 FL
7	1		*FRONT BUMPER LOWER	Grazed	561.00 F	*345.21 FL
8	1		*FRONT BUMPER LOGO	Necessary	85.00 F	*85.00 FL
9	1		*FRONT BUMPER SPONGE	Torn	162.00 F	*155.41 FL
10	1		*FRONT HEADLAMP O/S	Cracked	6,500.00 F	*2,594.23 FL
11	1		*FRONT SUPPORT PANEL	Repair	845.11 F	*- FL
12	1		*FRONT FENDER O/S	Buckled	1,018.00 F	*889.83 FL
13	1		*FRONT FENDER INNER SHIELD O/S	Torn	381.00 F	*186.10 FL
14	1		*SET FRONT FENDER INNER SHIELD CLIPS O/S	Necessary	60.00 F	*60.00 FL
15	1		*FRONT FENDER OUTER PROTECTOR O/S	Distorted	485.12 F	*218.89 FL
16	1		*FRONT SPORT RIM 19 INCH	Grazed	1,500.00 F	*1,485.93 FL
17	1		*FRONT LOWER ARM O/S	Not Necessary	611.20 F	*- FL
18	1		*FRONT WHEEL HUB BEARING O/S	Not Necessary	650.00 F	*- FL
19	1		*FRONT TEMPERATURE SENSOR	Not Necessary	380.00 F	*- FL
20	1		*FRONT KNUCKLE ARM O/S	Not Necessary	1,006.00 F	*- FL
					Sub Total (S\$)	17,511.85 8,863.56
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00 886.36
					Total Parts (S\$)	17,511.85 7,977.20

F=Franchise part. L=ListItemDisc.

Recommended Miscellaneous Items
There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED FRT PDC SENSOR	New	80.00	50.00
3	TO SPRAY RUST PROOFING	New	80.00	30.00
4	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
5	TO DISMANTLE & REPLACED FRT UNDER CARRIAGE	New	180.00	0.00
6	TO RESET & REPROGRAMME SYSTEM	New	180.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	880.00	500.00
8	TO PUTTY & SPRAY PAINTING	New	1,200.00	400.00
Gross Labour Cost (S\$)			2,770.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >