

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 14 Feb 2022

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|-------------------------|
| Vehicle No | : SJS7M | Accident Date | : 15/01/2022 |
| Make | : PORSCHE CAYENNE | Policy No. | : DMPCSNW00074102100 |
| Assignment Date | : 20/01/2022 | Excess | : S\$4,000.00 |
| Date of Inspection | : 20/01/2022 | Est. Duration of Repair | : 7 |
| Inspection At | : MBM WHEELPOWER PTE LTD (SIN MING) 176 SIN MING DRIVE #01-15, SIN MING AUTOCARE SINGAPORE 575721 | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|----------------|---|
| Repairer's Estimate (Gross) | :S\$ 82,412.01 | (ESTIMATE \$42,695.76 + SUPPLEMENTARY \$39,716.25) |
| Revised Amount | :S\$ 64,592.24 | |
| Check Items (Estimated) | :S\$ 7,400.61 | |
| Total | :S\$ 71,992.85 | |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | |
|--------------------|-----------------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ 440,000.00 |
| COE / PARF Rebate | :S\$ 147,644.00 |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ 292,356.00 |

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.