



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFA 3838D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SUNDRIES (SN)	NECESSARY	80.00	40.00
1	FRT LH FENDER (SN)	DENTED	600.25	600.25
1	FRT LH SIDE PANEL BRACKET 3 (SN)	NOT NECESSARY	35.30	-
			715.55	640.25
	<b><u>LABOUR</u></b>			
	TO REPLACE FRONT LEFT SIDE PANEL AND REPAIR INNER PILLAR LEFT.		2,550.00	850.00
	TO SPRAY PAINT FRONT LEFT SIDE PANEL AND FRONT LEFT A PILLAR.		1,558.00	841.00
	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)		118.00	112.00
	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS.		177.00	168.00
	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS. (1X)	NOT NECESSARY	531.00	-
			4,934.00	1,971.00
	<b>GRAND TOTAL</b>		<b>5,649.55</b>	<b>2,611.25</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>2,611.25</b>
	<b>LESS EXCESS</b>			<b>-750.00</b>
	<b>NETT LIABILITY</b>			<b>1,861.25</b>

Report Ref No. CS/UOI22000728/Evf3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.