

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 20 Jan 2022)
 Parts: N/A CITROEN C4 CACTUS 1.2 AT6 (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SMP8584R)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR TAIL GATE	0.00	0.00	*800.00 F XR
2	1		*REAR TAIL GATE LOCK	0.00	0.00	*200.00 F X R
3	1		*REAR TAIL GATE LOGO	0.00	0.00	*80.00 F x nn
4	1		*REAR TAIL GATE LOGO C4	0.00	0.00	*60.00 F x nn
5	1		*REAR TAIL GATE LOGO CACTUS	0.00	0.00	*60.00 F x nn
6	1		*REAR TAILGATE CENTRE PANEL	0.00	0.00	*460.00 F X SVC
7	1		*REAR TAIL GATE INNER TRIM BOARD	0.00	0.00	*350.00 F x SVC
8	1		*REAR LAMP LH	0.00	0.00	*600.00 F X SVC
9	1		*REAR LAMP RH	0.00	0.00	*600.00 F x SVC
10	1		*REAR BUMPER	0.00	0.00	*120.00 F V BVC
11	1		*REAR BUMPER SIDE RETAINER LH & RH	0.00	0.00	*160.00 F X SVC
12	1		*REAR BUMPER LOWER	0.00	0.00	*350.00 F V BVC
13	1		*REAR BUMPER CENTRE LOWER	0.00	0.00	*320.00 F ?
14	1		*REAR BUMPER TOW COVER	0.00	0.00	*400.00 F ?
15	1		*REAR CORNER GARNISH PANEL LH * BELOW LAMP	0.00	0.00	*400.00 F X SVC
16	1		*REAR CORNER GARNISH PANEL RH * BELOW LAMP	0.00	0.00	*400.00 F X SVC
17	1		*REAR REFLECTOR LH	0.00	0.00	*250.00 F X SVC
18	1		*REAR REFLECTOR RH	0.00	0.00	*250.00 F X SVC
19	1		*REAR WEATHERSHIELD	0.00	0.00	*260.00 F X SVC
20	1		*REAR END PANEL	0.00	0.00	*400.00 F BVC
21	1		*REAR END PANEL GARNISH	0.00	0.00	*100.00 F X SVC
22	1		*REAR TAIL GATE GLASS MOULDING	0.00	0.00	- xnn
23	1		*REAR FENDER LH	0.00	0.00	*2,000.00 F XR
24	1		*REAR FENDER SHIELD LH	0.00	0.00	*100.00 F X SVC
25	1		*REAR FENDER WHEEL ARCH LH	0.00	0.00	*290.00 F X SVC
26	1		*REAR FENDER RH	0.00	0.00	*2,000.00 F XR
27	1		*REAR FENDER SHIELD RH	0.00	0.00	*100.00 F X SVC
28	1		*REAR FENDER WHEEL ARCH RH	0.00	0.00	*290.00 F BVC
29	1		*FRONT HEADLAMP LH	0.00	0.00	*800.00 F ?
30	1		*FRONT HEADLAMP LOWER BRACKET LH	0.00	0.00	*180.00 F ?
31	1		*FRONT HEADLAMP GARNISH LH	0.00	0.00	*150.00 F ?
32	1		*FRONT HEADLAMP RH	0.00	0.00	*800.00 F ?
33	1		*FRONT HEADLAMP LOWER BRACKET RH	0.00	0.00	*180.00 F ?
34	1		*FRONT HEADLAMP GARNISH RH	0.00	0.00	*150.00 F ?
35	1		*FRONT BUMPER	0.00	0.00	*1,200.00 F XR
36	1		*FRONT BUMPER SIDE RETAINER LH & RH	0.00	0.00	*240.00 F X SVC
37	1		*FRONT BUMPER LOWER	0.00	0.00	*350.00 F X SVC
38	1		*FRONT GRILLE CENTRE	0.00	0.00	*650.00 F X SVC
39	1		*FRONT EMBLEM	0.00	0.00	*140.00 F V nec
40	1		*FRONT FOGLAMP LH	0.00	0.00	*280.00 F X SVC
41	1		*FRONT FOGLAMP GARNISH LH	0.00	0.00	*150.00 F
42	1		*FRONT FOLAMP RH	0.00	0.00	*280.00 F X SVC
43	1		*FRONT FOGLAMP GARNISH RH	0.00	0.00	*150.00 F X SVC
44	1		*FRONT SIGNAL LAMP LH *BUMPER	0.00	0.00	*550.00 F X SVC
45	1		*FRONT SIGNAL LAMP RH *BUMPER	0.00	0.00	*550.00 F X SVC

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*FRONT REINFORCEMER ARM LH & RH	0.00	0.00	*360.00 F X R
47	1		*FRONT NUMBER PLATE GARNISH	0.00	0.00	*280.00 F ?
48	1		*REVERSE SENSOR SET	0.00	0.00	*480.00 F X
49	1		*REVERSE SENSOR SEAL SET	0.00	0.00	*180.00 F
50	1		*FRONT SUPPORT PANEL	0.00	0.00	*550.00 F X
51	1		*FRONT BUMPER TOW COVER	0.00	0.00	*-F ?

F=Franchise part.

Sub Total (\$\$)	20,050.00
+ Margin on L,N Items 10.00% (\$\$)	2,005.00
Total Parts (\$\$)	22,055.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	FRONT BUMPER & FRONT FENDER SHIELD CLIPS	60.00nm
2	1	FRONT NUMMBER PLATE WITH FRAME	45 50.00 BT
3	1	REAR BUMPER CLIPS & REAR FENDER SHIELD CLIPS	nee 60.00 ✓
4	1	REAR END PANEL GARNISH CLIPS	45.00Xnm
5	1	REAR FENDER WHEEL ARCH CLIPS LH & RH	0/5nel 80.00 X
6	1	REAR NUMBER PLATE WITH FRAME	45sh 50.00 ✓
7	1	REAR TAILGATE GLASS SEALANT	80.00 Xnm
8	1	REVERSE SENSOR SET	: 360.00 200SH
Sub Total (S\$)			785.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	SPRAY PAINT ON ALL AFFECTED AREA (FRONT & REAR)	New	300	1,200.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1200	1,500.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	40	100.00
4	TO APPLY ANTI RUST TREATMENT	New		120.00 X
5	TO REMOVE/REFIX REVERSE SENSOR	New		150.00 50
6	TO REMOVE/REFIX REAR INNER COMPARTMENT TO FACILITIES REPAIR	New		150.00 X
7	TO REMOVE/REFIX REAR TAILGATE, TOP SPOILER, WIPER MOTOR, MECHEMISM & ETC TO NEW TAILGATE	New		300.00 X
8	TO CHECK WATER LEAKING	New		150.00 20
9	COMPUTER DIAGNOSTIS AFTER REPAIR	New		380.00 ?
Gross Labour Cost (S\$)				4,050.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >