

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000734/UEA3Q2**Date:** 19/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100505592
Claimant Vehicle No :	GBE6361T	Insured Vehicle No :	SLM4914B
Date of Loss:	19/01/2022	Nature of Claim:	TP
		Claim No:	2678222683SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE6361T		
Make & Model:	TOYOTA DYNA, 3.0 D (M)	Engine No:	1KD2566180
Reg. Date:	29/01/2016 (Man. Year: 2015)	Chassis No:	KDY2318022250
Colour:	White	Odometer:	171109 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R13 (D)
Front Left Side:	Giti 6 mm	Rear Left Side:	Giti 6/6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Giti 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,036.00	2,844.95	11,191.05	79.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,450.00	1,560.00	3,890.00	71.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,486.00	4,404.95	15,081.05	77.39
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	19,486.00	3,500.00	15,986.00	82.04
+ GST 7.00/7.00% (S\$)	1,364.02	245.00	1,119.02	82.04
Nett Amount (S\$)	20,850.02	3,745.00	17,105.02	82.04
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,247.00		

INSPECTION

Date of Assignment:	20/01/2022	
Date Inspected:	20/01/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented / Bent	2,660.00 FL	*1,482.50 FL
2	2		*REAR TAILGATE LOCK LATCHS	Repair	760.00 FL	*- FL
3	1		*REAR TAILGATE LOCK LOWER L BRACKETS	N/S Bent	360.00 FL	*110.50 FL
4	2		*REAR TAILGATE LOCK LOWER L BRACKET RUBBERS	Serviceable	240.00 FL	*- FL
5	1		*REAR TAILGATE DYNA STICKER	Necessary	80.00 FL	*58.60 FL
6	2		*TAILLAMPS	Cracked	900.00 FL	*590.40 FL
7	2		*TAILLAMP HOUSING PANELS	Repair	360.00 FL	*- FL
8	1		*REAR LICENCE PLATE BRACKET	Bent	345.00 FL	*184.20 FL
9	1		*REAR EXHAUST	Not Necessary	1,250.00 FL	*- FL
10	1		*REAR EXHAUST MOUNTING	Not Necessary	85.00 FL	*- FL
11	1		*REAR TAILGATE LOWER PANEL	Dented / Bent	840.00 FL	*580.40 FL
12	1		*REAR SPARE TYRE CARRIER & CHAIN	Not Necessary	680.00 FL	*- FL
13	1		*DROPSIDE GATE PANEL N/S	Repair	2,890.00 FL	*- FL
14	1		*DROPSIDE GATE PANEL O/S	Not Necessary	2,890.00 FL	*- FL
15	1		*SET REAR TAILGATE 70KM/H & 12 PAX STICKER	Necessary	50.00 FS	*20.00 FS
16	1		*SET REAR REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
17	1		*REAR LICENCE PLATE	Cracked	50.00 FS	*40.00 FS
18	1		*SET REAR CARGO DECK STOPPER RUBBER	Not Necessary	200.00 FS	*- FS
19	2		*REAR REFLECTORS	Cracked	230.00 FS	*150.00 FS
20	1		*REAR STEP BRACKET	Bent	300.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,470.00	3,596.60
- List Item Discount on L Items 10.00/25.00% (\$\$)	1,434.00	751.65
Total Parts (\$\$)	14,036.00	2,844.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	100.00	50.00
3	TO DISMANTLE & REPLACE REAR CARGO DECK	New	800.00	0.00
4	TO STRAIGHTEN & REALIGN CHASSIS	New	1,000.00	0.00
5	TO SPRAY RUST PROOFING	New	200.00	60.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,500.00	680.00
7	TO PUTTY & SPRAY PAINTING	New	1,800.00	750.00
Gross Labour Cost (\$\$)			5,450.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >